

SUPREME AUTO SERVICE PTE LTD

c/o 176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

YEO YONG PHENG

c/o 46 Lenton Plain
Singapore 786548

*Not Withheld
L/Sing &
Resurvey After Painting
Today*

Date: 8/9/2016

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE: MERCEDE BENZ C180 COUPE / SKG 9109 U	
1 pc	front bumper	1,368.70 ✓
1 pc	front parking sensor	286.30 ✓
1 pc	front fender (aluminium)	875.90 ✓
1 pc	front fender dust cover	293.20 X
1 pc	front headlamp	1,183.70 X
1 pc	steering tie rod	238.50 X
1 pc	steering tie rod end	197.30 X
1 pc	lower arm	438.10 X
1 pc	trust arm	365.30 X
1 pc	knuckle arm	638.70 X
1 pc	front shock absorber	613.80 X
1 pc	wheel bearing	186.50 X
1 pc	alloy rim	962.80 ✓
	sub-total	7,648.80
	less 10%	764.88
	sub-total	6,883.92
	To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.	350 600.00
	To check wiring system.	50.00 150
	To apply putty & spray painting on affected areas.	600.00 400
	To remove & install front undercarriage parts to enable repair.	220.00 X
	To replace alloy rim(s) & perform wheel balancing.	80.00 20
	To machine press wheel bearing.	80.00 X
	To perform 4 wheels computerised alignment.	100.00 60
	Diagnostic & Resetting the steering rack.	360.00 X
	Total	8,973.92

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: