



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 19/03/2021

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SMB1399D
Case Reference Number	BUS/01/21/7014
Registration Date	1/11/2013
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN NL320F(A22)
Name of Driver	Saw Chiang Chue
Type of Accident	Side Swipe
Accident Date and Time	8/1/2021 4:03 PM
Accident Reported Date and Time	8/1/2021 5:15 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24109518
Special Instruction to ARC,if any	SMB1399D - LEFT FRONT PORTION AND RIGHT FRONT PORTION GBG5718U (TP) - INSURED WITH NTUC
Prepared Date and Time	14/1/2021 7:48 AM
Chassis Number	WMAA22ZZ4D7001938
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$3,710.00	\$3,180.00
Total Spray Cost	\$1,126.00	\$1,000.00
Total Spare Part Cost	\$13,043.47	\$9,606.98
Total Other Cost	\$520.00	(\$836.00)
TOTAL COST	\$18,399.47	\$12,950.98
Lump Sum Total	\$0.00	\$12,950.00
Number of Repair Days	8.0	7.0
Prepared / Adjusted By	Kok Khoon Goh	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	14/01/2021 8:10 AM	14/01/2021 2:28 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 19/03/2021

User ID : CatherineLee

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope				Quotation from AR				Adjusted by Surveyor, if applicable	
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.				\$3,710.00				\$3,180.00	
Total Labour				\$3,710.00				\$3,180.00	
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope				Quotation from ARC				Adjusted by Surveyor, if applicable	
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS				\$1,126.00				\$1,000.00	
Total Spray Painting & Panel Beating				\$1,126.00				\$1,000.00	
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope				Quotation from ARC				Adjusted by Surveyor, if applicable	
TOWING CHARGE				\$200.00				\$0.00	
TO APPLY RUST-PROOFING ON AFFECTED AREA				\$240.00				\$0.00	
TO CHECK WIRING AND SYSTEM FUNCTION				\$80.00				\$0.00	
Lump Sum Adjustment by Surveyor				\$0.00				(\$836.00)	
Total Other Costs				\$520.00				(\$836.00)	
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010148	GLASS	4001X01-GLASS5171	WINDSCREEN,FRONT:F OR MAN A22 BUS	1.00	\$5,031.80	10.00	\$4,528.62	Replace	Replace
4006315	CONSUMABLE	Aktivator - 100	ACTIVATOR	3.00	\$80.00	0.00	\$240.00	Replace	Replace
4006314			SEALANT SIKAFLEX	37.00	\$37.00	0.00	\$1,369.00	Replace	Replace
4006313	CONSUMABLE	SIKA® Primer-206 G+P	PRIMER (SIKA 206 G+P)	3.00	\$80.00	0.00	\$240.00	Replace	Replace
6010073	Body	F01001-CW262	DOME:FRONT,FOR MAN A22 BUS	1.00	\$2,817.50	100.00	\$0.00	Repair	Repair
6010153	Body	F01001-CW264	COVER,HEADLAMP:FRT ,LH,FOR MAN A22 BUS	1.00	\$974.70	10.00	\$877.23	Replace	Replace
6010304	VE	8-25101-6539	HEADLAMP,LH (MAN BUS)	0.00	\$1,603.60	0.00	\$0.00	Replace	Check
6010306	VE	81-25320-6111	FLASHER,AUX HEADLAMP,LH (MAN BUS)	0.00	\$904.40	0.00	\$0.00	Replace	Check
6010459	DOOR		GLASS,FRONT DOOR:FOR MAN A22 BUS	0.00	\$510.00	0.00	\$0.00	Replace	Not Given
			RUBBER PROFILE	1.00	\$150.00	0.00	\$150.00	Replace	Replace
6010502	DOOR		GLASS,EXIT DOOR:FOR MAN A22 BUS	0.00	\$510.00	0.00	\$0.00	Replace	Not Given
6010173	GLASS	4001X01-GLASS5176	GLASS,SIDE:L4,FOR MAN A22 BUS	1.00	\$1,060.90	10.00	\$954.81	Replace	Replace
6010174	GLASS	4001X01-GLASS5177	GLASS,SIDE:L5,FOR MAN A22 BUS	1.00	\$957.40	10.00	\$861.66	Replace	Replace
6010175	GLASS	4001X01-GLASS5178	GLASS,SIDE:L6,FOR MAN A22 BUS	1.00	\$543.40	10.00	\$489.06	Replace	Replace
6010050	Body	F01001-CW270	DOME:REAR,FOR MAN A22 BUS	1.00	\$2,817.50	100.00	\$0.00	Repair	Repair
6010161	BODY RH	4001M01-ACCE467	MIRROR,VIEW:FRONT,R H,FOR MAN	1.00	\$1,244.90	100.00	\$0.00	Replace	Repair
6010163	GLASS	4001Y01-GLASS5150	GLASS,DRIVER WINDOW:FOR MAN A22 BUS	1.00	\$1,423.20	10.00	\$1,280.88	Replace	Replace
6010303	VE	4001B05-LAM141	LAMP,INDICATOR,SIDE: LED (MAN BUS)	1.00	\$186.10	10.00	\$167.49	Replace	Replace
6010330			WHEEL ARCH TRIM	1.00	\$124.20	10.00	\$111.78	Replace	Replace
			SMRT STICKER	1.00	\$200.00	0.00	\$200.00	Replace	Replace



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 19/03/2021

User ID : CatherineLee

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009986	BODY RH	A01001-CW569	PANEL,SIDE:R5,FOR MAN A22 BUS	1.00	\$353.70	10.00	\$318.33	Replace	Replace
6009987	BODY RH	A01001-CW568	PANEL,SIDE:R6,FOR MAN A22 BUS	1.00	\$1,776.80	100.00	\$0.00	Repair	Repair
6009997	BODY LH	A01001-CW553	PANEL,SIDE:L3,FOR MAN A22 BUS	1.00	\$244.30	10.00	\$219.87	Replace	Replace
6009998	BODY LH	A01001-CW554	PANEL,SIDE:L4,FOR MAN A22 BUS	1.00	\$517.50	100.00	\$0.00	Repair	Repair
Total					\$24,148.90		\$12,008.73		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									