

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21000726/EQF3E2

Date: 05/02/2021

REFERENCE

Insured/Claimant: RAFFLES CORPORATION (SG) PTE LTD
Date of Loss: 13/01/2021

Policy No: 1700021926

Nature of Claim: OD Claim No: 6672931214SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLR6786P**
Make & Model: MITSUBISHI ATTRAGE, 1.2 (A)
Reg. Date: 11/07/2017 (Man. Year: 2016)
Colour: Blue
Engine Capacity: 1193 cc
Market Value/New Car Price: S\$45,000.00
Sum Insured (S\$): **Market Value/New Car Price**
Engine No: 3A92UDP8439
Chassis No: MMBSTA13AHH004189
Odometer: 19297 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R15 Rear Tyre Size: 185/55 R15
Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm
Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	567.47	473.53	93.94	16.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,385.00	2,445.00	2,940.00	54.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,952.47	2,918.53	3,033.94	50.97
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	5,352.47	2,318.53	3,033.94	56.68
+ GST 7.00/7.00% (S\$)	374.67	162.30	212.37	56.68
Nett Amount (S\$)	5,727.14	2,480.83	3,246.31	56.68

INSPECTION

Date of Assignment: 15/01/2021

Date Inspected: 15/01/2021 Inspected At:

Estimated Period of Repair: 4.0 days

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
2	1		*GLASS, RR WINDOW	Broken	544.00 FL	*544.00 FL
3	2		*STOPPER, WINDSHIELD GLASS	Necessary	6.00 FL	*6.00 FL
4	3		*SPACER, RR WINDOW	Necessary	27.00 FL	*27.00 FL
5	2		*STOPPER, WINDSHIELD GLASS	Necessary	6.00 FL	*6.00 FL
6	1		*SPACER, WINDSHIELD	Necessary	6.00 FL	*6.00 FL
7	1		*SPACER, QTR WINDOW	Not Necessary	8.00 FL	*- FL
8	1		*TAPE, WINDSHIELD GLASS	Not Necessary	24.00 FL	*- FL
9	1		*MARK, THREE-DIA	Not Necessary	69.00 FL	*- FL
10	1		*MARK, ATTRAGE	Not Necessary	21.00 FL	*- FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					731.00	609.00
- List Item Discount on L Items 23.00/23.00% (\$\$)					163.53	135.47
Total Parts (\$\$)					567.47	473.53

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPAIR ROOF TOP, BOOTLID, RHR FENDER & RHR DOOR	New	2,250.00	450.00
2	RESPRAY ROOF TOP, BOOTLID, RHR FENDER & RHR DOOR	New	1,400.00	700.00
3	REMOVE & REFIT ROOF LINING	New	225.00	225.00
4	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
6	REMOVE & REFIT FRT WINDSCREEN GLASS	New	240.00	0.00
7	RENEW RR WINDSCREEN GLASS	New	240.00	240.00
8	INSTALL RR WINDSCREEN SOLAR FILM	New	280.00	280.00
9	CLEAN & VACUUM BROKEN GLASS	New	80.00	80.00
10	CONDUCT WATER LEAK TEST ON BOTH FRT & RR WINDSCREEN GLASS	New	120.00	80.00
11	SUPPLT FRT WINDSCREEN SEALANT	New	80.00	0.00
12	SUPPLY RR WINDSCREEN SEALANT	New	80.00	80.00
13	APPLY ANTI CORROSION ON AFFECTED AREAS	New	80.00	40.00
14	SUPPLY C&C BADGE	New	40.00	0.00
15	REMOVE & REFIT REAR SEAT, SPEAKER, TRIM BOARD & OTHERS (Supplementary)	New	120.00	120.00
Gross Labour Cost (S\$)			5,385.00	2,445.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >