



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



MITSUBISHI
MOTORS

Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd.	Cust No/Name	KCV17784/MR RAFFLES CORPORATION (SG) PTE
MOTOR CLAIM DEPT	Reg No/Reg Date	SLR6786P / 11/07/201
78 SHENTON WAY #09-16	Date In/Mileage	/ 19297
AIG BUILDING	Chassis No	MMBSTA13AHH004189
SINGAPORE 079120	Engine No	3A92UDP8439
Contact No 6419 1892	Make/Model	MIT/17MY ATTRAGE 1.2 CVT
	Colour/Trim	T06 MED BLUE MICA / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Qty	Unit Price	Disc%	Amount
KAX00008	Credit	15/01/2021/ 09:47	BLE	261 / Edwin Caina	61859				
Description of Goods / Services						Qty	Unit Price	Disc%	Amount
E PNT88000						450 X 1			2250.00
REPAIR ROOF TOP, BOOTLID, RHR FENDER & RHR DOOR									1400.00
E PNT98000						350 X 1			225.00
RESPRAY ROOF TOP, BOOTLID, RHR FENDER & RHR DOOR									30.00
E PNT88000									120.00
REMOVE & REFIT ROOF LINING									240.00
A 54900099									240.00
CHECK WIRING ELECTRICAL SYSTEM									280.00
A 10028901									80.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST									120.00
USING HI-SCAN PRO TEST									80.00
E PNT88000									80.00
REMOVE & REFIT FRT WINDSCREEN GLASS									80.00
E PNT88000									80.00
RENEW RR WINDSCREEN GLASS									80.00
M SUNDRY									80.00
INSTALL RR WINDSCREEN SOLAR FILM									40.00
E PNT88000									20.00
CLEAN & VACUUM BROKEN GLASS									418.88
E PNT88000									4.62
CONDUCT WATER LEAK TEST ON BOTH FRT & RR WINDSCREEN GLASS									
M SUNDRY									
SUPPLY FRT WINDSCREEN SEALANT									
M SUNDRY									
SUPPLY RR WINDSCREEN SEALANT									
M SUNDRY									
APPLY ANTI CORROSION ON AFFECTED AREAS									
M SUNDRY									
SUPPLY C&C BADGE									
M SUNDRY									
Sundries						1.00	544.00	23.00	
M GLASS,RR WINDOW						2.00	3.00	23.00	
M STOPPER,WINDSHIELD GLASS									

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel 65684555 Fax 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV17784/MR RAFFLES CORPORATION (SG) PTE Reg No/Reg Date SLR6786P / 11/07/201 Date In/Mileage / 19297 Chassis No MMBSTA13AHH004189 Engine No 3A92UDP8439 Make/Model MIT/17MY ATTRAGE 1.2 CVT Colour/Trim T06 MED BLUE MICA / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	15/01/2021/ 09:47	BLE	261 / Edwin Caina	61859			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	SPACER,RR WINDOW	✓ APC			3.00	9.00	23.00	20.79
M	STOPPER,WINDSHIELD GLASS	✓ APC			2.00	3.00	23.00	4.62
M	SPACER,WINDSHIELD	✓ APC			1.00	6.00	23.00	4.62
M	SPACER,QTR WINDOW	X NN			1.00	8.00	23.00	6.16
M	TAPE,WINDSHIELD GLASS	(find price) X NN			1.00	24.00	23.00	18.48
M	MARK,THREE-DIA	X NN			1.00	69.00	23.00	53.13
M	MARK,ATTRAGE	X NN			1.00	21.00	23.00	16.17

Estimate

SURVEYOR NAME : Steve (LKK) 15/1/21, 11:30am

SURVEYOR SIGNATURE : OD- NM AutL

DATE : Excess - ?

REMARKS : P/P

4 days

LKK Auto Consultants hence notify
the Repairer of the following:

- Confirm & accepted by during resurvey
- Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized signatory and company stamp

7% GST on Net 5,832.47
5832.47 408.27
Total Payable 6,240.74

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.