



CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
NG KAI WEN (HUANG KAIWEN)		Cust No/Name	LCV10120/NG KAI WEN (HUANG KAIWEN)
BLK 469C SENGKANG WEST WAY		Reg No/Reg Date	SKK1888K / 11/06/201
#26-622		Date In/Mileage	/ 0
SINGAPORE 793469		Chassis No	KNAD6811VK6296660
Contact No		Engine No	G3LCKP029988
		Make/Model	KIA/STONIC 1.0 A BET
		Colour/Trim	ABT / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV10120	CRDVCH	15/01/2021/ 10:19	TLC	442 / Cocolu	27083

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPAIR REAR DOOR RH, REAR BUMPER RH, RENEW REAR BUMPER	1.5 X 490			609 800.00
E PNT98000 SPRAY PAINT FOR REAR DOOR RH, REAR BUMPER				350 700.00
M SUNDRY TRANSFER REAR RIGHT RIM				8 30.00 X
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment				120.00
A 90000001 CHECK WIRING & ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120 320.00
A 90000001 RENEW REAR UNDER CARRIAGE				640.00 X
M SUNDRY Sundry				20.00
M MOULDING ASSY-SIDE SILL,RH	1.00	248.00	00.00	248.00
M GARNISH-QTR SIDE RH	1.00	50.00	00.00	50.00
M GARNISH ASSY-RR DR SIDE,RH	1.00	92.00	00.00	92.00
M GARNISH ASSY-FR DR SIDE RH	1.00	82.00	00.00	82.00
M WHEEL ASSY-ALUMINIUM	1.00	659.00	00.00	659.00
M HUB ASSY-RR WHEEL	1.00	358.00	00.00	358.00
M COVER-RR BUMPER LWR	1.00	366.00	00.00	366.00

# Estimate

Steve (LKK)

15/1/21, 11:30am

OO- Nm AL, Excess - ?

P/P

Confirm & accepted by the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

Ry Bc sm  
4 days

Nett	4,515.00
7% GST on	316.05
Total Payable	4,831.05

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.