

KING'S AUTO REPAIR & SERVICE PTE LTD

BLK 176, SIN MING DRIVE, #02-10, SINGAPORE 575721
TEL: 6457-8629 FAX: 6451-7651

king auto 1973@gmail.com

DATE 18th Jan 2021
OUR REF SMT 7556 H
Tang Swee Keem
TO 245 Hougang Street 22
#12-143
Singapore 530245
RE QUOTATION FOR TOYOTA ALTIS

Quantity	Item	Unit Price (S\$)	Amount (S\$)	
1	Front RH Fender		662.64	RX
1	Front RH Lamp		✓ 530.09	CUTV
1	Front RH Fender Inner Shield		471.80	NDX
set	Front RH Fender Inner Shield Clips		30.00	NNX
1	Front Bumper		✓ 465.99	CUTV
2	Front Bumper Side Retainer	48.85	57.13 97.70	NECV
2	Front Bumper Bracket		41.12 82.24	NDX
1	Front Bumper Lower Grille		247.30 336.38	BRV
1	Front RH Fog Lamp		254.00 282.60	BRV
1	Front RH Fog Lamp Cover		✓ 67.00	BRV
1	Front Bumper Sponge		102.00	NDX
set	Front Bumper Clips		30.00 42.00	NECV
SUB-TOTAL			2,887.00	
LESS 25% DISCOUNT			721.75	1692.08
TOTAL			2,165.25	423.02 @ 25%
				1269.06

FOR LABOUR CHARGES

Quantity	Item	Unit Price (S\$)	Amount (S\$)	
	Panel beating		600.00	200.00 / 400.00
	Spray painting		600.00	400.00 /
	Check wirings and lightings		40.00	
TOTAL			1,140.00	640.00

GRAND TOTAL FOR THIS QUOTATION 3,305.25

Survey
15/1/2021

Tan Min

Resurvey

18/1/2021

Tan Min

PARTS 1269.06
LABOUR 840.00
2109.06
@ 20% 421.81
1687.25

Lump sum repair

Repair days 45

L/S 1700/2