

LH Express Motor Trading

Blk 5038 #01-405, Ang Mo Kio Ind. Park 2
Singapore 569541.
Email: dyeo.lhmotortrading@gmail.com
Fax: 64816131, Tel:64817221.

Not Authorized
1/1/11 &
Resurvey After Paint
7 days

Lee Hong Airconditioning Services
37A Hong Kong Street
Singapore 059676.

Vehicle No : GBB 9718U
Chassis No : JTFHT02PX0-0065188
Make : Toyota Hiace
Year : 2010

QTY	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

	1	Rear Fender LH	Ry	\$2,800.00	✓
	1	Fender Center Sliding Guide LH	Sm	\$213.00	X
	1	Rear Fender Inner Shield LH	Sm	\$126.00	X
	1	Rear Fender Inner Shield Clips	na	\$40.00	X
1 set		Sliding Door LH	Ry	\$1,630.00	✓
	1	Sliding Door Lower Guide LH		\$103.30	✓
	1	Sliding Door Weather Strip LH		\$289.30	✓
	1	Sliding Door Lock LH		\$215.00	✓
	1	Rear Bumper	Wt	\$653.00	✓
	1	Rear Bumper Side Retainer LH	Sm	\$35.00	X
1 set		Rear Bumper Clips	na	\$30.00	✓
	1	Rear Absorber LH	Sm	\$280.00	X
	1	Rear Tail Lamp LH	R	\$277.20	X
				\$6,476.80	
			Less 25%	\$1,619.20	
				\$4,857.60	

Labour Charges

TO remove and replaced damaged parts including straightening and repositioning replacement parts.

Supply Paint Material and necessary items. To be replaced

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal straightening allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Approved by Repairer
Signature:
Date:

Doc1
\$1,000.00

Doc1
\$1,200.00

and other affected panels

Reconnect wiring at the damage section and check for proper functions.

\$50.00 201

To carry out antirust treatment on affected panels.

\$100.00 601

To remove and refit roof lining to facilitate repair.

\$200.00 1001

To remove/replace rear LH under carriage

200 \$200.00 X

Special Nett Item

Rear Tyre

50 \$200.00 X

Grand Total :

\$7,807.60