

ASS. REC. BY:

REF:

CC31M62100740/ATB

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMF51645

Yr Regn:

2018 / Nov

Type:

MCar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi Q5

Colour:

Black

Sp. Reading

23/64

Eng/No:

C/No:

WAUZZZF12J2245321

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modf: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/55R19

R:

235/55R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

15/01/21

Survey held at

Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

OD AIG.

Part by Part \$15,472/-
(Red: 16,931 : 52%)

MV: 165K.

PV: 65K

Nett: 100K.

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

Report Format:

Lump Sum / LBH/G

15472/-

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0854/2020/NS
DATE	:	9-Nov-20
WIP	:	56920

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT
TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MR GUO HUAWEI
ADDRESS	:	11 JURONG LAKE LINK #09-37 SINGAPORE 648155
TELEPHONE	:	HP +65 91260329
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	1800135802-02
VEHICLE NO	:	SMF 5164 S
MODEL CODE	:	AUDI Q5 SPORT 2.0 TFSI QU
MODEL YEAR	:	15/11/2018
ENGINE NO	:	DAX 047338
CHASSIS NO	:	WAUZZZF2J2245321
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	7-Nov-20
PLACE OF ACCIDENT	:	PIE(TOWARDS CHANGI AIRPORT)

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMF 5164 S

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$	360.00	 
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR WIPER ASSY.	S/N \$	480.00	 
3	TO RENEW REAR WINDSCREEN TO FACILITATE	S/N \$	480.00	 
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$	400.00	 
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$	200.00	 
SUB TOTAL LABOUR CHARGES		:	<u><u>\$ 1,920.00</u></u>	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMF 5164 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$ 480.00	X X
7	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. CUT OUT AND WELD REAR END PANELLING. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,800.00	1000 ✓
8	TO RESPRAY REAR BUMPER, REAR LOWER BUMPER, REAR LID, END PANELLING, SPARE WHEEL HOUSING AND BOTH REAR WHEEL ARCH TRIMS. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS.	\$ 5,700.00	2050 ✓ $550 \times 3 = 1650$ $Arch = 200 \times 2 = 400$ <u>2050</u>
9	TO RENEW REAR EXHAUST SILENCER AND CENTRE	S/N \$ 480.00	X
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 13,572.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 5164 S

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
1 REAR UPPER BUMPER <i>Repair & cracked, Dented</i>	\$	1,724.00 *	1379.20
2 REAR LOWER BUMPER <i>Dented</i>	\$	1,182.00 ✓	945.60
3 REAR BUMPER SPOILER <i>Dented</i>	\$	830.00 ✓	664
4 REAR BUMPER TOWING EYE COVER - LH <i>new</i>	\$	48.00 *	
5 REAR BUMPER CLOSING ELEMENT - LH <i>new</i>	\$	95.00 *	
6 REAR BUMPER TRIM - LH <i>new</i>	\$	234.00 *	
7 TAIL LIGHT - LH <i>undented</i>	\$	691.00 ✓	552.80
8 BOOT LID CONTROL UNIT <i>new</i>	\$	399.00 *	
9 REAR BUMPER CARRIER <i>new Dented.</i>	\$	911.00 ✓	723.80
10 REAR BUMPER HOLDING STRAP <i>new</i>	\$	166.00 *	
11 REAR BUMPER GUIDE SECTION - LH/RH <i>new</i>	\$	166.00 *	
12 REAR PARKING AID SENSOR - REAR <i>new</i>	2	484.00 *	
13 REAR PARKING AID SEAL RING <i>new</i>	4	14.00 *	
14 REAR LID <i>Dented</i>	\$	4,168.00 ✓	3334.40
15 REAR LID ATTACHMENT PARTS <i>new</i>	\$	120.00 *	
16 PACKING ADHESIVE <i>new</i>	\$	18.00 ✓	14.40
17 AUDI EMBLEM <i>new</i>	\$	122.00 ✓	97.60
18 Q5 INSCRIPTION <i>new</i>	\$	95.00 ✓	76.00
19 TFSI INSCRIPTION <i>new</i>	\$	95.00 ✓	76.00
20 QUATTRO INSCRIPTION <i>new</i>	\$	95.00 ✓	76.00
SUB TOTAL SPARE PARTS	:	\$ 11,657.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 5164 S

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
21 LOCK CARRIER REINFORCEMENT <i>Repis</i>		\$ 239.00	? X
22 REAR CROSS PANEL <i>Repis</i>		\$ 560.00	? X
23 REAR WINDSCREEN <i>neu</i>		\$ 1,131.00	✓ 904.80
24 PRIMER <i>neu</i>		\$ 19.00	✓ 15.20
25 SPOILER FIXING PARTS <i>Ne neu</i>		\$ 32.00	? X
26 REAR SPOILER - LH/RH <i>neu</i>	2	\$ 462.00	✓ 369.60
27 REAR WHEEL COVER - LH/RH <i>neu</i>	2	\$ 1,154.00	✓ 923.20
28 REAR SILENCER <i>not a</i>		\$ 1,344.00	+
29 REAR SILENCER DUAL CLIP		\$ 54.00	+
30 RETAINING RING	2	\$ 45.00	+
31 CENTRE SILENCER		\$ 966.00	+
32 CENTRE SILENCER DUAL CLIP - INNER/OUTER <i>neu</i>	2	\$ 108.00	+
33 REAR NO PLATE <i>not a</i>	S/N	\$ 60.00	+
34 REAR WINDSCREEN SEALANT <i>neu</i>	S/N	\$ 200.00	✓ 200
35 STONE CHIP <i>Ne neu</i>	S/N	\$ 180.00	? X
36 CAVITY WAX <i>Ne neu</i>	S/N	\$ 140.00	? X
37 ACRYLIC SEALANT <i>Ne neu</i>	S/N	\$ 180.00	? X
38 SUNDRIES <i>Neu</i>		\$ 300.00	2.40
TOTAL SPARE PARTS	:	\$ 18,831.00	
TOTAL LABOUR CHARGES	:	\$ 13,572.00	
GRAND TOTAL	:	\$ 32,403.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



15 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: *Adrian*
: *15/01/21*
:
:
:
:
:

Not Authorised, 04 Days

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

PREMIUM AUTOMOBILES



1, SINGAPORE 408699
2323 FAX: 6841 1183
KHAIRAH@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0854/2020/NS
DATE	:	09-Nov-20
WIP	:	56920

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

Hi Adrian,

4 days - ok - Jy - 29 Mar 21

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT
TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MR GUO HUAWEI
ADDRESS	:	11 JURONG LAKE LINK #09-37 SINGAPORE 648155
TELEPHONE	:	HP +65 91260329
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	1800135802-02
VEHICLE NO	:	SMF 5164 S
MODEL CODE	:	AUDI Q5 SPORT 2.0 TFSI QU
MODEL YEAR	:	15/11/2018
ENGINE NO	:	DAX 047338
CHASSIS NO	:	WAUZZZFY2J2245321
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	07-Nov-20
PLACE OF ACCIDENT	:	PIE(TOWARDS CHANGI AIRPORT)



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMF 5164 S

	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$	360.00	\$	360.00
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR WIPER ASSY.	S/N \$	480.00	\$	480.00
3	TO RENEW REAR WINDSCREEN TO FACILITATE FFNDER RENFWAI /	S/N \$	480.00	\$	480.00
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$	400.00	\$	400.00
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$	200.00	\$	150.00
SUB TOTAL LABOUR CHARGES		:	\$ 1,920.00	\$	1,870.00



SINGAPORE 408699
 FAX : 6841 1183
 EMAIL: KHAIR@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMF 5164 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
	c/f		\$ 1,870.00
6	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$ 480.00	
7	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. CUT OUT AND WELD REAR END PANELLING. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,800.00	\$ 1,000.00
8	TO RESPRAY REAR BUMPER, REAR LOWER BUMPER, REAR LID, END PANELLING, SPARE WHEEL HOUSING AND BOTH REAR WHEEL ARCH TRIMS. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS.	\$ 5,700.00	\$ 2,050.00
9	TO RENEW REAR EXHAUST SILENCER AND CENTRE EXHAUST SILENCER TO ALIGN TO POSITION	S/N \$ 480.00	
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 13,572.00	\$ 5,112.00

PREMIUM AUTOMOBILES



SINGAPORE 408699
FAX : 6841 1183

EMAIL: SALES@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

SERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 5164 S

SN PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	REAR UPPER BUMPER		\$ 1,724.00	\$	1,379.20
2	REAR LOWER BUMPER		\$ 1,182.00	\$	945.60
3	REAR BUMPER SPOILER		\$ 830.00	\$	664.00
4	REAR BUMPER TOWING EYE COVER - LH		\$ 48.00		
5	REAR BUMPER CLOSING ELEMENT - LH		\$ 95.00		
6	REAR BUMPER TRIM - LH		\$ 234.00		
7	TAIL LIGHT - LH		\$ 691.00	\$	552.80
8	BOOT LID CONTROL UNIT		\$ 399.00		
9	REAR BUMPER CARRIER		\$ 911.00	\$	728.80
10	REAR BUMPER HOLDING STRAP		\$ 166.00		
11	REAR BUMPER GUIDE SECTION - LH/RH	2	\$ 166.00		
12	REAR PARKING AID SENSOR - REAR	2	\$ 484.00		
13	REAR PARKING AID SEAL RING	4	\$ 14.00		
14	REAR LID		\$ 4,168.00	\$	3,334.40
15	REAR LID ATTACHMENT PARTS		\$ 120.00		
16	PACKING ADHESIVE		\$ 18.00	\$	14.40
17	AUDI EMBLEM		\$ 122.00	\$	97.60
18	Q5 INSCRIPTION		\$ 95.00	\$	76.00
19	TFSI INSCRIPTION		\$ 95.00	\$	76.00
20	QUATTRO INSCRIPTION		\$ 95.00	\$	76.00
SUB TOTAL SPARE PARTS		:	\$ 11,657.00	\$	7,944.80

PREMIUM AUTOMOBILES
 SINGAPORE 408699
 FAX : 6841 1183
 EMAIL: KHAIR@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG
MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 5164 S



SN PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
21 LOCK CARRIER REINFORCEMENT	c/f		\$	7,944.80
22 REAR CROSS PANEL		\$	239.00	
23 REAR WINDSCREEN		\$	560.00	
24 PRIMER		\$	1,131.00	\$ 904.80
25 SPOILER FIXING PARTS		\$	19.00	\$ 15.20
26 REAR SPOILER - LH/RH		\$	32.00	
27 REAR WHEEL COVER - LH/RH	2	\$	462.00	\$ 369.60
28 REAR SILENCER	2	\$	1,154.00	\$ 923.20
29 REAR SILENCER DUAL CLIP		\$	1,344.00	
30 RETAINING RING		\$	54.00	
31 CENTRE SILENCER	2	\$	45.00	
32 CENTRE SILENCER DUAL CLIP -		\$	966.00	
INNER/OUTER	2	\$	108.00	
33 REAR NO PLATE	S/N	\$	60.00	
34 REAR WINDSCREEN SEALANT	S/N	\$	200.00	\$ 200.00
35 STONE CHIP	S/N	\$	180.00	
36 CAVITY WAX	S/N	\$	140.00	
37 ACRYLIC SEALANT	S/N	\$	180.00	
38 SUNDRIES		\$	300.00	\$ 2.40
TOTAL SPARE PARTS	:	\$	18,831.00	\$ 10,360.00
TOTAL LABOUR CHARGES	:	\$	13,572.00	\$ 5,112.00
GRAND TOTAL	:	\$	32,403.00	\$ 15,472.00

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bl-08/03/21