

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

DATE : 18/1/2021

M/S AIG ASIA PACIFIC INSURANCE PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR SKH1091H

TO SUPPLY :

List Items

01)	1 PC	REAR BUMPER	20/22	LS2	\$ 2,000.32	✓
02)	10 PCS	CLIPS	res		\$ 75.00	✓
03)	1 PC	REVERSE SENSOR	82c		\$ 211.33	X
04)	1 PC	REVERSE SENSOR COVER	11		\$ 30.77	X
05)	1 PC	FRONT LOWER GRILLE	11		\$ 104.70	X
06)		SPRAY PAINTING			\$ 440.00	220
07)		LABOUR CHARGE			\$ 400.00	150
08)		TO REMOVE AND RENEW SENSOR			\$ 80.00	50
					<u>\$ 3,342.12</u>	

not authorized
L/S \$1900
2 days

Wu phan the repair

9-2125.32
500
1971.82
2391.55
1913