

ASS. REC. BY:

REF:

AKZ/ 21000 7471K

Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s MBM  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

1.30pm

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: 2-3 days Res.: Yes or No  
 Lum Sum: 118.7% 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

⌢	
N/S	O/S

Veh No: Smx 898X Yr Regn: 10, 20  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or Wagon  
 Make: Mer GLB 200d c.c. 1332  
 Colour: Black A/C: Insured / Std / NI / NA  
 Sp. Reading: 5820 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: WDC 2476152-W009525  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Mod: NII / S/Rim / STD / R/Rim or  
 Tyre Size: F: \_\_\_\_\_ R: 235/50R19  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_  
 Front R/Bal. 9 mm Rear R/Bal. 9 mm  
 L/Bal. 9 mm L/Bal. 9 mm  
 D.O.A. 12/1/21 D.O.I. 18/1/2021  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt Rear / O/S / N/S / UIC / Rooftop or  
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

: Prell. Report  
 : Final Report

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS. \$ \_\_\_\_\_

Fuel \$ \_\_\_\_\_

Others \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)


: Tech Invs (\$ \_\_\_\_\_)

: \_\_\_\_\_ (\$ \_\_\_\_\_)

Report Format :

Lump Sum / I.B.I. (\$) \_\_\_\_\_

# MBM WHEELPOWER PTE. LTD.



YOUR REF.: SLN7131T  
OUR REF.: SMX898X

*Not Authorized  
Recovery B4 paint  
2-3 days*

TO: AUTO & GENERAL  
CC: MOTOR CLAIMS DEPARTMENT

DATE: 18/1/2021  
FROM: Lee Shirley  
FAX: 64525333  
CONTACT: 86865188  
MAKE & MODEL: MERCEDES BENZ GLB220  
AMG LINE  
CHASSIS NO.: WDC2476152W009525  
ENGINE NO.: 65492080601231  
YEAR MADE: 2020  
ACCIDENT DATE: 12 January 2021

FAX:

ESTIMATE FOR VEHICLE NO.: SMX898X

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	BONNET		1	\$ X R 1,950.00 X
2	BONNET HINGE LH		1	\$ X R 100.00 X
3	BONNET HINGE RH		1	\$ X R 100.00 X
4	BONNET LOCK		1	\$ X R 150.00 X
5	BONNET MERCEDES LOGO		1	\$ X Sm 82.00 X
6	HEADLAMP LH		1	\$ X Sm 3,500.00 X
7	HEADLAMP RH		1	\$ X Sm 3,500.00 X
8	FRONT RADIATOR GRILLE		1	\$ ✓ Du 1,500.00 ✓
9	FRONT RADIATOR MERCEDES LOGO		1	\$ ✓ Du 160.00 ✓
10	FRONT BUMPER		1	\$ Bull/nd 1,700.00 ✓
11	FRONT BUMPER SPONGE		1	\$ ? 165.00 ?
12	FRONT BUMPER REINFORCEMENT		1	\$ R 622.00 X
13	FRONT BUMPER RETAINER LH		1	\$ Sm X 17.00
14	FRONT BUMPER RETAINER RH		1	\$ Sm X 17.00
15	FRONT BUMPER TOWING COVER LH		1	\$ Sm X 60.00
16	FRONT BUMPER TOWING COVER RH		1	\$ Sm X 60.00
17	FRONT BUMPER CENTER GRILLE		1	\$ Sm X 450.00
18	FRONT BUMPER SIDE GRILLE LH		1	\$ Sm X 93.00
19	FRONT BUMPER SIDE GRILLE RH		1	\$ Sm X 93.00
20	FRONT BUMPER LOWER CHROME STRIP		1	\$ Sm X 250.00
21	FRONT BUMPER LOWER SPOILER		1	\$ Sm X 130.00
22	FRONT BUMPER SENSOR		4	\$ ? 1,000.00
23	FRONT BUMPER CLIP		10	\$ Ac ✓ 80.00
24	FRONT BUMPER SIDE DOVER LH		1	\$ Sm X 140.00
25	FRONT BUMPER SIDE DOVER RH		1	\$ Sm X 140.00
TOTAL:				\$ 16,059.00
LESS 10%:				\$ (1,605.90)
PARTS TOTAL:				\$ 14,453.10

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

MBM WHEELPOWER PTE. LTD.  
160 SIN MING DRIVE, #06-02  
SIN MING AUTOCITY  
# 6262 8888 f 6452 5333

**SPECIAL NETT**

FRONT NUMBER PLATE & HOLDER	1	\$ <i>Per 45m</i>	80.00
BODY SEALANT	1	\$ <i>max</i>	50.00
CERAMIC COATING ON FRONT BUMPER AND BONNET	1	\$ <i>?</i>	1,600.00

**LABOUR**

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS		\$ <i>300l</i>	1,600.00
TO CHECK & RECONNECT ALL NECESSARY WIRING		\$ <i>15l</i>	150.00
TO REMOVE & REFIT ALL SENSOR		\$ <i>60l</i>	100.00
TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)		\$ <i>?</i>	150.00
TO SPRAY PAINT ON THE AFFECTED AREAS		\$ <i>300l</i>	1,200.00

TOTAL:	\$	19,383.10
7% GST:	\$	1,356.82
<b>GRAND TOTAL:</b>	<b>\$</b>	<b>20,739.92</b>



# SINGAPORE ACCIDENT STATEMENT

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission .....	13/01/2021 14:03 (SGT)
Date of Accident .....	12/01/2021 14:49 (SGT)
Exact Location of Accident .....	34A Bedok South Ave 2, Singapore 462034
Additional Location Information .....	-
Country/State of Loss .....	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number .....	SMX898X
-----------------------------------	---------

**INSURED/POLICYHOLDER**

Is company? .....	No
Name Of Registered Owner .....	Lee Poh Seng
NRIC No .....	SXXXX698H
Email Address .....	libaocheng@yahoo.com
Mobile Phone No .....	(Phone) +65-98755990
Alternative Phone No .....	(Home) +65-98755990

**VEHICLE PARTICULARS**

Manufacturer .....	Mercedes
Model .....	GLB220 AMG Line Premium D 4M Auto
Variant .....	-
Exact purpose for which vehicle was being used at time of accident .....	Private use
Are you claiming under your own insurance policy for repair to your vehicle? .....	No - Claiming third party
Vehicle Category .....	Private car

**INSURANCE COMPANY**

Name of Insurance Company .....	Axa
Type of Coverage .....	Comprehensive
Fleet Policy .....	No
Policy Number .....	GA554876/1
Cover Note Number .....	-

**DRIVER**

Name of Driver .....	Lee Poh Seng
NRIC No .....	SXXXX698H
Date Of Birth .....	14/09/1980
Occupation .....	Indoor


**Accident report SS02211D0004**

Page 1 of 18

ccident report SS02211D0004

Date Of Driving Pass ..... 10/09/2001  
 Driving experience ..... 19 YEARS AND 4 MONTHS  
 Gender ..... Male  
 Mobile Number ..... (Phone) +65-98755990  
 Alt. Phone Number ..... (Home) +65-98755990  
 Email Address ..... libaocheng@yahoo.com  
 Address ..... Blk 31 #24-301 Bedok South Ave 2  
 Address complement ..... -  
 Postcode ..... 480031  
 Is the driver the policyholder? ..... Yes  
 If No, Relationship of the Driver with the Insured ..... -  
 Does Driver Own Other Vehicles? ..... No  
 Vehicle Registration Number of Other Vehicle Owned by Driver ..... -  
 Insurance Company of Other Vehicle Owned by Driver ..... -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident ..... Hit and run / Vandalism / Damaged whilst parked  
 Weather Conditions ..... Clear  
 Road Surface ..... Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? ..... No  
 Number of vehicles involved in the accident ..... 2  
 Was anybody injured in the Accident? ..... No  
 Was any injured conveyed to hospital by ambulance? ..... -  
 Was any other material or property damaged? ..... Yes  
 Number of Passengers (Including Driver) ..... 0  
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? ..... No

DETAILS OF POLICE ACTION

Was the accident reported to the police? ..... Yes  
 Police Station Name ..... Bedok South Neighbourhood Police Centre  
 Police Station Phone No ..... (Phone) +65-18002448999  
 Alt. Police Station Phone No ..... (Fax) +65-62446558  
 Police Station Address ..... 20 Chai Chee Drive Singapore 469045  
 Was notice of intended Prosecution given? ..... No  
 If yes, against whom? ..... -

CIRCUMSTANCES OF ACCIDENT

refer attached report.

ATTACHMENT(S)

Are accident photos available for attachment? ..... Yes  
 Was there any video captured by Car Camera? ..... No  
 Was there any audio recorded? ..... No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number ..... SLN7131T  
 Vehicle Manufacturer ..... -  
 Vehicle Model ..... -  
 Vehicle Variant ..... -  
 Vehicle Colour ..... -  
 Vehicle Category ..... Private car  
 Name of Driver ..... -  
 Contact Number ..... -



**SINGAPORE  
POLICE FORCE**



T/20210112/2098

Police Station Of Origin:  
Bedok South N.P.C  
20 Chai Chee Drive SINGAPORE 469045  
Tel No: 1800-2448999

1 of 3  
Report No: T/20210112/2098

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 12/01/2021 17:57		Vide Report No.:		Station Diary No. 27	
<b>Informant's Particulars</b>					
Name of Informant: LEE POH SENG			Address: APT BLK 31 BEDOK SOUTH AVENUE 2 #24-301 SINGAPORE 460031		
ID Type / ID No. NRIC NO / S8028698H			Contact No. Home/Office:		Mobile: 98755990
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 40	Date of Birth: 14/09/1980	Type of Informant: Driver		
Race: Chinese		Language:		Institution / School Name:	
Occupation: BUSINESS MANAGER			Driving Licence Information: Class: 3		Date of Expiry:

**General Information of the Accident**

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 12/01/2021 17:00	Type of Location: Car Park
Location: BEDOK SOUTH AVENUE 2				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: No Traffic
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passengers
SLN7131T	Car	TOYOTA		Beige		1
SMX898X	Car	MERCEDES BENZ	GLB220 AMG LINE PREMIUM D 4M AUTO	Black	Slightly Damaged	0

**Details of Vehicle Insurance**

Police No.:	Insurance Company:
-------------	--------------------



Police Station Of Origin:  
Bedok South N.P.C  
20 Chai Chee Drive SINGAPORE 469045  
Tel No: 1800-2448999

**CONTINUATION OF REPORT**

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
SMX898X	AXA INSURANCE SINGAPORE PTE LTD	GA554876	19/11/2020	13/10/2021

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	LEE POH SENG		ID No.	S8028698H
Related Vehicle	SMX898X (Car)		Contact No.	98755990
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

**Brief Details.**

On the 12/01/2021 at about 1311hrs I parked my vehicle bearing, (SMX898X) at the multi storey carpark located at Blk 34A Bedok South Avenue 2, Lot 164. Everything was intact at that point of time. On the same day at about 17:10hrs I returned back to my vehicle and discovered that there were slight scratches at the front left side of my vehicle. I then immediately made a check on my in-car camera and noticed that on the 12/01/2021 at about 1449hrs it could be seen that a vehicle bearing, (SLN7131T) was attempting to park into a parking lot opposite my vehicle.

While attempting to park into the lot the said vehicle brushed through the front left side of my vehicle and subsequently adjusted his vehicle before parking at the parking lot which was opposite left of my vehicle. I then made a search around my vehicle and did not notice any note left by the said driver. I am not sure if the vehicle is still parked at the said location. I would like to inform that due to the accident my vehicle sustained scratches at the front number plate, bumper and grille.

My in-car camera has captured the accident and I do have a footage of the accident.