

REF.: SLN7131T
REF.: SMX898X

Not Authorized
Recovery By paint
3 days
3809.20

AUTO & GENERAL

MOTOR CLAIMS DEPARTMENT

DATE: 18/1/2021
FROM: Lee Shirley
FAX: 64525333
CONTACT: 86865188
MAKE & MODEL: MERCEDES BENZ GLB220
CHASSIS NO.: WDC2476152W009525
ENGINE NO.: 65492080601231
YEAR MADE: 2020
ACCIDENT DATE: 12 January 2021

DATE FOR VEHICLE NO.: SMX898X

QTY.	PART NO.	DESCRIPTION	LIST PRICE
1		BONNET	1,950.00 X
1		BONNET HINGE LH	100.00 X
1		BONNET HINGE RH	100.00 X
1		BONNET LOCK	150.00 X
1		BONNET MERCEDES LOGO	82.00 X
1		HEADLAMP LH	3,500.00 X
1		HEADLAMP RH	3,500.00 X
1		FRONT RADIATOR GRILLE	1,500.00
1		FRONT RADIATOR MERCEDES LOGO	160.00
1		FRONT BUMPER	1,700.00
1		FRONT BUMPER SPONGE	165.00 X
1		FRONT BUMPER REINFORCEMENT	622.00 X
1		FRONT BUMPER RETAINER LH	17.00
1		FRONT BUMPER RETAINER RH	17.00
1		FRONT BUMPER TOWING COVER LH	60.00
1		FRONT BUMPER TOWING COVER RH	60.00
1		FRONT BUMPER CENTER GRILLE	450.00
1		FRONT BUMPER SIDE GRILLE LH	93.00
1		FRONT BUMPER SIDE GRILLE RH	93.00
1		FRONT BUMPER LOWER CHROME STRIP	250.00
1		FRONT BUMPER LOWER SPOILER	130.00
1		FRONT BUMPER SENSOR	1,000.00 X
4		FRONT BUMPER CLIP	80.00
10		FRONT BUMPER SIDE DOVER LH	140.00
1		FRONT BUMPER SIDE DOVER RH	140.00

TOTAL: \$ 16,059.00
LESS 10%: \$ (1,605.90)
PARTS TOTAL: \$ 14,453.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

MBM WHEELPOWER PTE. LTD.
160 SIN MING DRIVE, #06-02
SIN MING AUTOCITY
1 6262 8888 f 6452 5333
COMPANY REG. NO.: 200204110W

SPECIAL NETT

FRONT NUMBER PLATE & HOLDER 1 \$ *Pw* *45m* 80.00
BODY SEALANT 1 \$ *nn* *x* 50.00
CERAMIC COATING ON FRONT BUMPER AND BONNET 1 *nn* \$ *400* *1,600.00*

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS

\$ *300* 1,600.00

TO CHECK & RECONNECT ALL NECESSARY WIRING

\$ *15* 150.00

TO REMOVE & REFIT ALL SENSOR

\$ *60* 100.00

TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)

\$ *nn* 150.00

TO SPRAY PAINT ON THE AFFECTED AREAS

\$ *300* 1,200.00

TOTAL: \$ 19,383.10

7% GST: \$ 1,356.82

GRAND TOTAL: \$ 20,739.92