



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2101579
3 ANSON ROAD #16-00	INV Date	12/03/2021
SPRINGLEAF TOWER	Reference	CC6/CTI21000750/Kes3q2
SINGAPORE 079909	Code	CTI

PROFESSIONAL SERVICE FEE

Vehicle No.	SLZ 5565A
Insured Veh.	SGE7272B
Claim No.	SNM21D200253
Policy No.	DMPCSNW00066472000
Accident Date	13/01/2021
Inspection Date	18/01/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWERSINGAPORE 079909

Ref: CC6/CTI21000750/Kes3q2

Date: 12/03/2021

Code: CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGE7272B	Veh. Inspected	SLZ 5565A
Policy No.	DMPCSNW00066472000	Coverage (\$)	0.00
Claim No.	SNM21D200253	Excess (\$)	0.00
Assign From		Assign Date	18/01/2021

2. Vehicle Particulars & Condition

Make & Model	HONDA SHUTTLE (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	GP71209238	Colour	METALLIC DARK GREY
Odometer	182335 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	MICHELIN	8 mm
L/H Front Tyre	185/60 R15	MICHELIN	8 mm
R/H Rear Tyre	185/60 R15	MICHELIN	8 mm
L/H Rear Tyre	185/60 R15	MICHELIN	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/01/2021	Inspection Date	18/01/2021
Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 Sector C SINGAPORE 575643.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 5565A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	BUCKLED	1,150.60	1,150.60
2	REAR BUMPER BRACKET @\$24.90	TO REPAIR SEE LABOUR	49.80	-
1	REAR BUMPER LAMP	SERVICEABLE	148.50	-
1	REAR BUMPER LAMP GARNISH	SERVICEABLE	86.20	-
1	REAR BOOT LID	BENT	1,193.00	1,193.00
1	REAR BOOT EMBLEM-HYBRID	NECESSARY	38.00	38.00
1	REAR BOOT EMBLEM-LOGO	NECESSARY	55.00	55.00
1	REAR BOOT EMBLEM-SHUTTLE	NECESSARY	80.10	80.10
1	TOW COVER	SERVICEABLE	18.50	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	538.30	-
	LESS 20% DISCOUNT		-671.60	-503.34
			2,686.40	2,013.36
<u>SPECIAL NETT ITEMS</u>				
1	REVERSE SENSOR (SN)	DENTED	300.00	200.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	55.00	40.00
			355.00	240.00
<u>LABOUR</u>				
	TO REMOVE AND REFIT OF WINDSCREEN GLASS.		120.00	120.00
	TO KNOCK JACKOUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER BRACKET AND REAR END PANEL.		550.00	400.00
	SPRAY PAINTING ON AFFECTED & REPLACE PARTS.		850.00	420.00
			1,520.00	940.00
GRAND TOTAL			4,561.40	3,193.36



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,550.00
---	--	--	-----------------

Report Ref No. CC6/CT121000750/Kes3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLZ 5565A

INSPECTION







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLZ 5565A

RE-INSPECTION

