

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG21000753/QGA3Q2
Date: 08/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993716
Claimant Vehicle No :	SHB5702U	Insured Vehicle No :	SMA8049Z
Date of Loss:	11/01/2021	Nature of Claim:	TP
		Claim No:	3762640667SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB5702U		
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Engine No:	2ZRS110382
Reg. Date:	30/11/2017 (Man. Year: 2017)	Chassis No:	JTDKB3FU403575795
Colour:	Maroon	Odometer:	224356 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 6 mm	Rear Left Side:	Sailun 6 mm
Front Right Side:	Sailun 6 mm	Rear Right Side:	Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,835.40	1,190.81	6,644.59	84.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,236.00	440.00	796.00	64.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,071.40	1,630.81	7,440.59	82.02
Approved Total (Overridden) (S\$)		1,400.00		

Nett Amount (S\$)	9,071.40	1,400.00	7,671.40	84.57
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$114.49/day) (S\$)		343.47		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		1,900.47		

INSPECTION

Date of Assignment: 12/01/2021

Date Inspected: 12/01/2021

Estimated Period of Repair: 2.0 days

Inspected At:

SMRT Automotive Services Pte Ltd (Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Adjuster: OI SUN PIN**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,FR BUMPER (DISC 25%)	Crumpled	495.50 F	*371.63 F
2	1		*LAMP ASSY ,FOG ,LH (DISC 10%)	Cracked	910.20 F	*819.18 F
3	1		*SUPPORT ,FR BUMPER RH	Serviceable	76.90 F	*- F
4	1		*SUPPORT ,FR BUMPER LH	Serviceable	82.30 F	*- F
5	1		*COVER ,FR BUMPER LH	Serviceable	28.10 F	*- F
6	1		*REINFORCEMENT FRONT	Serviceable	691.10 F	*- F
7	1		*ABSORBER ,FR BUMPER	Serviceable	70.30 F	*- F
8	1		*EXTENSION SUB-ASSY ,LH	Serviceable	116.30 F	*- F
9	1		*EXTENSION SUB-ASSY ,RH	Serviceable	116.30 F	*- F
10	1		*REINFORCEMENT FRONT	Serviceable	238.50 F	*- F
11	1		*ABSORBER ,FR BUMPER	Serviceable	117.00 F	*- F
12	1		*GRILLE RADIATOR	Serviceable	165.00 F	*- F
13	1		*GRILLE SUB-ASSY	Serviceable	335.60 F	*- F
14	1		*CLIPS PIECE FRT & RR	Serviceable	1.50 F	*- F
15	1		*COVER ASSY ,ENGINE	Serviceable	180.10 F	*- F
16	1		*COVER ASSY ,ENGINE UNDER	Serviceable	452.80 F	*- F
17	1		*COVER ENGINE UNDER	Serviceable	94.50 F	*- F
18	1		*LAMP ASSY ,FOG ,LH	Serviceable	910.20 F	*- F
19	1		*UNIT HEADLAMP	Serviceable	2,558.90 F	*- F
20	1		*LINER FR FENDER LH	Serviceable	194.30 F	*- F

F=Franchise part.

Total Parts (S\$)	7,835.40	1,190.81
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING & BODY WORK	New	338.00	200.00
2	SPRAY PAINT	New	558.00	200.00
3	TO REPLACE SUNDRY PARTS	New	100.00	0.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	20.00
5	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
6	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (S\$)			1,236.00	440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >