



Section A - Accident Details

Registration Number	SHB5702U
Case Reference Number	TAX/01/21/2013
Registration Date	30/11/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	KHO PENG TEE
Type of Accident	Side Swipe
Accident Date and Time	11/1/2021 8:30 AM
Accident Reported Date and Time	11/1/2021 10:49 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24109411
Special Instruction to ARC, if any	TP/ LEFT FRONT PORTION /AIG - LKK
Prepared Date and Time	11/1/2021 2:51 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$338.00	\$200.00
Total Spray Cost	\$558.00	\$200.00
Total Spare Part Cost	\$5,234.86	\$952.65
Total Other Cost	\$340.00	\$40.00
TOTAL COST	\$6,470.86	\$1,392.65
Lump Sum Total	\$6,450.00	\$1,400.00 (L/S)
Number of Repair Days	5.0	2.0
Prepared / Adjusted By	Ang Bang Kien	Sun Pin (LKK) / AIG
ARC / Surveyor Sign Off Date	15/01/2021 5:34 PM	15/01/2021 10:53 AM
Signature		
Remarks	Total number of repair days = 2 days. SUP = 0 day.	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2101-0349	Invoice Number	
Quotation Date	25.01.2021	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$338.00	\$200.00
Total Labour	\$338.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$558.00	\$200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$340.00	\$40.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5211947962	COVER, FR BUMPER	1.00	\$495.50	25.00	\$371.63	Replace	Replace
		5211547050	SUPPORT, FR BUMPER RH	0.00	\$76.90	0.00	\$0.00	Replace	Not Given
		5211647050	SUPPORT, FR BUMPER LH	0.00	\$82.30	0.00	\$0.00	Replace	Not Given
		5212847906	COVER, FR BUMPER LH	0.00	\$28.10	0.00	\$0.00	Replace	Not Given
		5202147110	REINFORCEMENT FRONT	0.00	\$691.10	0.00	\$0.00	Replace	Check
		5261147140	ABSORBER, FR BUMPER	0.00	\$70.30	0.00	\$0.00	Replace	Check
		5210347010	EXTENSION SUB-ASSY, LH	0.00	\$116.30	0.00	\$0.00	Replace	Check
		5210247020	EXTENSION SUB-ASSY, RH	0.00	\$116.30	0.00	\$0.00	Replace	Not Given
		5213247010	REINFORCEMENT FRONT	0.00	\$238.50	0.00	\$0.00	Replace	Check
		5261847090	ABSORBER, FR BUMPER	0.00	\$117.00	0.00	\$0.00	Replace	Not Given
		5311247240	GRILLE, RADIATOR	0.00	\$165.00	0.00	\$0.00	Replace	Check
		5310147080	GRILLE SUB-ASSY	0.00	\$335.60	0.00	\$0.00	Replace	Not Given
		5216116010	CLIPS PIECE, FRT & RR	0.00	\$1.50	0.00	\$0.00	Replace	Not Given
		5142047030	COVER ASSY, ENGINE	0.00	\$180.10	0.00	\$0.00	Replace	Not Given
		5141047020	COVER ASSY, ENGINE UNDER	0.00	\$452.80	0.00	\$0.00	Replace	Not Given
		5144747030	COVER, ENGINE UNDER	0.00	\$94.50	0.00	\$0.00	Replace	Not Given
		8122047020	LAMP ASSY, FOG, LH	0.00	\$910.20	0.00	\$0.00	Replace	Not Given

CR4

SVC

SVC

SVC

SVC

SVC

SVC

SVC

SVC

SVC

SVC

SVC

SVC

SVC

SVC

SVC

SVC

SVC

SVC

SVC

SVC

SVC

		81145476 91	UNIT , HEADLAMP ,	0.00	\$2,558.90	0.00	\$0.00	Replace	Check <input checked="" type="checkbox"/>
		53876471 10	LINER, FR FENDER, LH	0.00	\$194.30	0.00	\$0.00	Replace	Not Given <input checked="" type="checkbox"/>
Total					\$6,925.20		\$371.63		

SUC
SUC

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		81220470 20	LAMP ASSY, FOG, LH	1.00	\$910.20	10.00	\$819.18	Replace	Replace <input checked="" type="checkbox"/>
Total					910.20		819.18		

CRA

1190.81 /

- 207 /

952.65 /

+ 200.00 /

+ 240.00 /

1392.65 /

4s \$1400 /
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____