



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/RAKESH KUMAR BHARDWAJ
	Reg No/Reg Date	SMQ8312D*ECB1/ 04/12/201
	Date In/Mileage	14/01/2021/ 0
	Chassis No	KNACC81CVL5338365
	Engine No	G4LEKS562188
	Make/Model	KIA/NIRO 1.6 A SX SR ASY PE
	Colour/Trim	C3U DEEP CERULEAN B/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	15/01/2021/ 14:09	BLK	282 / Kevin Leong	27417

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT ¹ BUMPER, BONNET, FRT BOTH ² FENDER, SUPPORT ¹ PANEL, FRT LH ¹ DOOR, FRT LH BODY CHASSIS, FRT LH BODY FRAME & AFFECTED AREA REPAIR ON FRT RH DOOR & ROOF, TOP	400 X 7			2800 4800.00
E PNT98000 PAINT WORK ON FRT ¹ BUMPER, BONNET, BOTH ² FRT FENDER, BOTH FRT DOOR, (LH) BOTH SIDE ¹ ROCKER PANEL, ROOF ¹ TOP, FRT LH CHASSIS, FRT LH WHEEL HOUSIN & BOTH FRT A-PILLAR ²	350 X 10			3500 4550.00
E PNT88000 REPLACE REAR ¹ BUMPER, REAR LH ² FENDER, REAR LH ¹ DOOR & AFFECTED AREA	400 X 4			1600 2000.00
E PNT98000 PAINT WORK ON REAR ¹ BUMPER, REAR LH FENDER & REAR LH DOOR				1050.00
E PNT88000 REMOVE & INSTALL FRT RADIATOR, CONDENSER FOR FACILITATE REPAIR				120.00
M SUNDRY TO TOP UP AIRCON GAS			(photo)	80.00
A 11900199 REMOVE & INSTALL ENGINE FOR FACILITATE REPAIR			(photo)	400.00
E PNT88000 REMOVE & INSTALL REAR HYBRID BATTERY FOR FACILITATE REPAIR				120.00
E PNT88000 TO TANSFER FRT LH DOOR ATTACHMENTS TO NEW PANEL				120.00
E PNT88000 TO TANSFER REAR LH DOOR ATTACHMENTS TO NEW PANEL			(photo)	4000.00 400
A 52900099 REMOVE & INSTALL DASH BOARD FOR FACILITATE REPAIR			(photo)	200.00
A 52900099 TO REMOVE & INSTALL FRT UNDER CARPET FOR FACILITATE REPAIR			(photo)	400.00
A 13900099 REMOVE & INSTALL FUEL TANK FOR FACILITATE REPAIR			(photo)	240.00
E PNT88000 REMOVE & INSTALL SUN ROOF FOR FACILITATE REPAIR				180.00
E PNT88000				

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /RAKESH KUMAR BHARDWAJ Reg No/Reg Date SMQ8312D*ECB1/ 04/12/201 Date In/Mileage 14/01/2021/ 0 Chassis No KNACC81CVL5338365 Engine No G4LEK5562188 Make/Model KIA/NIRO 1.6 A SX SR ASY PE Colour/Trim C3U DEEP CERULEAN B/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	15/01/2021/ 14:09	BLK	282 / Kevin Leong	27417

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
TO REMOVE & INSTALL REAR LH QUARTER GLASS FOR FACILITATE REPAIR				50.00 ✓
M SUNDRY				
TO APPLY REAR QUARTER GLASS SEALANT			(photo)	120.00 ✓
E PNT88000				
REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR			(photo)	120.00 ✓
E PNT88000				
REMOVE & INSTALL REAR SEAT FOR FACILITATE REPAIR			(photo)	400.00 ✓
A 33900099				
REPLACE FRT UNDERCARRIAGE			(photo)	400.00 ✓
A 34900099				
REPLACE REAR UNDERCARRIAGE			(photo)	120.00 ✓
A WHEELALIGNMENTBP				
To Conduct Computerize Full Wheel Alignment				150.00 ✓
M SUNDRY				
TO TRANSFER RIM INCLUDING BALANCING				400.00 ✓
A 52900099				
REPLACE ROOF LINING				400.00 ✓
A 16000010				
REPLACE LH CURTAIN AIRBAG				200.00 ✓
A 52900099				
REPLACE FRT LH SEAT AIRBAG				200.00 ✓
A 52900099				
REPLACE AIR BAG CONTROL UNIT				30.00 ✓
A 54900099				
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				120.00 ✓
A 10028901				
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				900.00 ✓
M SUNDRY				
REPLACE ALL TYRES (Front LH & Rear LH)				50.00 ✓
M SUNDRY				
SUNDRIES				
M LAMP ASSY-HEAD,LH / BR	1.00	2102.00	20.00	1681.60 ✓

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel. 65684555 Fax: 65651240



Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000		Cust No/Name	/RAKESH KUMAR BHARDWAJ
		Reg No/Reg Date	SMQ8312D*ECB1/ 04/12/201
		Date In/Mileage	14/01/2021/ 0
		Chassis No	KNACCB1CVL5338365
		Engine No	G4LEKS562188
		Make/Model	KIA/NIRO 1.6 A SX SR ASY PE
		Colour/Trim	C3U DEEP CERULEAN B/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	15/01/2021/ 14:09	BLK	282 / Kevin Leong	27417			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	LAMP ASSY-HEAD,RH	? X NM	X NM		1.00	2102.00	20.00	1681.60
M	LAMP ASSY-REAR COMB INSIDE,LH	X NM			1.00	636.00	20.00	508.80
M	LAMP ASSY-REAR COMB OUTSIDE,LH	? X NM			1.00	775.00	20.00	620.00
M	HORN ASSY-LOW PITCH	X NM			1.00	79.00	20.00	63.20
M	HORN ASSY-HIGH PITCH	/ MIS			1.00	79.00	20.00	63.20
M	PAD-HOOD INSULATING	X NM			1.00	213.00	20.00	170.40
M	MOULDING ASSY-FRONT FRAME,LH	? - NEC			1.00	48.00	20.00	38.40
M	W/STRIP ASSY-FR DR BELT O/S LH	? X NM			1.00	54.00	20.00	43.20
M	W/STRIP ASSY-FR DR SIDE LH	? X NM			1.00	111.00	20.00	88.80
M	W/STRIP-FR DR BODY SIDE LH	? X NM			1.00	109.00	20.00	87.20
M	HANDLE ASSY-DOOR OUTSIDE	X NM			1.00	66.00	20.00	52.80
M	COVER-FR DR O/S HDL	X NM			1.00	24.00	20.00	19.20
M	MOULDING ASSY-RR DR FRAME,LH	? - NEC			1.00	33.00	20.00	26.40
M	W/STRIP ASSY-RR DR BELT O/S LH	? X NM			1.00	50.00	20.00	40.00
M	W/STRIP ASSY-RR DR SIDE LH	? X NM			1.00	122.00	20.00	97.60
M	HANDLE ASSY-DOOR OUTSIDE	X NM			1.00	42.00	20.00	33.60
M	COVER-FR DR O/S HDL,PASSENGER	X NM			1.00	24.00	20.00	19.20
M	DOOR ASSY-FUEL FILLER	X NM			1.00	48.00	20.00	38.40
M	TRIM ASSY-LUGGAGE SIDE LH	? - BR			1.00	330.00	20.00	264.00
M	HEADLINING ASSY	/ CRU			1.00	1563.00	20.00	1250.40
M	TRIM ASSY-CTR PILLAR UPR LH	? NM X			1.00	70.00	20.00	56.00
M	UNDER COVER ASSY,LH	? / MIS			1.00	191.00	20.00	152.80
P	COVER-FR BUMPER UPR	/ MIS			1.00	637.00	20.00	509.60
M	STRIP ASSY-FR BUMPER UPR	/ MIS			1.00	28.00	20.00	22.40
M	COVER-FR BUMPER,LWR	/ MIS			1.00	373.00	20.00	298.40
M	LIP ASSY-FRONT BUMPER	/ MIS			1.00	38.00	20.00	30.40
M	SKID PLATE-FR BUMPER	/ MIS			1.00	60.00	20.00	48.00
M	PIECE-FRT BUMPER GUARD LWR,LH	/ MIS			1.00	16.00	20.00	12.80
M	PIECE-FRT BUMPER GUARD LWR,RH	/ MIS			1.00	16.00	20.00	12.80
M	COVER ASSY-RADIATOR GRILLE UPR	/ MIS			1.00	40.00	20.00	32.00
M	GRILLE ASSY-RADIATOR	/ MIS			1.00	441.00	20.00	352.80
M	ABSORBER-FRONT BUMPER ENERGY	/ MIS			1.00	68.00	20.00	54.40
M	GRILLE-FRONT BUMPER	/ MIS			1.00	131.00	20.00	104.80

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
 PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



o Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /RAKESH KUMAR BHARDWAJ Reg No/Reg Date SMQ8312D*ECB1/ 04/12/201 Date In/Mileage 14/01/2021/ 0 Chassis No KNACCB1CVL5338365 Engine No G4LEKS562188 Make/Model KIA/NIRO 1.6 A SX SR ASY PE Colour/Trim C3U DEEP CERULEAN B/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Qty	Unit Price	Disc%	Amount
LAX00000	Credit	15/01/2021/ 14:09	BLK	282 / Kevin Leong	27417				
Description of Goods / Services									
M	BRACKET-RR BEAM UPR MTG, LH	X	N/N			1.00	5.00	20.00	4.00
M	BRACKET-RR BEAM LWR MTG, LH	X	N/N			1.00	5.00	20.00	4.00
M	BRACKET-RR RAIL LWR MTG	X	N/N			1.00	5.00	20.00	4.00
M	BRACKET-RR BEAM UPR MTG, RH	X	N/N			1.00	5.00	20.00	4.00
M	BRACKET-RR BEAM LWR MTG, LH	X	N/N			2.00	5.00	20.00	8.00
M	BEAM-RR BUMPER	X	N/N			1.00	261.00	20.00	208.80
M	ANTENNA ASSY-SMARTKEY	X	N/N			1.00	39.00	20.00	31.20
M	STAY-RR BUMPER LH	X	N/N			1.00	67.00	20.00	53.60
M	STAY-RR BUMPER RH	X	N/N			1.00	67.00	20.00	53.60
M	BRACKET ASSY-RR BUMPER SIDE, LH			BR		1.00	25.00	20.00	20.00
M	BRACKET ASSY-RR BUMPER SIDE, RH			BR		1.00	25.00	20.00	20.00
M	GLASS & MOULDING ASSY-QUARTER	X	N/N			1.00	368.00	20.00	294.40
M	PANEL ASSY-HOOD	DD				1.00	1222.00	20.00	977.60
M	PANEL-FENDER, LH	DD				1.00	385.00	20.00	308.00
M	PANEL-FENDER, RH	DD				1.00	385.00	20.00	308.00
M	INSULATOR-FENDER LH		CRU			1.00	46.00	20.00	36.80
M	INSULATOR-FENDER RH	X	N/N			1.00	46.00	20.00	36.80
M	BEAM COMPLETE-FR BUMPER		DD			1.00	661.00	20.00	528.80
M	CARRIER ASSY-FRONT END MODULE			BR		1.00	675.00	20.00	540.00
M	BRACKET ASSY-FENDER MTG FR, LH			MIS		1.00	30.00	20.00	24.00
M	CROSSMEMBER COMPL		BT			1.00	810.00	20.00	648.00
M	STAY LH	X	N/N			1.00	22.00	20.00	17.60
M	STAY RH	X	N/N			1.00	22.00	20.00	17.60
M	ARM COMPLETE-FR LWR, LH		BT			1.00	286.00	20.00	228.80
M	ARM COMPLETE-FR LWR, RH		BT			1.00	286.00	20.00	228.80
M	PANEL ASSY-FRONT DOOR, LH		DD			1.00	1466.00	20.00	1172.80
M	PANEL ASSY-REAR DOOR, LH		DD			1.00	1542.00	20.00	1233.60
M	HINGE ASSY-REAR DOOR UPPER, LH			X N/N		1.00	33.00	20.00	26.40
M	HINGE ASSY-DOOR UPPER, LH			X N/N		1.00	26.00	20.00	20.80
M	PANEL ASSY-QUARTER OUTER, LH		DD			1.00	1207.00	20.00	965.60
M	PANEL-SIDE SILL OUTER, LH			X N/N		1.00	649.00	20.00	519.20
M	GEAR ASSY-STEERING		BT			1.00	832.00	20.00	665.60
M	BRAKE ASSY-FR, LH		TN			1.00	584.00	20.00	467.20

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Table with 2 main columns: Invoice Name & Address (AIG Asia Pacific Insurance Pte. Ltd.) and Owner Name & Vehicle Info (Cust No/Name, Reg No/Reg Date, Date In/Mileage, Chassis No, Engine No, Make/Model, Colour/Trim).

Main table with columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No, Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Includes a large 'Estimate' watermark.

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Table with 2 main columns: Invoice Name & Address (AIG Asia Pacific Insurance Pte. Ltd.) and Owner Name & Vehicle Info (Rakesh Kumar Bhardwaj, KIA Niro 1.6 A SX SR ASY PE).

Summary table with columns: Account No (LAX00000), Terms (Credit), Date/Time Printed (15/01/2021/ 14:09), CSE (BLK), Operator (282 / Kevin Leong), WIP No (27417).

Main items table with columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Includes items like WHEEL ASSY-ALUMINIUM, SHAFT ASSY-DRIVE, TRANSMISSION ASSY-DCT, etc.

Estimate

Handwritten notes: Steve CLKK, OO- Nm AnL, Excess -?, 15/1/29, 4.90pm

Handwritten signature: My BL smy, 35 days

LKK Auto Consultants hence notify the Repairer of the following: To resurvey before/after spray painting...

Summary table for payment: 7% GST on 73996.80, Total Payable 79,176.58

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST...