

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SKW 8254E

TP/FC

M/S : MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

Estimate No: ES2190077/YISHUN

Date: 29 Jan 2021

Policy No:

Veh Reg No: SKW8254E

Make/Model: NISSAN NISSAN
QASHQAI 1.2

Chassis No: SJNFEAJ11U1490864

Engine No: HRA2191991A

Reg. Date: 18/11/2015

WS Ref: TP/FC

Claim Type: Third Party

Accident Date: 03/12/2020

TP Veh Reg No: SHB4598K

Not Notified

Repair After Paint

8620h

2days

Estimate Repair Cost to Vehicle No :SKW8254E

Description	U/Price	Quantity	List Price S\$	Amount S\$
Labour				
1 REMOVE & REFIX FRT RH FENDER ARP GARNISH,FRT RH DOOR PROTECTOR,KNOCK & REPAIR FRT RH FENDER & DOOR AND REALIGN THE SAME	300.00	1 LA	300.00	220
2 PUTTY & RESPRAY ON FRT RH DOOR AND FRT RH FENDER	500.00	1 LA	500.00	400
			800.00	800.00
Total				S\$ 800.00
Add GST @ 7%				56.00
Total Amount Payable				S\$ 856.00

For Cheng Hoe Motor Pte Ltd


AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: