

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0039/2021/NS
DATE : 12-Jan-21
WIP : 11048

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR TAY SIONG CHIN
ADDRESS : BLK 544 JELAPANG ROAD
#02-82
SINGAPORE 670544
TELEPHONE : HP +65 98205887
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900168888-01
VEHICLE NO : **SBX 777 S**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI 8W
MODEL YEAR : 30/9/2019
ENGINE NO : CVK 086644
CHASSIS NO : WAUZZZF41KA109105
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 11-Jan-21
PLACE OF ACCIDENT : SLIP ROAD OUT OF KPE TAMOINES ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SBX 777 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	X.
2	TO REMOVE AND REINSTALL AIRCON CONDENSER, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,200.00	X.
3	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 700.00 250	
4	TO DISMANTLE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY.	S/N \$ 280.00	X.
SUB TOTAL LABOUR CHARGES		: \$ 2,660.00	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SBX 777 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
5	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS HEADLIGHT. TO RENEW FRONT LOCK CSRRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,900.00	500 1000
6	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET, HINGES AND LHS FRONT DOOR.	\$ 3,900.00	1100
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 11,652.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SBX 777 S

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER <i>Del'd</i>		\$ 1,787.00	✓
2 FRONT BUMPER FIXING PARTS <i>new</i>		\$ 587.00	+
3 FRONT BUMPER SECURING STRIP <i>new</i>	2	\$ 71.00	+
4 FRONT BUMPER GRILLE - CENTRE <i>new</i>		\$ 196.00	✓
5 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>		\$ 210.00	+
6 FRONT BUMPER AIR GUIDE - LH <i>new</i>		\$ 63.00	+
7 RADIATOR GRILLE <i>new</i>		\$ 1,332.00	✓
8 FRONT BUMPER AIR GUIDE GRILLE - LH/RH <i>LH ?</i>	2	\$ 270.00	?
9 FRONT BUMPER CARRIER <i>?</i>		\$ 845.00	?
10 FRONT BUMPER FOAM FILLER PIECE <i>?</i>		\$ 124.00	?
11 FRONT BUMPER TOP COVER <i>new</i>		\$ 127.00	+
12 FRONT BUMPER GUIDE SECTION - LH <i>new</i>		\$ 36.00	+
13 CAUTION SIGN STICKER <i>new</i>	NEC	\$ 14.00	+
14 AIRCON STICKER <i>new</i>	NEC	\$ 8.00	+
15 LOCK CARRIER BRACKET <i>?</i>		\$ 137.00	?
16 LOCK CARRIER BRACKET SUPPORT - LH/RH <i>?</i>	2	\$ 58.00	?
17 HORN - LH HIGH TONE <i>new</i>		\$ 126.00	+
18 HORN - RH LOW TONE <i>new</i>		\$ 126.00	+
19 SPRING SHACKLE - LH/RH <i>new</i>	2	\$ 58.00	+
20 FRONT PARKING AID SENSOR - INNER/OUTER <i>new</i>	3	\$ 726.00	+
SUB TOTAL SPARE PARTS	:	\$ 6,901.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SBX 777 S

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 FRONT PARKING AID SEAL RING <i>new</i>	4	\$ 14.00	+
22 BONNET <i>Regis</i>		\$ 3,246.00	+
23 BONNET ATTACHMENT PARTS <i>3 new</i>		\$ 412.00	+
24 BONNET LID HINGE - LH/RH	2	\$ 610.00	+
25 BONNET IMPACT PROTECTION - LH/RH/CENTRE <i>Centre Could</i>	3	\$ 84.00	28
26 BONNET RELEASE CABLE <i>3 new</i>		\$ 58.00	+
27 BONNET RELEASE LEVER <i>3 new</i>		\$ 14.00	+
28 BONNET BOWDEN CABLE - CENTRE <i>new</i>		\$ 58.00	+
29 BONNET STRIKER - LH/RH <i>new</i>	2	\$ 100.00	+
30 BONET LID LOCK <i>new</i>	2	\$ 427.00	+
31 FRONT FENDER - LH	2	\$ 767.00	+
32 FRONT FENDER ATTACHMENT PARTS		\$ 202.00	+
33 FRONT FENDER CLOSING ELEMENT - LH		\$ 72.00	+
34 FRONT FENDER BRACKET - LH		\$ 35.00	+
35 FRONT FENDER BRACE - LH		\$ 118.00	+
36 WHEEL HOUSING LINER - LH		\$ 240.00	+
37 WHEEL HOUSING LINER ATTACHMENT PART		\$ 233.00	+
38 WHEEL SPOILER - LH		\$ 73.00	+
39 WHEEL SPOILER TRIM - LH		\$ 35.00	+
40 STONE CHIP GUARD - LH		\$ 51.00	+
SUB TOTAL SPARE PARTS	:	\$ 6,849.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SBX 777 S

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
41 TOP FENDER LEDGE COVER - UPPER		\$ 31.00	+
42 TOP FENDER LEDGE COVER - LOWER		\$ 23.00	+
43 LED HEADLIGHT - LH/RH	2	\$ 15,386.00	7693.
44 LIFT CYLINDER - LH/RH	2	\$ 420.00	+
45 LIFT CYLINDER CORRUGATED PIPE		\$ 93.00	+
46 LOCK CARRIER		\$ 1,016.00	+
47 AIRCON CONDENSER		\$ 622.00	+
48 TEMPERATURE SENSOR BRACKET		\$ 19.00	+
49 READY MIX COOLANT		\$ 179.00	+
50 RADIATOR AIR GUIDE - LH/RH OUTER	2	\$ 56.00	+
51 RADIATOR AIR GUIDE - LH/RH INNER	2	\$ 24.00	+
52 RADIATOR AIR GUIDE - UPPER		\$ 16.00	+
53 RADIATOR AIR GUIDE - LOWER		\$ 22.00	+
54 FRONT NO PLATE	S/N	\$ 60.00	✓
55 SUNDRIES		\$ 300.00	?
TOTAL SPARE PARTS	:	\$ 32,017.00	
TOTAL LABOUR CHARGES	:	\$ 11,652.00	
GRAND TOTAL	:	\$ 43,669.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

:

Adrian King

SURVEYED DATE

:

15/01/21

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

:

Not Authorised, 04 Days.

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT