

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0039/2021/NS
DATE : 12-Jan-21
WIP : 11048

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Adrian

4 days - ok - jb - 22 Mar 21

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR TAY SIONG CHIN
ADDRESS : BLK 544 JELAPANG ROAD
#02-82
SINGAPORE 670544
TELEPHONE : HP +65 98205887
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900168888-01
VEHICLE NO : **SBX 777 S**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI 8W
MODEL YEAR : 30/9/2019
ENGINE NO : CVK 086644
CHASSIS NO : WAUZZZF41KA109105
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 11-Jan-21
PLACE OF ACCIDENT : SLIP ROAD OUT OF KPE TAMOINES ROAD

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SBX 777 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND <i>FRONT PARKING AID. (Reinforcement replaced)</i>	S/N \$ 480.00	\$ 480.00
2	TO REMOVE AND REINSTALL AIRCON CONDENSER, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,200.00	
3	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 700.00	\$ 250.00
4	TO DISMANTLE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY.	S/N \$ 280.00	na
SUB TOTAL LABOUR CHARGES		: \$ 2,660.00	\$ 730.00

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SBX 777 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
	<i>c/f</i>		\$ 730.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS HEADLIGHT. TO RENEW FRONT LOCK CSRRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,900.00	\$ 500.00
6	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET, HINGES AND LHS FRONT DOOR.	\$ 3,900.00	\$ 1,100.00
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 11,652.00	\$ 2,522.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SBX 777 S

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER		\$ 1,787.00	\$ 1,429.60
2	FRONT BUMPER FIXING PARTS		\$ 587.00	
3	FRONT BUMPER SECURING STRIP	2	\$ 71.00	
4	FRONT BUMPER GRILLE - CENTRE		\$ 196.00	\$ 156.40
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE		\$ 210.00	
6	FRONT BUMPER AIR GUIDE - LH		\$ 63.00	
7	RADIATOR GRILLE		\$ 1,332.00	\$ 1,065.60
8	FRONT BUMPER AIR GUIDE GRILLE - LH/RH	2	\$ 270.00	\$ 108.00
9	FRONT BUMPER CARRIER		\$ 845.00	\$ 675.60
10	FRONT BUMPER FOAM FILLER PIECE		\$ 124.00	\$ 99.20
11	FRONT BUMPER TOP COVER		\$ 127.00	\$ 101.60
12	FRONT BUMPER GUIDE SECTION - LH		\$ 36.00	
13	CAUTION SIGN STICKER	NEC	\$ 14.00	\$ 10.88
14	AIRCON STICKER	NEC	\$ 8.00	\$ 5.68
15	LOCK CARRIER BRACKET		\$ 137.00	\$ 109.60
16	LOCK CARRIER BRACKET SUPPORT - LH/RH	2	\$ 58.00	\$ 44.96
17	HORN - LH HIGH TONE		\$ 126.00	
18	HORN - RH LOW TONE		\$ 126.00	
19	SPRING SHACKLE - LH/RH	2	\$ 58.00	
20	FRONT PARKING AID SENSOR - INNER/OUTER	3	\$ 726.00	
SUB TOTAL SPARE PARTS		:	\$ 6,901.00	\$ 3,807.12

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SBX 777 S

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
	<i>c/f</i>		\$ 3,807.12
21 FRONT PARKING AID SEAL RING	4	\$ 14.00	
22 BONNET		\$ 3,246.00	
23 BONNET ATTACHMENT PARTS		\$ 412.00	
24 BONNET LID HINGE - LH/RH	2	\$ 610.00	
25 BONNET IMPACT PROTECTION - LH/RH/CENTRE	3	\$ 84.00	\$ 21.84
26 BONNET RELEASE CABLE		\$ 58.00	
27 BONNET RELEASE LEVER		\$ 14.00	
28 BONNET BOWDEN CABLE - CENTRE		\$ 58.00	
29 BONNET STRIKER - LH/RH	2	\$ 100.00	
30 BONET LID LOCK	2	\$ 427.00	
31 FRONT FENDER - LH		\$ 767.00	
32 FRONT FENDER ATTACHMENT PARTS		\$ 202.00	
33 FRONT FENDER CLOSING ELEMENT - LH		\$ 72.00	
34 FRONT FENDER BRACKET - LH		\$ 35.00	
35 FRONT FENDER BRACE - LH		\$ 118.00	
36 WHEEL HOUSING LINER - LH		\$ 240.00	
37 WHEEL HOUSING LINER ATTACHMENT PART		\$ 233.00	
38 WHEEL SPOILER - LH		\$ 73.00	
39 WHEEL SPOILER TRIM - LH		\$ 35.00	
40 STONE CHIP GUARD - LH		\$ 51.00	
SUB TOTAL SPARE PARTS	:	\$ 6,849.00	\$ 3,828.96

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SBX 777 S

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
	<i>c/f</i>		\$ 3,828.96
41 TOP FENDER LEDGE COVER - UPPER		\$ 31.00	
42 TOP FENDER LEDGE COVER - LOWER		\$ 23.00	
43 LED HEADLIGHT - LH/RH	2	\$ 15,386.00	\$ 6,154.40
44 LIFT CYLINDER - LH/RH	2	\$ 420.00	
45 LIFT CYLINDER CORRUGATED PIPE		\$ 93.00	
46 LOCK CARRIER		\$ 1,016.00	
47 AIRCON CONDENSER		\$ 622.00	
48 TEMPERATURE SENSOR BRACKET		\$ 19.00	
49 READY MIX COOLANT		\$ 179.00	
50 RADIATOR AIR GUIDE - LH/RH OUTER	2	\$ 56.00	\$ 44.64
51 RADIATOR AIR GUIDE - LH/RH INNER	2	\$ 24.00	\$ 18.88
52 RADIATOR AIR GUIDE - UPPER		\$ 16.00	
53 RADIATOR AIR GUIDE - LOWER		\$ 22.00	
54 FRONT NO PLATE	S/N	\$ 60.00	\$ 60.00
55 SUNDRIES		\$ 300.00	\$ 2.56
TOTAL SPARE PARTS	:	\$ 32,017.00	\$ 10,109.44
TOTAL LABOUR CHARGES	:	\$ 11,652.00	\$ 2,522.00
GRAND TOTAL	:	\$ 43,669.00	\$ 12,631.44

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bl-17/02/21



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF
THE AFFECTED VEHICLE. SHOULD WE REQUIRE
FURTHER LAOUR CHARGES AND SPARE PARTS IN THE
PROGRESS OF REPAIR, WE SHALL INFORM YOU
ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT