

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0046/2021/NS
DATE : 14-Jan-21
WIP : 11304

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

*Hi Adrian,**5 days - ok - Jy - 26 Mar 21***ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT****TEL: 6841 0055 - FAX: 6256 4315**

OWNER'S NAME : MR LIM EK CHOW(LIN YICHAO)
ADDRESS : 27 YIO CHU KANG ROAD
#05-07
SINGAPORE 545542
TELEPHONE : HP +65 97623538
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800024297-02
VEHICLE NO : **SKM 2899 L**
MODEL CODE : AUDI Q2 1.0 TFSI S TRONIC
MODEL YEAR : 13/03/2018
ENGINE NO : CHZ 553766
CHASSIS NO : WAUZZZGA9JA030672
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 13-Jan-21
PLACE OF ACCIDENT : CARPARK AT 27 YIO CHU KANG ROAD

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKM 2899 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER LHS FRONT AND REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 800.00	\$ 640.00
2	TO DISMANTLE AND RENEW LHS FRONT AND REAR DOOR. TO REPAIR LHS REAR FENDER. TO INSPECT LHS B-PILLAR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.(Additional \$250 for repair front door)	\$ 2,800.00	\$ 750.00
3	TO REPRAY LHS FRONT DOOR, LHS REAR DOOR, LHS REAR FENDER AND HINGES.	\$ 3,600.00	\$ 1,100.00
4	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	\$ 280.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 7,672.00	\$ 2,962.00



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKM 2899 L

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT DOOR - LH		\$ 2,756.00	
2	FRONT DOOR ATTACHMENT PARTS		\$ 94.00	
3	FRONT DOOR CATCH		\$ 120.00	
4	FRONT DOOR COVER - LH		\$ 257.00	\$ 205.20
5	REAR DOOR - LH		\$ 2,756.00	\$ 2,204.80
6	REAR DOOR OUTER SEAL - LH	NEC	\$ 135.00	\$ 108.00
7	BONDING AGENT	NEC	\$ 49.00	
8	CLEANING SOLUTION	NEC	\$ 68.00	
9	REAR DOOR ATTACHMENT PARTS		\$ 94.00	
10	REAR DOOR CATCH		\$ 120.00	
11	REAR DOOR HINGE HALF-UPPER PART - LH UPPER		\$ 44.00	
12	REAR DOOR HINGE HALF LOWER PART - LH UPPER		\$ 48.00	
13	REAR DOOR HINGE HALF-UPPER PART - LH LOWER		\$ 47.00	
14	REAR DOOR HINGE HALF-LOWER PART - LH LOWER		\$ 44.00	
15	REAR DOOR SEAL - OUTER		\$ 60.00	
16	REAR DOOR COVER - LH		\$ 226.00	\$ 180.40
17	REAR WHEEL COVER - LH		\$ 170.00	\$ 136.00
18	REAR ALUMINIUM RIM - LH		\$ 949.00	\$ 758.80
19	SUNDRIES		\$ 300.00	\$ 5.20
TOTAL SPARE PARTS		:	\$ 8,337.00	\$ 3,598.40
TOTAL LABOUR CHARGES		:	\$ 7,672.00	\$ 2,962.00
GRAND TOTAL		:	\$ 16,009.00	\$ 6,560.40

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

