

KIANG MOTOR

Block 25 Kaki Bukit Road 4 #08-26 Synergy@KB Singapore 417800
HP: 92712214 Fax: (65) 69664526

BLACK EAGLE RENTAL LLP
BLOCK 3020A UBI ROAD 1
01-33
Singapore 408714

TPEQ

18th JAN 2021

XiaoChan

Accident date: 18th OCT 2020

Estimated repair cost for vehicle no:

GBB2377M

TOYOTA DYNA DYNA 150M '08 (COE TIL. 2023 NOV)

S/n	Qty	Items	U/price	Amount
1	1	Front bumper		\$425.10 X
2	1	Front Bumper Side Bracket		\$58.20 X
3	1	Front grille		\$387.72 X
4	4	Front grille clips		\$61.60 30
5	1	Front panel		\$981.40 X
6	1	Front panel top cover (center)		\$387.10 X
7	1	front panel emble logo		\$83.70 X
8	1	Front headlamp -LH		\$681.20 X
9	1	Front headlamp panel		\$351.20 X
10	1	Water pump		\$258.10 X

216402

Subtotal :- \$3,665.32

Labour charges

To check wiring system

Tuff kote

Panel beating

Spray painting

1623.01

890

\$60.00 30

\$100.00 60

\$600.00 400

\$600.00 400

Subtotal :- \$1,360.00

Total :- \$5,025.32

total 2513.01

W/S: 2K

04 Days