Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111 Fax No.: 6257 1330 Tel No.: 6287 6666

CO./GST Reg. No. 201019626G

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

SHD 5426G

SHD 5426G

JTDKB3FU503073670

Not Norhaise

TOYOTA **PRIUS**

5.1.2020

	Third Party Insurer :	AIG	
	Date of Registration :	26/10/2018	
	PART	LI	ST
1	FRONT BUMPER	\$	516.00
1	FRONT BUMPER SIDE RETAINER RH	\$	80.10
1	REINFORCEMENT, FRONT BUMPER	\$	716.60
1	REINFORCEMENT, FRONT BUMPER, NO.2	\$	246.10
1	ABSORBER, FRONT BUMPER, LOWER	\$	132.70
1	ABSORBER, FRONT BUMPER ENERGY	\$	79.60
1	COVER SUB-ASSY, ENGINE, NO.1	\$	472.40
1	COVER SUB-ASSY, ENGINE UNDER, NO.2	\$	241.90
1	EXTENSION, FRONT BUMPER, RH	\$	120.10
1	FRONT LED LAMP (LOWER) RH	\$	951.40
1	FRONT HEADLAMP RH	\$	2,637.60
1	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$	960.50
1	MOTOR, HEADLAMP LEVELING, RH	\$	487.50
1	FRONT FENDER RH	\$	977.80
1	LINER, FRONT FENDER, RH	\$	206.70
1	COVER SUB ASSY, FRONT PILLAR, UPPER RH	\$	100.40
1	FRONT FENDER EMBLEM RH	\$	54.60
1	PAD, FRONT WHEEL OPENING EXTENSION, RH	\$	59.60
1	PROTECTOR, FRONT FENDER SIDE PANEL, RH	\$	93.90
1	FRONT BONNET	\$	983.10
1	HINGE ASSY, HOOD, RH	\$	58.90
1	RIGHT SIDE VIEW MIRROR	\$	1,436.60
1	MOULDING ASSY, BODY ROCKER PANEL, RH	\$	594.80
1	SHAFT ASSY, FRONT DRIVE, RH	\$	1,251.70
1	ARM SUB-ASSY, FRONT SUSPENSION, LOWER NO.1 RH	\$	760.10
1	KNUCKLE, STEERING, RH	\$	663.40
1	FRONT SHOCK ABSORBER	\$	438.30

13 JAN 2020

Sez x

Trans-cab Auto Services Pte Ltd No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No.: 6287 6666 Fax No.: 6257 1330 CO./GST Reg. No. 201019626G SHD 5426G		AAD2001-064
1 SUPPORT SUB-ASSY, FRONT SUSPENSION, RH	\$	236.40
1 EMBLEM ASSY, RADIATOR GRILLE	\$	90.80 Siz x
1 GRILLE SUB-ASSY, RADIATOR	\$	346.00
1 GRILLE, RADIATOR, LOWER NO.1	\$	170.10
TOTAL	\$	16,165.70
25%	\$	4,041.43
	\$	12,124.28
Special Nett		
1 FRONT WHEEL RIM	\$	1,879.40
1 FRONT WHEEL RIM COVER	\$	211.50
1 FRONT TYRE 195/65/15	\$	350.00
1 CLIP, FRONT FENDER LINER	\$	35.00
1 FRONT NUMBER PLATE WITH MOULDING	\$	200.00
1 BUMPER CLIP FRT	\$	66.00 > Sex x
1 FRONT DOOR STICKER 'TRANS-CAB'	\$	100.00
1SET FRONT BUMPER RETAINER CLIP	\$	35.00
1SET ROCKER PANEL MOULDING CLIP	\$	30.00
1SET FRONT FENDER LINER RETAINER	\$	35.00
1SET FRONT FENDER LINER SCREW	\$	35.00
TOTAL	\$	2,976.90
TOTAL PARTS	\$	15,101.18
LABOUR Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The		
Same	\$	an 6,000.00 X
Sume	Ψ	
Putty And Spray Painting Of The Affected Portion.	\$	6,000.00 50
To transfer of door fittings, attachment and perform water		
seepage test.	\$	~~ 170.00 X

Trans-cab Auto Services Pte Ltd

AAD2001-064

No. 2 Ang Mo Kio Street 63 Singapore 569111

Fax No.: 6257 1330 Tel No.: 6287 6666

CO./GST Reg. No. 201019626G

SHD 5426G

LKK Auto Consultanta hazar ata	\$ 30),031.18	
TOTAL	\$ 14	14,930.00	
To Rust-Proofing Of The Affected Areas.	\$ 4	170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	10
To transfer of tire, rim and on wheel balancing.	\$ 4	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$ 5	380.00	X
To check steering geometry and computer wheel alignment	\$ 4	220.00	X
To transfer of Bonnet fittings, attachments and perform water seepage test.	\$ 4	170.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$ 4	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$ 5	380.00	X
To check ABS and brake efficiency, final checking and testing.	\$ 4	380.00	X
To transfer of Front Bumper fittings, attachments and perform water seepage test.	\$ 4	170.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$ N	170.00	X

LKK Auto Consultants hence notify the Repairer of the following:

(PART-BY-PART) Repair Days

20 days Trulay

To resurvey before/after spray painting

To display damaged part(s) during resurvey

Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer