



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /NG KIAT HOE Reg No/Reg Date SKV9678P*ECB+/ 29/10/201 Date In/Mileage / 0 Chassis No KNAF3416MK5019638 Engine No G4FGJH703637 Make/Model KIA/CERATO 1.6 A SR SX G335 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	16/01/2021/ 08:37	QUD	247 / DonBong	27484

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON LH FRONT FENDER REPAIR FRONT BUMPER	1.5 x 410			600 800.00
E PNT98000 PAINT WORK SPRAY FRONT BUMPER, LH FRONT FENDER AND AFFECTED PORTION	CR5 col 480x2			960.00
E PNT88000 REMOVE AND INSTALL FRONT PARKING ASSIST				60.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment				120.00
M SUNDRY LABOUR RENEW LH FRONT SPORT RIM INCLUDING BALANCING				30.00
M SUNDRY SUNDRIES				30 50.00
M PANEL-FENDER,LH	1.00	430.00	20.00	344.00
M BRACKET-FR BUMPER UPR SIDE MTG	1.00	22.00	20.00	17.60
M WHEEL ASSY-ALUMINIUM	1.00	926.00	20.00	740.80

Estimate

SURVEYOR NAME: Steve (LK)
 SURVEYOR SIGNATURE: 18/1/21, 11:30am
 DATE: PIP
 REMARKS: By BR Spj
OO - N/A AL
Excess

3298

Confirm & accepted by

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

4 dys

7% GST on	3272.40	229.07
Nett	3,272.40	
Total Payable		3,501.47

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.