

43 W/STRIP ASSY-RR DR SIDE LH	NEC	1	102	20	81.6
44 GLASS & MOULDING ASSY-QUARTER	NEC	1	252	20	201.6
45 PANEL ASSY-QUARTER OUTER, LH	00	1	1349	20	1079.20
46 GUARD-REAR WHEEL, LH	CRU	1	75	20	60
47 PAD-WINDSHIELD GLASS	NEC	10	2	20	16
48 TRIM-RR STEP PLATE LH	BR	1	12	20	9.6
50 HINGE ASSY-DOOR UPPER, RH	BT	1	26	20	20.8
57 PANEL-SIDE SILL OUTER, LH	00	1	1208	20	966.4

SMN6008L

Supplementary

Labour renew LH rear fender & LH sill panel \$1490 (4 days) ✓
 R & I Rear windscreen \$240 ✓
 Supply Rear windscreen Sealant \$80 ✓
 R & I Inter & cushion \$400 ✓
 R & I Rear compartment \$120 ✓
 R & I fuel tank \$200 ✓
 Paint Side sill panel \$480 ✓
 Total repair days 13 days ✓