TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit Autohub

2 Kaki Bukit Ave 2, #01-17

Singapore 417921

Tel No.: +65 6744 0510 / 6842 0051 Fax No.: +65 6741 0510

Company Reg. No.: 200714616M GST Registration No.: 200714616M

Our Ref:

SKG 276 D

Your ref:

SHA 7679 X

15 January 2021

AXA INSURANCE PTE LTD

8 SHENTON WAY #27-01/02 AXA TOWER SINGAPORE 068811

Attn: Motor Claims Department

Dear Sir/Madam,

DATE OF ACCIDENT: 14 Jan 2021

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

PURSUANT TO PARAGRAPH 2.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

We are instructed by XU ZHIPING to notify you of a road traffic accident on 14 Jan 2021 at about 13:35 HRS along CTE TWDS SLE SLIP RD INTO BRADDELL RD involving our client's vehicle SKG 276 D & SHA 7679 X driven by you/your insured at the material time.

BY EMAIL motor.survey@axa.com.sg ONLY

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please be inform that we don't excess to Merimen System and kindly reply to us by Email / Fax.

Yours faithfully,



Twincar Automotive Pte Ltd