

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

XU ZHIPING
178 JALAN EUNOS #02-09
SINGAPORE 419530

Contact : 86696111

TRAXA.
Xiao Tong.

ESTIMATE

Repair Code : CLM15155

Date in : 14/01/2021

Vehicle Num. : SKG276D

Model : PORSCHE PANAMERA

Chassis/Eng# : WP0ZZZ97ZCL002559/C06796

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>behind</i>	1	2429.70	✓ 2,429.70
REAR BUMPER CENTER GUIDE BRACKET <i>new</i>	1	196.50	✗ 196.50
REAR BUMPER LOWER LID GARNISH <i>behind</i>	1	473.00	✗ 473.00
REAR BUMPER LOWER SPOILER <i>behind</i>	1	1100.00	✓ 1,100.00
REAR BUMPER REINFORCEMENT <i>Dented</i>	1	1045.00	✓ 1,045.00
REAR BUMPER REVERSE SENSOR <i>Dented</i>	2	249.90	✓ 499.80
REAR BUMPER REVERSE SENSOR 'O' RING <i>new</i>	2	6.50	✓ 13.00
REAR BUMPER REVERSE SENSOR HOLDER BRACKET <i>new</i>	4	23.10	✗ 92.40
REAR BUMPER SIDE BRACKET L/R <i>2</i>	2	501.00	✗ 1,002.00
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	97.70	✗ 195.40
REAR BUMPER TOW HOOK COVER <i>new</i>	1	42.00	✗ 42.00
REAR BUMPER UNDER COVER <i>new</i>	1	456.00	✗ 456.00
Subtotal before discount			7,544.80
Percentage discount <i>5% 10%</i>			377.24
Sub-total 1			7,167.56
REAR BUMPER CLIPS - SET <i>new</i>	1	80.00	✗ 80.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

XU ZHIPING

178 JALAN EUNOS #02-09

SINGAPORE 419530

Contact : 86696111

ESTIMATE

Repair Code : CLM15155

Date in : 14/01/2021

Vehicle Num. : SKG276D

Model : PORSCHE PANAMERA

Chassis/Eng# : WP0ZZZ97ZCL002559/C06796

Subtotal before discount 80.00

Percentage discount 0% 0.00

Sub-total 2 80.00

Parts-total 7,247.56

LABOUR

To reset system after repair works

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total 1,590.00

Parts & Labour Total 8,837.56

*** This is a computer-generated document which requires no signature.***

page 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj

03 Days

total: 5744.45

L/S: ASK.

ASK