

FONG MOTORS

1 Kaki Bukit Ave 6 #01-27/45

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AutoBay@ Kaki Bukit, Singapore 417883

Tel: 6748 5648, Email: fongmotors@gmail.com

Estimate of Cost of Repairs

Date

Vehicle No.

Model

Toyota Altis.
MROS3REH104538054 CHASSIS/ENG#

PARTS

S/N	Item	Quantity	Unit Price
1	Tail Gate <i>Buckled</i>	1	\$780.20 ✓
2	Tail Gate Emblem <i>Nec</i>	1	\$49.30 ✓
3	Toyota Altis Emblem <i>Nec</i>	1	\$52.20 ✓
4	Tail Gate Weatherstrip <i>Nol new</i>	1	\$163.80 X.
5	Tail Gate Lock <i>Nol new</i>	1	\$370.40 X
6	End Panel <i>Dented</i>	1	\$659.70 ✓
7	End Panel Electrical Antenna Switch <i>Damaged</i>	1	\$182.65 ✓
8	Rear Bumper Reinforcement <i>Dented</i>	1	\$321.40 ✓
9	Tail Lamp LH/RH <i>LH cracked</i>	2	\$382.30 $\times 2 = 764.60$ 382.30
10	Tail Lamp Lower Bracket <i>NP new</i>	2	\$65.60 $\times 2 = 131.20$ X
11	Tail Lamp Gasket <i>LH Nec</i>	2	\$28.00 $\times 2 = 56$ 28.
12	Rear Bumper <i>Deformed</i>	1	<u>\$652.40</u> 581.50
13	End Panel Garnish <i>Deformed</i>	1	\$283.70 ✓
2491.01			Sub-total 1

NETT ITEMS

1	Rear Bumper Clips <i>New</i>	5	\$6.00 = 30 ✓
2	End Panel Garnish Clip <i>New</i>	5	\$6.00 = 30 ✓
3	Reverse Sensor <i>Damaged</i>	1 Set	\$350.00 200.

Sub-total 2

LABOUR

1	To remove/refit and knock all affected parts (Rear portion)	900 800
2	Spray painting of affected parts	1000 800
3	To remove/refit reverse sensors and antenna switch	120 50
4	Tuff Kote	100 60
5	To transfer upholstery	100 60
6	To check wiring	80 30
	<i>Boothid chrome assembly New</i>	80 60

Parts & Labour Total

total: 4611.01
2/5 37K 06 Days