



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens Singapore 609339 Tel 65684555 Fax 65651240



Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
HO NGAI CHI 182B WOODLANDS STREET 13 #10-749 SINGAPORE 732182 Contact No	Cust No/Name LCV12509/HO NGAI CHI Reg No/Reg Date SMT9237R / 24/07/202 Date In/Mileage / 0 Chassis No KNAF5416ML5087295 Engine No G4FGKH754845 Make/Model KIA/CERATO 1.6 A GT LINE H171 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LCV12509	CRDVCH	18/01/2021/ 11:15		442 / CocoLu	27539			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M SUNDRY								20.00
Sundry								
E PNT88000								1600 2000.00
RENEW REAR BUMPER, BOOTLID, REAR END PANEL. REAR SPOLIAR					400 X 4			
E PNT88000								60.00
REMOVE & INSTALL PARKING SENSOR								200.00
E PNT88000								
REMOVE & INSTALL REAR COMPARTMENT TRIMS								1440 1050.00
E PNT98000 CRS								
SPRAY PAINT FOR REAR BUMPER, REAR END PANEL, BOOTLID					480 X 3			30.00
A 90000001								120.00
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								40 80.00
USING HI-SCAN PRO TEST								
M SUNDRY								
APPLY SEALANT FOR ACCIDENT PORTION								40.00
M SUNDRY								
C&C LOGO								20.00
M SUNDRY								
Sundry								
M COVER-RR BUMPER					1.00	651.00	00.00	651.00
M COVER-RR BUMPER LWR					1.00	241.00	00.00	241.00
M COVER-RR BUMPER FOG LAMP, RH					1.00	19.00	00.00	19.00
M LAMP ASSY-SIDE T/SIGNAL, RH					1.00	181.00	00.00	181.00
M BRACKET-RR BEAM UPR MTG, RH					1.00	9.00	00.00	9.00
M BRACKET-RR BEAM UPR MTG, LH					1.00	9.00	00.00	9.00
M BRACKET-RR BEAM LWR, CTR					1.00	6.00	00.00	6.00
P BRACKET-RR BEAM LWR MTG					2.00	6.00	00.00	12.00
M BEAM-RR BUMPER					1.00	318.00	00.00	318.00
M ANTENNA ASSY-SMARTKEY					1.00	46.00	00.00	46.00
M STAY-RR BUMPER RH					1.00	65.00	00.00	65.00
M STAY-RR BUMPER LH					1.00	65.00	00.00	65.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



& CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



g No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
HO NGAI CHI 182B WOODLANDS STREET 13 #10-749 SINGAPORE 732182 Contact No	Cust No/Name LCV12509/HO NGAI CHI Reg No/Reg Date SMT9237R / 24/07/202 Date In/Mileage / 0 Chassis No KNAF5416ML5087295 Engine No G4FGKH754845 Make/Model KIA/CERATO 1.6 A GT LINE H171 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LCV12509	CRDVCH	18/01/2021/ 11:15		442 / CocoLu	27539			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
					1.00	25.00	00.00	25.00
M	BRACKET ASSY-RR BPR SIDE UPR,L	1	X NM		1.00	31.00	00.00	31.00
M	BRACKET-ASSY RR BPR SIDE UPR,R		X NM		1.00	1297.00	00.00	1297.00
M	PANEL ASSY-TRUNK LID	00			1.00	324.00	00.00	324.00
M	PANEL ASSY-BACK	00			1.00	32.00	00.00	32.00
M	LOGO ASSY-KIA SUB	rec			1.00	28.00	00.00	28.00
M	EMBLEM-CERATO	rec			1.00	45.00	00.00	45.00
M	EMBLEM-GT LINE	rec			1.00	100.00	00.00	100.00
M	W/STRIP-TRUNK LID OPNG	CR4			1.00	112.00	00.00	112.00
M	LATCH ASSY-TRUNK LID	X MAI	X NM		1.00	41.00	00.00	41.00
M	TRIM ASSY-RR TRANSVERSE				1.00	608.00	00.00	608.00
M	LAMP ASSY-REAR COMB INSIDE, RH	CUT			1.00	675.00	00.00	675.00
M	LAMP ASSY-REAR COMB OUTSIDE, RH	CUT			1.00	690.00	00.00	690.00
M	LAMP ASSY-CENTER GARNISH	1	X NM		1.00	19.00	00.00	19.00
M	LAMP ASSY-LUGGAGE & GLOVE	1	X NM		1.00	19.00	00.00	19.00

Steve (LKK) 18/1/21, 1.30pm

OD - N/A AL

Excess - ?

P/P

M B/L S/T

7 d/s

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Confirm & accepted by

Acknowledged by Repairer

Signature:

Date:

7% GST on Net 9,269.00  
9269.00  
Total Payable 9,917.83

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.