

FIRST AUTOWORKS

Repair Estimate

Date : 12/01/2021

Reference: SMV 1335H

To Whom It May Concern

Make: OPEL
Astra

Dear Sir,

RE: VEHICLE : SMV 1335H
CHASSIS NO.: W0VBE6ETXLG053354
ENGINE NO.: N219324XHKKX0874

Name of insured : SARKAR KAUSIK
Date of accident.: 10/01/2021

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	REAR BUMPER UPPER <i>Defend</i>	1,680.00 ✓
2	1	REAR BUMPER LOWER <i>new</i>	658.00 +
3	1	REAR BUMPER TOW COVER	34.00 +
4	1	REAR BUMPER REFLECTOR RH	63.00 +
5	1	REAR BUMPER REFLECTOR LH	63.00 +
6	1	REAR END PANEL	487.00 +
7	1	REINFORCEMENT, RR END PANEL	970.00 ✓
8	1	REAR BUMPER GUIDE LH	87.00 ✓
9	1	REAR BUMPER GUIDE RH	87.00 ✓
10	1	REAR BUMPER GUIDE CENTER	95.00 ✓
11	1	REAR TAILGATE	2,280.00 +
12	1	REAR OPEL EMBLEM	120.00 -
13	1	LETTERING ASTRA	110.00 -

Parts Total: 6,734.00
Less 10%: 673.40
Total : 6,060.60

3149
2834.10

Labour

No.	Labour Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	2200.00 <i>1625</i>
2	Carry out spray painting on accident affected area. (Rear Tailgate, Rear bumper, Rear end panel)	1900.00 <i>1650</i>
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	150.00 <i>30</i>
4	Remove and refit reverse sensor (Labour)	130.00 <i>60</i>

Labour Total : 4,380.00

3365

Other


<u>No.</u>	<u>Other Description</u>	<u>Price (SGD)</u>
1	Sealant <i>mu</i>	50.00 <i>x</i>
2	Rear number plate <i>mu</i>	40.00 <i>✓</i>
3	Rear Bumper Clip Set <i>se</i>	40.00 <i>✓</i>

Other Total : 130.00

Total : \$10,570.60
Gst (7%) : \$739.94
GRAND TOTAL: \$11,310.54

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully


Service Advisor
Ronnie Tan
DID: 6844 1985 Fax:6844 5185

Adnan Lj

P/P 15/01/21

04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Supplementary: 1627.00

total: 7906.30
(P/P)

VEHICLE NO: SMV 1335 H

VEHICLE NO: SMV 1335 H

[illegible]