## FIRST AUTOWORKS

## 1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 ( South Wing) Singapore 415933 Tel: 68441985 Fax: 68445185

## **TAX INVOICE**

AIG Asia Pacific Insurance Pte. Ltd. AIG Building 78 Shenton Way #07-16, Singapore 079120

GST Ref. No:

M2-0111811-5

Vehicle No: SMV 1335H

**DESCRIPTION** 

Invoice No: CGI-ASC-21IR02068G

Chasis No : W0VBE6ETXLG053354

Invoice Date:

2/11/2021

Engine No: N219324XHXKX0874

AMOUNT SGD

Parts			
No.	Qty.	Description	Price (SGD)
	1	REAR BUMPER UPPER	1,680.00
1 2 3 4 5 6 7	1	REINFORCEMENT, RR END PANEL	970.00
3	1	REAR BUMPER GUIDE LH	87.00
4	1	REAR BUMPER GUIDE RH	87.00
<u>5</u>	1	REAR BUMPER GUIDE CENTER	95.00
<u>6</u>	1	REAR OPEL EMBLEM	120.00
7	1	LETTERING ASTRA	110.00
Supplemen	ntary Itei	<u>ms</u>	
<u>8</u>	1	REVERSE CAMERA	318.00
9	2	RR NUMBER PLATE LAMP	132.00
<u>10</u>	2	RR END PANEL AIR DUCT	232.00
<u>11</u>	1	RR BUMPER BRACKET RH	96.00
<u>12</u>	1	RR BUMPER BRACKET LH	86.00
<u>13</u>	1	RR END PANEL TOP GARNISH	280.00
8 9 10 11 12 13 14 15	1	RR KEYLESS RECEIVER SENSOR	274.00
<u>15</u>	1	RR BUMPER REVERSE SENSOR WIRE HARNESS	390.00

Total: 4957.00 Less 10%: 495.70 Parts Total : 4461.30

<u>Description</u>	Price (SGD)
To dismantle / renew the accident damaged portion, to panel	
beating, reshape, straighten, orientate & align repair / replacement parts	1,625.00
Carry out spray painting on accident affected area. (Rear Tailgate, Rear bumper, Rear end panel)	1,650.00
To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	30.00
Remove and refit reverse sensor (Labour)	60.00
	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate & align repair / replacement parts Carry out spray painting on accident affected area. ( Rear Tailgate, Rear bumper, Rear end panel) To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair

Labour Total:

3365.00

Other				
No.		Other Description	Pr	ice (SGD)
<u>1</u>	Rear number plate			40.00
2	Rear Bumper clip Set			40.00
			Other Total:	80.00

Total:

7906.30

GST (7%)

553.44

Grand Total: 8459.74

Yours Faithfully,

Ronnie Tan Service Advisor

Tel: 68441985 Fax:68445185

E&OE

ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "1 ST AUTOWORKS PTE LTD".

PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.