

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21000804/AEA3Q2**Date:** 20/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070112285
Claimant Vehicle No :	FBJ3798K	Insured Vehicle No :	SMU1403A
Date of Loss:	08/01/2021	Nature of Claim:	TP
		Claim No:	5687999982SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBJ3798K	Engine No:	21CG044165
Make & Model:	YAMAHA FZ16, 153cc (M)	Chassis No:	ME121C0G1E2044133
Reg. Date:	25/04/2014 (Man. Year: 2013)	Odometer:	0 km
Colour:	Black		
Engine Capacity:	153 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/80 R17	Rear Tyre Size:	130/70 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,649.28	1,176.03	3,473.25	74.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,280.00	480.00	800.00	62.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,929.28	1,656.03	4,273.25	72.07
Approved Total (Overridden) (S\$)		1,300.00		
(S\$)	5,929.28	1,300.00	4,629.28	78.07
+ GST 7.00/7.00% (S\$)	415.05	91.00	324.05	78.07
Nett Amount (S\$)	6,344.33	1,391.00	4,953.33	78.07
+ Loss of Use (6.0 x S\$30.00/day) (S\$)		180.00		
Nett Liability (S\$)		1,571.00		
Global Sum Settlement (S\$)		1,400.00		

INSPECTION

Date of Assignment:	18/01/2021	Ms Car Auto Pte Ltd (HQ) 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT Singapore 415875
Date Inspected:	18/01/2021 Inspected At:	
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET MIRROR (RIZOMA)	Cut	145.00 FL	*145.00 FL
2	1		*HANDLE BAR	Not Necessary	289.40 FL	*- FL
3	1		*HANDLE BAR STEM	Not Necessary	124.80 FL	*- FL
4	1		*HEADLAMP ASSY	Cut	327.10 FL	*327.10 FL
5	1		*HEADLAMP COWLING	Not Necessary	122.80 FL	*- FL
6	1		*HEADLAMP GARNISH	Cut	75.00 FL	*75.00 FL
7	1		*HEADLAMP STAY	Not Necessary	92.40 FL	*- FL
8	1		*HEADLAMP WIRE	Not Necessary	60.00 FL	*- FL
9	1		*BALANCER	Cut	78.40 FL	*45.00 FL
10	1		*FRONT SIGNAL L+R	N/S Cut	180.00 FL	*40.00 FL
11	1		*CLUSTER METER	Not Necessary	524.60 FL	*- FL
12	1		*CLUTCH LEVER (RIZOMA)	Cut	135.60 FL	*60.00 FL
13	1		*FORK ASSY (LH)	Bent	586.70 FL	*293.00 FL
14	1		*FORK STEM	Damaged	68.20 FL	*68.20 FL
15	1		*GEAR PEDAL	Not Necessary	164.30 FL	*- FL
16	1		*FRONT BRAKE DISC	Not Necessary	200.00 FL	*- FL
17	2		*FRONT WHEEL BEARING	Not Necessary	50.00 FL	*- FL
18	1		*FRONT WHEEL SHAFT NUT	Not Necessary	30.00 FL	*- FL
19	1		*FUEL TANK COWLING	Not Necessary	179.50 FL	*- FL
20	1		*FRONT SIDE COWLING LH	Cracked	78.40 FL	*78.40 FL
21	1		*BRAKE PEDAL	Cut	75.00 FL	*75.00 FL
22	1		*FRONT FOOT REST PEG LH	Cut	50.00 FL	*50.00 FL
23	1		*IU UNIT	Not Necessary	180.80 FS	*- FS
24	1		*TAIL BOX	Not Necessary	320.00 FS	*- FS
25	1		*HELMET	Not Necessary	250.00 FS	*- FS
26	1		*FORK OIL	Necessary	45.00 FS	*45.00 FS
27	1		*FRONT WHEEL RIM	Not Necessary	350.00 FS	*- FS
28	1		*FRONT TYRE	Not Necessary	200.00 FS	*- FS
29	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,013.00	1,301.70
- List Item Discount on L Items 10.00/10.00% (\$\$)	363.72	125.67
Total Parts (\$\$)	4,649.28	1,176.03

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WORKMANSHIP	New	600.00	200.00
2	SPRAYPAINTING	New	400.00	200.00
3	ELECTRICAL	New	80.00	30.00
4	BALANCE FRONT WHEEL	New	50.00	0.00
5	CHECK CHASSIS ALIGNMENT	New	50.00	0.00
6	REBLEED BRAKE SYSTEM	New	100.00	50.00
Gross Labour Cost (\$\$)			1,280.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >