

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/LHI/0005/2021
DATE : 16-JAN-2021

UNITED OVERSEAS INSURANCE LIMITED
3 ANSON ROAD
#28-01 SPRINGLEAF TOWER
S(079909)
TEL : 62227733(16 LINES)
FAX : 2242718
UPDATED 16JUN2005

OWNER'S NAME : WONG KOK WAH
ADDRESS : APT BLK 20 JALAN MEMBINA
#15-42
S(164020)
TELEPHONE NO : 98386487

TYPE OF CLAIM : COMPREHENSIVE CLAIM
POLICY NO : 1
VEHICLE NO : SLZ2892A
MODEL CODE : SJ5EK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20YD36834
CHASSIS NO : JF1SJ5KC5JG107854
MILEAGE : 1 KM
DATE IN : 16/01/2021
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : JEFF TEH TENG CHUEN
ACCIDENT DATE : 16/01/2021

Print Date : 16/01/2021
Print Time : 18:52:46

MOTORIMAGE ENTERPRISES PTE. LTD.,
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLZ2892A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	SPG	TO SUPPLY & INSTALL FRONT SPORTY GRILLE	50.00	
2	ZZ/001	TO REPAIR AND REPLACE FRONT BUMPER, FRONT BONNET, FRONT BOTH SIDE FENDER, ENERGY ABSORBER, FRONT	2800.00	
3	ZZ/002	UNDERSPOILER AND FRONT SUPPORT PANEL		
4	ZZ/003	TO RESPRAY FRONT BONNET, FRONT BUMPER, FRONT BOTH SIDE FENDER, FRONT BUMPER BEAM AND FRONT SUPPORT	3520.00	
5	ZZ/004	PANEL		
6	ZZ/005	TO CONDUCT FRONT LIGHTING SYSTEM TEST	100.00	
7	ZZ/006	TO CONDUCT FRONT HEADLAMP WASHER TEST	100.00	
8	ZZ/007	SUNDRIES	50.00	
TOTAL LABOUR CHARGES			6620.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLZ2892A

S/NO PARTS DESCRIPTION		PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	RAD PNL COMPL RPR	53029SG0019P	360.00			
2	FRT FENDER RH	57120SG0209P	270.00			
3	FRT FENDER LH	57120SG0309P	270.00			
4	HOOD F CPL	57229SG0009P	882.00			
5	BRKT CORNER F RH	57707SG000	36.00			
6	BRKT CORNER F LH	57707SG010	36.00			
7	BUMPER COVER FRT (FOR HL/W)	57709SG011	594.00			
8	BACK BEAM CPL F	57711SG0009P	288.00			
9	ENERGY ABSOR F	57722SG020	126.00			
10	COVER HOOK F SP	57731SG070	5.40			
11	COVER FOG F SP RH	57731SG080	43.20			
12	COVER FOG F SP LH	57731SG090	43.20			
13	COVER SD F SP RH	57731SG120	12.60			
14	COVER SD F SP LH	57731SG130	12.60			
15	LAMP ASSY HEAD EOF RIGHT SIDE	84002SG222	2380.00			
16	LAMP ASSY HEAD EOF LH	84002SG232	2380.00			
17	FOG LAMP ASSY F *2	84501AJ060	544.00			
18	BRKT F FOG ASSY RH	84927SG020	19.80			
19	BRKT F FOG ASSY LH	84927SG030	19.80			
20	NOZZLE H L WASHERRH	(SUPP) 86636SG361	79.20			
21	NOZZLE H L WASHERLH	86636SG371	79.20			
22	NOZZLE COVER ASSYRH	86636SG380EN	54.00			
23	NOZZLE COVER ASSYLH	86636SG390EN	54.00			
24	BRKT GRILLE LWR NA	91165SG000	21.60			
25	ORNAMENT F	93013SG050	68.40			

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

		DAMAGED PARTS & PRICES					
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST	REMARKS
26	FRONT GRILLE	J1010SG101	1200.00				
27	FORESTER 2.0I-S KIT FRONT UNDER SPOILER (TCS)	TCS-FJ8-FL-002	1396.00				
SUB TOTAL			11275.00	0.00	0.00	0.00	
LESS DISCOUNT (NETT-20 %)			2255.00	0.00	0.00	0.00	
GRAND TOTAL			9020.00	0.00	0.00	0.00	
OVERALL TOTAL			9020.00				

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLZ2892A

TOTAL LABOUR CHARGES	6620.00
TOTAL SPARE PARTS CHARGES	9020.00
GRAND TOTAL	15640.00 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.