



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909			Ref: CS/UOI21000806/R1tf3e2	
			Date: 16/03/2021	
			Code: UOI2	
<b>1. Policy Particulars :- OWN DAMAGE</b>				
	<b>Insured Veh.</b>		<b>Veh. Inspected</b>	SLZ 2892A
	<b>Policy No.</b>	DHOM110167641901	<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	M11D11802102	<b>Excess (\$)</b>	500.00
	<b>Assign From</b>	JOSEPHINE WONG	<b>Assign Date</b>	18/01/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	SUBARU FORESTER 2.0I	<b>c.c</b>	1995
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2018
	<b>Chassis No.</b>	JF1SJ5KC5JG107854	<b>Colour</b>	GREY
	<b>Odometer</b>	63489 KM	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
	<b>General</b>	FAIR		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	225/60 R17	MICHELIN	6 mm
	<b>L/H Front Tyre</b>	225/60 R17	MICHELIN	6 mm
	<b>R/H Rear Tyre</b>	225/60 R17	MICHELIN	6 mm
	<b>L/H Rear Tyre</b>	225/60 R17	MICHELIN	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	13/01/2021	<b>Inspection Date</b>	22/01/2021
	<b>Survey held at</b>	25 LENG KEE ROAD		
	<b>Repairer</b>	MOTOR IMAGE ENTERPRISES PTE LTD		
<b>5a. Remarks</b>				
	A)THE MARKET VALUE IS S\$79,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>	