

Veh No: 201 Prime Mover
- car / M.Cycle / Bus / Van / Lorry / Taxi

١٠٠

OWNER'S NAME : WONG KOK WAH
ADDRESS : APT BLK 20 JALAN MEMBINA
#15-42
S(164020)
TELEPHONE NO : 98386487

```
Print Date      : 16/01/2021
Print Time     : 18:52:46
```

ED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLZ2892A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	SPG	TO SUPPLY & INSTALL FRONT SPORTY GRILLE	50.00	30
2	ZZ/001	TO REPAIR AND REPLACE FRONT BUMPER, FRONT BONNET, FRONT BOTH SIDE FENDER, ENERGY ABSORBER, FRONT	2800.00	1120
3	ZZ/002	UNDERSPOILER AND FRONT SUPPORT PANEL		
4	ZZ/003	TO RESPRAY FRONT BONNET, FRONT BUMPER, FRONT BOTH SIDE FENDER, FRONT BUMPER BEAM AND FRONT SUPPORT	3520.00	840
5	ZZ/004	PANEL		
6	ZZ/005	TO CONDUCT FRONT LIGHTING SYSTEM TEST	100.00	80
7	ZZ/006	TO CONDUCT FRONT HEADLAMP WASHER TEST	100.00	60
8	ZZ/007	SUNDRIES	50.00	20
9	ZZ/008	TO SUPPLY AND REPLACE FRONT LICENSE PLATE WITH CASING	55.00	64

TOTAL LABOUR CHARGES

6675.00

MOTORIMAGES PTE. LTD.

ROAD

59097

LIST FOR ACCIDENT VEHICLE REGN NO SLZ2892A

DAMAGED PARTS & PRICES

S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
1	RAD PNL COMPL RPR	53029SG0019P	360.00			
2	FRT FENDER RH	57120SG0209P	270.00			
3	FRT FENDER LH	57120SG0309P	270.00			
4	HOOD F CPL	57229SG0009P	882.00			
5	BRKT CORNER F RH	57707SG000	36.00			
6	BRKT CORNER F LH	57707SG010	36.00			
7	BUMPER COVER FRT (FOR HL/W)	57709SG011	594.00			
8	BACK BEAM CPL F	57711SG0009P	288.00			
9	ENERGY ABSOR F	57722SG020	126.00			
10	COVER HOOK F SP	57731SG070	5.40			
11	COVER FOG F SP RH	57731SG080	43.20			
12	COVER FOG F SP LH	57731SG090	43.20			
13	COVER SD F SP RH	57731SG120	12.60			
14	COVER SD F SP LH	57731SG130	12.60			
15	LAMP ASSY HEAD EOF RIGHT SIDE	84002SG222	2380.00			
16	LAMP ASSY HEAD EOF LH	84002SG232	2380.00			
17	FOG LAMP ASSY F	84501AJ060	544.00			
18	BRKT F FOG ASSY RH	84927SG020	19.80			
19	BRKT F FOG ASSY LH	84927SG030	19.80			
20	NOZZLE H L WASHERRH	(SUPP) 86636SG361	79.20			
21	NOZZLE H L WASHERLH	86636SG371	79.20			
22	NOZZLE COVER ASSYRH	86636SG380EN	54.00			
23	NOZZLE COVER ASSYLH	86636SG390EN	54.00			
24	BRKT GRILLE LWR NA	91165SG000	21.60			
25	ORNAMENT F	93013SG050	68.40			

Truck / Trailer or

Truck / Trailer or

ad Cost:

MOTORIMAGES ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 160007

FOR ACCIDENT VEHICLE REGN NO SLZ2892A

PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
6 FRONT GRILLE <i>sub</i>	J1010SG101	1200.00			
27 FORESTER 2.0I-S KIT FRONT UNDER SPOILER (TCS) <i>crn</i>	TCS-FJ8-FL-002	1396.00			
SUB TOTAL		11275.00	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)		2255.00	0.00	0.00	0.00
GRAND TOTAL		9020.00	0.00	0.00	0.00
OVERALL TOTAL		9020.00			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

Type: motor vehicle
Truck / Trailer or

Cost:

ERPRISES PTE. LTD.

OAD
9097

OF ESTIMATE FOR VEHICLE REGN NO SLZ2892A

LABOUR CHARGES	6620.00
AL SPARE PARTS CHARGES	9020.00
GRAND TOTAL	15640.00 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME : Rasul - Hp 90010068
SURVEYED DATE : 22/01/2021 @ 1120
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00 5 days
LIABILITY : 0.00
REMARKS : EXCESS: TBA

REPAIR
Resurvey before paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Type: M/Car / M/Cycle / Bus / Van / Light Truck / Heavy Truck / Trailer or

Truck / Trailer or