

MOTORIMAGE ENTERPRISES PTE. LTD.  
25 LENG KEE ROAD  
SINGAPORE 159097

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLZ2892A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	SPG	TO SUPPLY & INSTALL FRONT SPORTY GRILLE	50.00	30.00
2	ZZ/001	TO REPAIR AND REPLACE FRONT BUMPER, FRONT BUMPER AND FRONT UNDERSPOILER	2800.00	1120.00
3	ZZ/003	TO RESPRAY FRONT BONNET AND FRONT BUMPER	3520.00	840.00
4	ZZ/005	TO CONDUCT FRONT LIGHTING SYSTEM TEST	100.00	80.00
5	ZZ/006	TO CONDUCT FRONT HEADLAMP WASHER TEST	100.00	60.00
6	ZZ/007	SUNDRIES	50.00	20.00
7	ZZ/008	TO SUPPLY AND REPLACE FRONT LICENSE PLATE WITH CASING	55.00	55.00
8	ZZ/009	TO REPLACE AND RESPRAY FRONT BUMPER BEAM (SUPP)	280.00	280.00
9	ZZ/10	TO REPLACE AND RESPRAY FRONT LHS FENDER (SUPP)	560.00	560.00
TOTAL LABOUR CHARGES			7515.00	3045.00