

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/LHI/0005/2021
DATE : 16-JAN-2021

UNITED OVERSEAS INSURANCE LIMITED
3 ANSON ROAD
#28-01 SPRINGLEAF TOWER
S(079909)
TEL : 62227733(16 LINES)
FAX : 2242718
UPDATED 16JUN2005

OWNER'S NAME : WONG KOK WAH
ADDRESS : APT BLK 20 JALAN MEMBINA
#15-42
S(164020)
TELEPHONE NO : 98386487

TYPE OF CLAIM : COMPREHENSIVE CLAIM
POLICY NO : 1
VEHICLE NO : SLZ2892A
MODEL CODE : SJ5EK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20YD36834
CHASSIS NO : JF1SJ5KC5JG107854
MILEAGE : 1 KM
DATE IN : 16/01/2021
LIABILITY : 0.00
EXCESS CLAUSE : 500.00
ESTIMATE BY : CALVIN TAN CHONG ENG
ACCIDENT DATE : 16/01/2021

Print Date : 10/02/2021
Print Time : 19:25:32

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLZ2892A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	SPG	TO SUPPLY & INSTALL FRONT SPORTY GRILLE	50.00	30.00
2	ZZ/001	TO REPAIR AND REPLACE FRONT BUMPER, FRONT BUMPER AND FRONT UNDERSPOILER	2800.00	1120.00
3	ZZ/003	TO RESPRAY FRONT BONNET AND FRONT BUMPER	3520.00	840.00
4	ZZ/005	TO CONDUCT FRONT LIGHTING SYSTEM TEST	100.00	80.00
5	ZZ/006	TO CONDUCT FRONT HEADLAMP WASHER TEST	100.00	60.00
6	ZZ/007	SUNDRIES	50.00	20.00
7	ZZ/008	TO SUPPLY AND REPLACE FRONT LICENSE PLATE WITH CASING	55.00	55.00
8	ZZ/009	TO REPLACE AND RESPRAY FRONT BUMPER BEAM (SUPP)	280.00	280.00
9	ZZ/10	TO REPLACE AND RESPRAY FRONT LHS FENDER (SUPP)	560.00	560.00
TOTAL LABOUR CHARGES			7515.00	3045.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLZ2892A

		DAMAGED PARTS & PRICES					
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST	REMARKS
1	RAD PNL COMPL RPR	53029SG0019P	360.00				X
2	FRT FENDER RH	57120SG0209P	270.00				X
3	FRT FENDER LH (SUPP)	57120SG0309P	270.00				OK
4	HOOD F CPL	57229SG0009P	882.00				OK
5	BRKT CORNER F RH	57707SG000	36.00				OK
6	BRKT CORNER F LH	57707SG010	36.00				OK
7	BUMPER COVER FRT (FOR HL/W)	57709SG011	594.00				OK
8	BACK BEAM CPL F (SUPP)	57711SG0009P	288.00				OK
9	ENERGY ABSOR F (SUPP)	57722SG020	126.00				OK
10	COVER HOOK F SP (SUPP)	57731SG070	5.40				OK
11	COVER FOG F SP RH	57731SG080	43.20				X
12	COVER FOG F SP LH	57731SG090	43.20				X
13	COVER SD F SP RH	57731SG120	12.60				OK
14	COVER SD F SP LH	57731SG130	12.60				X
15	LAMP ASSY HEAD EOF RIGHT SIDE	84002SG222	2380.00				X
16	LAMP ASSY HEAD EOF LH	84002SG232	2380.00				OK
17	FOG LAMP ASSY F *2	84501AJ060	544.00				X
18	BRKT F FOG ASSY RH	84927SG020	19.80				X
19	BRKT F FOG ASSY LH	84927SG030	19.80				X
20	NOZZLE H L WASHERRH	(SUPP) 86636SG361	79.20				OK
21	NOZZLE H L WASHERLH	86636SG371	79.20				X
22	NOZZLE COVER ASSYRH	86636SG380EN	54.00				OK
23	NOZZLE COVER ASSYLH	86636SG390EN	54.00				OK
24	BRKT GRILLE LWR NA	91165SG000	21.60				OK
25	ORNAMENT F	93013SG050	68.40				OK

		DAMAGED PARTS & PRICES					
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST	REMARKS
26	FRONT GRILLE	J1010SG101	1200.00				OK
27	FORESTER 2.0I-S KIT FRONT UNDER SPOILER (TCS)	TCS-FJ8-FL-002	1396.00				OK
SUB TOTAL			7503.20	0.00	0.00	0.00	
LESS DISCOUNT (NETT-20 %)			1500.64	0.00	0.00	0.00	
GRAND TOTAL			6002.56	0.00	0.00	0.00	
OVERALL TOTAL			6002.56				

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLZ2892A

NETT ITEM	7503.20
LESS 20 %	-1500.64
NETT AMOUNT	6002.56

LIST ITEM	0.00
LESS 50 %	0.00
LIST AMOUNT	0.00

SPECIAL NETT AMOUNT	0.00
---------------------	------

S/LIST ITEM	0.00
LESS 30 %	0.00
S/LIST AMOUNT	0.00

TOTAL LABOUR CHARGES	3045.00
TOTAL SPARE PARTS CHARGES	6002.56

TOTAL CHARGES	9047.56
LESS EXCESS	500.00

TOTAL	8547.56
ADD 7 % GST	598.33

GRAND TOTAL	9145.89
-------------	---------
