



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: LYNN KHONG			Ref: CC4/ASM19012128/Bha3s2 Date: 19/02/2020 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 7917D	Veh. Inspected	SLC 2633C	
Policy No.	VPX/P1680520	Coverage (\$)	0.00	
Claim No.	S9M01TAS	Excess (\$)	0.00	
Assign From	LYNN KHONG	Assign Date	09/07/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA ACCORD	c.c	2354	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	MRHCP2630AP060005	Colour	BLACK	
Odometer	224531 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R17	GOODYEAR	6 mm	
L/H Front Tyre	225/50 R17	GOODYEAR	6 mm	
R/H Rear Tyre	225/50 R17	GOODYEAR	6 mm	
L/H Rear Tyre	225/50 R17	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/07/2019	Inspection Date	09/07/2019	
Survey held at	160 SIN MING DRIVE #01-14			
Repairer	TEAM AUTOPRO PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	