

SJE :

Date of Survey :

Date of ReSurvey:

Contacts :

After-Paint:

Vehicle Nos : **SLC 2633C**

Model : Honda Accord

Year :

Chassis No :

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear bumper	1	\$ 1,099.60	\$ 766.30 1,099.60
2	Rear bumper retainer	2	\$ 91.70	\$ 183.40
3	Rear bumper side garnish	1	\$ 88.30	\$ 88.30
4	Taillamp Lh	1	\$ 448.80	\$ 341.95 448.80
5	Taillamp lower bracket Lh	1	\$ 78.70	\$ 78.70
6	Rear fender Lh	1	\$ 1,215.00	\$ 1,215.00
7	Rear fender inner shield Lh	1	\$ 108.10	\$ 108.10
8	Rear door	1	\$ 817.60	\$ 817.60
9	Rear door regulator assy	1	\$ 575.00	\$ 575.00
10	Rear control arm Lh	1	\$ 117.70	\$ 117.70
11	Lower arm Lh	1	\$ 316.00	\$ 316.00
12	Centre arm Lh	1	\$ 326.00	\$ 326.00
13	Rear shock absorber Lh	1	\$ 310.10	\$ 310.10
14	Rear knuckle arm Lh	1	\$ 431.30	\$ 386.20 431.30
15	Rear knuckle arm bearing Lh	1	\$ 315.40	\$ 185.00 315.40
16	Rear windscreen moulding	1	\$ 180.00	\$ 180.00
Parts Sub Total :				\$ 6,611.00
20% Discount :				\$ 1,322.20
PARTS TOTAL :				\$ 5,288.80

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Rear bumper clips	1	\$ 50.00	\$ 30.00 50.00
2	Taillamp clips Lh	1	\$ 50.00	\$ 30.00 50.00
3	Rear fender inner shield clips	1	\$ 50.00	\$ 50.00
4	Rear alloy Rim R17	1	\$ 500.00	\$ 200.00 500.00
5	Rear windscreen inner seal	1	\$ 120.00	\$ 60.00 120.00
6	Rear windscreen primer and cleaner	1	\$ 80.00	\$ 80.00
7	Rear windscreen clips	1	\$ 50.00	\$ 30.00 50.00
8	Sundries	1	\$ 60.00	\$ 60.00
SPECIAL NETT TOTAL :				\$ 960.00

Nos.	LABOUR	S\$
1	R&R fuel tank hose	\$ 80.00 150.00
2	R&R rear windscreen	\$ 120.00 250.00
3	R&R rear rim Lh	\$ 80.00
4	R&R undercarriage	\$ 150.00 250.00
5	R&R wire harness to facilitate repair and check function	\$ 50.00 80.00
6	4 wheels alignment	\$ 65.00
7	Panel beat	\$ 1000.00 1,600.00
8	Rust proofing	\$ 600.00 150.00
9	Spray painting	\$ 800.00 1,400.00
LABOUR TOTAL :		\$ 4,025.00

SPECIAL NETT TOTAL : \$ 960.00

LABOUR TOTAL : \$ 4,025.00

GRAND TOTAL : \$ 10,273.80

Min / Tctim
1710 hrs

Resurvey on 10/7/19

Lump sum repair

Repair days 7

REPAIR LIMIT: \$4650.00