



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883
Company GST Registration No : 201828067M

VEHICLE INSPECTION ESTIMATE

M/S : AUTO & GENERAL INSURANCE (S) P L
(MOTOR CLAIM DEPARTMENT)

Email claims@gadgetdirect.com.sg

Xiao Chen.

Parts - (%)	
SN	
Labour	
Lump sum	
ERV	

Vehicle No: SJA4895J

Date: 15.01.2021

Veh. Model SUZUKI SWIFT 1.5 AT

Reg. Date : 12.12.2007

Chassis No : JSAEZC21S00407234

D.O.A : 12.01.2021

1	Bonnet <i>Revised</i>	1 pc		560.00	
2	Bonnet Lock <i>Free</i>	1 pc		115.00	+
3	Bonnet Rubber Seal <i>Free</i>	1 pc		45.00	+
4	Bonnet Insulator <i>new</i>	1 pc		83.00	+
5	Bonnet Stopper <i>new</i>	2 pc	12.00	24.00	+
6	Headlamp RH <i>Cracked</i>	1 pc		580.00	386.
7	Headlamp Bracket RH <i>new</i>	1 pc		45.50	+
8	Front Bumper <i>Revised</i>	1 pc		740.00	575
9	Front Bumper Side Retainer RH <i>cracked</i>	1 pc		33.20	-
10	Front Bumper Grille <i>cracked</i>	1 pc		95.00	-
11	Front Bumper Grille Logo <i>new</i>	1 pc		32.00	-
12	Front Bumper Lower Grille <i>cracked</i>	1 pc		83.30	-
13	Front Bumper Tow Cover <i>new</i>	1 pc		29.60	+
14	Front Bumper Fog Lamp RH <i>cracked</i>	1 pc		196.50	-
15	Front Bumper Fog Lamp Cover RH <i>Missing</i>	1 pc		35.00	-
16	Front Bumper Reinforcement Top <i>Best</i>	1 pc		240.00	-
17	Front Bumper Reinforcement Sponge Top <i>cracked</i>	1 pc		140.00	-
18	Front Bumper Reinforcement Bottom <i>Best</i>	1 pc		183.00	-
19	Front Bumper Reinforcement Sponge Bottom <i>cracked</i>	1 pc		105.00	-
20	Support Panel <i>Ryis</i>	1 pc		645.00	+
21	Support Panel Air Guide Duct <i>new</i>	1 pc		61.00	+
22	Front Fender RH <i>Revised</i>	1 pc		289.00	-

4,360.10

C/F

4,360.10



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883
Company GST Registration No : 201828067M

VEHICLE INSPECTION ESTIMATE

B/F

4,360.10

23	Front Fender Inner Cowling RH <i>torn</i>	1 pc		74.00	✓
24	Front Fender Signal Lamp <i>new</i>	1 pc		28.00	+
25	Front Fender "VVT" Emblem <i>new</i>	1 pc		18.00	✓
26	Front Windscreen Quarter Garish <i>new</i>	1 pc		61.00	+
27	Wiper Cowling RH <i>cut</i>	1 pc		136.00	✓
28	Wiper Cowling Cover RH <i>new</i>	1 pc		35.00	+
29	Wiper Cowling Rubber RH <i>new</i>	1 pc		45.00	+
33	Wiper Washer Tank <i>Rebuilt</i>	1 pc		99.00	✓
34	Wiper Washer Tank Motor <i>3M</i>	1 pc		147.00	+
35	Wiper Washer Tank Seal <i>new</i>	1 pc		12.00	+
30	Front Door RH <i>Repr</i>	1 pc		689.00	+
31	Front Door Hings RH <i>new</i>	2 pc	51.00	102.00	+
32	Front Door Checker RH <i>new</i>	1 pc		51.00	+
36	Front Shock Absorber RH <i>Bent</i>	1 pc		331.00	✓
37	Front Shock Absorber Top Mounting RH <i>new</i>	1 pc		68.00	✓
38	Front Lower Arm RH <i>Bent</i>	1 pc		336.00	✓
39	Front Knuckle Arm RH <i>Bent</i>	1 pc		325.00	✓
40	Front Wheel Bearing RH <i>Rebuilt</i>	1 pc		128.00	✓
41	Front Wheel Speed Sensor RH <i>new</i>	1 pc		180.00	+
42	Front Tie Rod RH <i>3M</i>	1 pc		96.00	+
43	Front Tie Rod End RH	1 pc		75.00	+
44	Front Rim RH <i>cut</i>	1 pc		488.00	✓
45	RH front wheel house <i>3M</i>	1 pc		867.50	+
46	RH front drive shaft	1 pc		465.30	+
47	RH front stabilizer link	1 pc		172.20	Bent 95.
48	Radiator assy <i>3M</i>	1 pc		530.40	+
49	Radiator Condenser <i>new</i>	1 pc		465.50	+
				7,884.10	
				Less 15%	1,182.62
					6,701.49

4983

4235.55



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883
Company GST Registration No : 201828067M

VEHICLE INSPECTION ESTIMATE

B/F

6,701.49

Special nett item

1	Front Bumper Clips <i>MC</i>	1 set		30.00	✓
2	Bonnet Insulator Clips <i>MC</i>	1 set		30.00	✓
3	RH Front Fender inner Cowling Clips <i>MC</i>	1 set		30.00	✓
4	Front Tyre RH 195/55R15 <i>Punctured</i>	1 pc		350.00	180

240

To Panel Beat/Straighten/Weld And Align All Parts	2,000.00	800
To Respray Accidents Affected Areas	2,000.00	800
To Remove/Refix Mechanical Items To Assist Repair Include Top Up AC Gas	200.00	120
To Check Wire, Wire Connetor And Rewire/Repair	120.00	30
To Check And Realign Headlamp	100.00	✓
To Remove/Replace RH Front Undercarriage	450.00	220
To Conduct Wheel Alignment	180.00	80
	12,191.49	

2050

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian

H/S 18/01/21

060 days.

total: 6525.55

*H/S: SK
(Nett Value).*