

ASS. REC. BY:

REF: C72/21000815/KV

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / X / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_ S Thru

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 5-6 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLX 2100M Yr Regn: 03, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Alphard Wagon c.c. 2494Colour M.P. White A/C: Insured / Std / NI / NASp. Reading 17267 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JNCF-301+808073901Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NII / S/Rlm / STD A/Rlm or

Tyre Size: F: \_\_\_\_\_

R: 235/50R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO YOKO or

Front

Rear

R/Bal. 8 mmR/Bal. 8 mmL/Bal. 8 mmL/Bal. 8 mmD.O.A. 15/1/21D.O.I. 21/1/2021

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation:

S - RS, SI

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Report Format :

Lump Sum / I.B.I: (\$ \_\_\_\_\_)



Not available  
 L1Pry @  
 Penny After Repair  
 5-6 days

TO :  
 ATTN : MOTOR CLAIM DEPT.

T/P VEH. NO. : SMG827R

ESTIMATE REF 1st QUOTATION

JOB NO. : \_\_\_\_\_

OWNER'S PARTICULAR

NAME : BENNY SUHERMAN

CONTACT : 96662288

ADDRESS :

LICENSE NO. : SLX2100M TRANS. :

CHASSIS NO. :

MAKE / MODEL TOYOTA ALPHARD

ENGINE NO. :

OWNER'S INSU AXA INSURANCE

JOB-COD/TP

S/A : JOEY

ACCIDENT DATE : 15-Jan-21

CLAIM DETAIL

MATERIALS

	QTY	QUO-PRICE	DISC. %	DISC- PRICE	SU R.	EV. PRIC
1 REAR BUMPER	Bq 1.00	1776.30	25.00	1332.23	Y	✓
2 REAR BUMPER SIDE RETAINER LH	D11 1.00	90.00	25.00	67.50	Y	✓
3 REAR BUMPER SIDE RETAINER RH	1m 1.00	90.00	25.00	67.50	Y	X
4 REAR BUMPER REINFORCEMENT	NSP 1.00	580.00	25.00	435.00	Y	X
5 REAR BUMPER BRACKET LH	1.00	101.00	25.00	75.75	Y	?
6 REAR BUMPER BRACKET RH	1.00	101.00	25.00	75.75	Y	X
7 REAR BUMPER SIDE GARNISH LH	Bu/1m 1.00	175.00	25.00	131.25	Y	✓
8 REAR BUMPER SIDE GARNISH RH	1m 1.00	175.00	25.00	131.25	Y	X
9 REAR BUMPER SIDE REFLECTOR LH	CM 1.00	99.00	25.00	74.25	Y	✓
10 REAR BUMPER SIDE REFLECTOR RH	1m 1.00	99.00	25.00	74.25	Y	X
11 REAR BUMPER TOP SIDE RETAINER LH	D11 1.00	100.00	25.00	75.00	Y	✓
12 REAR BUMPER TOP SIDE RETAINER RH	1m 1.00	100.00	25.00	75.00	Y	X
13 REAR BUMPER TOWING COVER	CM 1.00	60.00	25.00	45.00	Y	✓
14 SPARE TYRE HOLDER ASSY	1.00	276.40	25.00	207.30	Y	X
15 REAR END PANEL	1.00	868.90	25.00	651.68	Y	?
16 REAR END PANEL INNER GARNISH	1.00	498.90	25.00	374.18	Y	?
17 REAR END PANEL TOOL COVER	1m 1.00	330.00	25.00	247.50	Y	X
18 REAR END PANEL COVER	1m 1.00	430.00	25.00	322.50	Y	X
19 REAR END INNER PANEL	1.00	798.00	25.00	598.50	Y	?
20 REAR INNER SIDE GARNISH BOARD LH	1m 1.00	252.00	25.00	189.00	Y	X
21 TAILGATE RUBBER	1m 1.00	357.90	25.00	268.43	Y	X
22 TAILGATE	Bq 1.00	1956.40	25.00	1467.30	Y	✓
23 TAILGATE GLASS WITH MOULDING	1.00	2380.00	25.00	1785.00	Y	?
24 TAILGATE LAMP RH	1m 1.00	647.90	25.00	485.93	Y	X
25 TAILGATE LAMP LH	1m 1.00	647.90	25.00	485.93	Y	X
26 TAILGATE LAMP CHROME LOWER LH	1m 1.00	899.00	25.00	674.25	Y	X
27 TAILGATE LAMP CHROME LOWER RH	1m 1.00	899.00	25.00	674.25	Y	X
28 TAILGATE CHORME TOP	1m 1.00	655.90	25.00	491.93	Y	X
29 TAILGATE EMBLEM ALPHARD	1m 1.00	69.90	25.00	52.43	Y	✓
30 TAILGATE INNER TRIM BOARD	1m 1.00	898.90	25.00	674.18	Y	✓
31 TAILGATE LOGO	1m 1.00	74.60	25.00	55.95	Y	✓
32 TAILGATE INNER LOCK	R 1.00	768.90	25.00	576.68	Y	X
33 TAILGATE INNER LOCK CATCH	R 1.00	69.90	25.00	52.43	Y	X



34	TAILGATE STOPPER LH	1.00	30.00	25.00	22.50	Y	X
35	TAILGATE STOPPER RH	1.00	30.00	25.00	22.50	Y	X
36	TAILLAMP RH	1.00	634.90	25.00	476.18	Y	X
37	TAILLAMP LH	1.00	634.90	25.00	476.18	Y	?
38	TAILGATE DAMPER LH	1.00	320.00	25.00	240.00	Y	X
39	TAILGATE DAMPER RH	1.00	320.00	25.00	240.00	Y	X
40	REAR BUMPER LOWER COVER	1.00	633.54	25.00	475.16	Y	?
41	KEYLESS CONTROL	1.00	380.00	25.00	285.00	Y	X
42	TAILGATE SAFETY SENSOR	1.00	306.00	25.00	229.50	Y	?

TOTAL (PARTS):

20616.04

15462.03

SPECIAL NETT ITEM

1	REAR END PANEL SEALANT	1.00	50.00	0.00	50.00	Y	?
2	TAILGATE REVERSE CAMERA	1.00	80.00	0.00	80.00	Y	X
3	TAILGATE REVERSE SENSOR	1.00	1120.00	0.00	1120.00	Y	X
4	TAILGATE W/S SOLA FLIM	1.00	380.00	0.00	380.00	Y	?
5	TAILGATE INNER TRIM CLIPS	1.00	50.00	0.00	50.00	Y	✓
6	REAR BUMPER CLIPS	1.00	50.00	0.00	50.00	Y	✓
7	REVERSE CAMERA	1.00	680.00	0.00	680.00	Y	X
8	TAILGATE GLASS SEALANT	1.00	50.00	0.00	50.00	Y	4052
9	TAILGATE GLASS INNER SEAL	1.00	50.00	0.00	50.00	Y	3052
10	TAILGATE CLEANER & PRIMER	1.00	50.00	0.00	50.00	Y	X

TOTAL (PARTS):

2560.00

2560.00

LABOUR

1	STRAIGHTEN AND PANEL BEAT ACCIDENT AREA	1.00	1600.00	0.00	1600.00	Y	?
2	SPRAY PAINTING ON ACCIDENT AREA	1.00	1600.00	0.00	1600.00	Y	9001
3	REMOVE AND REFIT TAILGATE COMPARTMENT	1.00	180.00	0.00	180.00	Y	601
4	REMOVE AND REFIT REAR TAILGATE GLASS	1.00	180.00	0.00	180.00	Y	1201
5	REMOVE AND REFIT CARPET, SEAT & INNER TRIM TO ASSIST ACCIDENT REPAIR	1.00	180.00	0.00	180.00	Y	601
6	REMOVE AND REFIT REVERSE SENSOR & RESET SYST	1.00	180.00	0.00	180.00	Y	601
7	RESPRAY TUFF KOTE ON ACCIDENT AREA	1.00	200.00	0.00	200.00	Y	?
8	CHECK & REPAIR WIRING SYSTEM	1.00	80.00	0.00	80.00	Y	201
9	REMOVE & REFIT REVERSE CAMERA & CALIBRATION	1.00	280.00	0.00	280.00	Y	?

TOTAL (LABOUR):

4480.00

4480.00

TOTAL PARTS & LABOUR

27656.04

22502.03

EXCESS : : S\$

NO. OF D.:

RE-SURVEY : BEFORE / AFTER PAINTING

PART BY PART OR LUMP-SUM : S\$

DATE OF SURV: 21 / 1 / 21

SURVEY : Kenneth

CONTACT : 96910663

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FAX NO



# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission ..... 20/01/2021 11:45 (SGT)  
Date of Accident ..... 15/01/2021 08:45 (SGT)  
Exact Location of Accident ..... 100 North Buona Vista Rd, Buona Vista, Singapore 139349  
Additional Location Information ..... -  
Country/State of Loss ..... Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SLX2100M

### INSURED/POLICYHOLDER

Is company? ..... No  
Name Of Registered Owner ..... BENNY SUHERMAN  
NRIC No ..... SXXXX554D  
Email Address ..... BENNY@GMAIL.COM  
Mobile Phone No ..... (Phone) +65-96662288  
Alternative Phone No ..... +65-96662288

### VEHICLE PARTICULARS

Manufacturer ..... Toyota  
Model ..... Alphard  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... Private use  
Are you claiming under your own insurance policy for repair to your vehicle? ..... No - Claiming third party  
Vehicle Category ..... Private car

### INSURANCE COMPANY

Name of Insurance Company ..... Axa  
Type of Coverage ..... Comprehensive  
Fleet Policy ..... No  
Policy Number ..... -  
Cover Note Number ..... -

### DRIVER

Name of Driver ..... SYAFUL HASAN  
Passport No/FIN ..... BXXX0871  
Date Of Birth ..... 15/01/1991  
Occupation ..... Indoor



Date Of Driving Pass	02/01/2018
Driving experience	3 YEARS
Gender	Male
Mobile Number	(Phone) +65-96662288
Alt. Phone Number	-
Email Address	SYAIFUL@GMAIL.COM
Address	28 LI HWAN TERRACE SINGAPORE
Address complement	-
Postcode	556956
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Friend
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### PASSENGER 1

Name	HANS GUNDAI
Gender	Male

#### PASSENGER 2

Name	OILVER GUNADI
Gender	Male

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

SEE ATTACH SKETCH PLAN & STATEMENT

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No


#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMG827R
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-



**SKETCH PLAN**

AGE towards TUGS



**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

While driving straight along AGE towards MAS, vehicles in front of me suddenly jammed brake, I brake immediately and did not hit onto the front car. Suddenly vehicle B came from behind and hit the rear portion of my vehicle.

**DECLARATION**

(We declare the foregoing particulars are true in every respect.)

*Robert Joseph*  
 Policyholder's Signature  
 Date & Time

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time

Reporting Centre Personnel's Signature  
 Name:  
 SMC No.: