



Precision touchpad

Faster wireless

4020

S THREE AUTOMOTIVE RECOVERY PTE LTD  
 Blk 8 Sin Ming Industrial Estate  
 #01-64/66 Singapore 575643  
 Tel : 6284 1542 / 6284 1575  
 Fax : 6467 5315  
 sthreeautomotive@gmail.com

Not At Hand  
 L1 Pay @ 5500ph  
 Running After Paint  
 6 days

TO :  
 ATT: MOTOR CLAIM DEPT.

T/P VEH. NO.: SMG827R

ESTIMATE REF 1st QUOTATION

JOB NO: \_\_\_\_\_

OWNER'S PARTICULAR

NAME: BENNY SUHERMAN

CONTACT: 96662288

ADDRESS:

LICENSE NO.: SLX2100M TRANS.:

CHASSIS NO.:

MAKE / MODEL: TOYOTA ALPHARD

ENGINE NO.:

OWNER'S INSU AXA INSURANCE

JOB-COD: TP

S/A: JOEY

ACCIDENT DATE: 15-Jan-21

## CLAIM DETAIL

## MATERIALS

|    |                                  | QTY                  | QUO-PRICE | DISC. % | DISC-PRICE | SU R. | EV. PRIC |
|----|----------------------------------|----------------------|-----------|---------|------------|-------|----------|
| 1  | REAR BUMPER 845-10               | B <sub>g</sub> 1.00  | 1776.30   | 25.00   | 1332.23    | Y     | ✓        |
| 2  | REAR BUMPER SIDE RETAINER LH     | D <sub>11</sub> 1.00 | 90.00     | 25.00   | 67.50      | Y     | ✓        |
| 3  | REAR BUMPER SIDE RETAINER RH     | L <sub>m</sub> 1.00  | 90.00     | 25.00   | 67.50      | Y     | X        |
| 4  | REAR BUMPER REINFORCEMENT        | N <sub>SP</sub> 1.00 | 580.00    | 25.00   | 435.00     | Y     | X        |
| 5  | REAR BUMPER BRACKET LH           | R 1.00               | 101.00    | 25.00   | 75.75      | Y     | X        |
| 6  | REAR BUMPER BRACKET RH           | R 1.00               | 101.00    | 25.00   | 75.75      | Y     | X        |
| 7  | REAR BUMPER SIDE GARNISH LH      | B <sub>u</sub> 1.00  | 175.00    | 25.00   | 131.25     | Y     | ✓        |
| 8  | REAR BUMPER SIDE GARNISH RH      | L <sub>m</sub> 1.00  | 175.00    | 25.00   | 131.25     | Y     | X        |
| 9  | REAR BUMPER SIDE REFLECTOR LH    | C <sub>M</sub> 1.00  | 99.00     | 25.00   | 74.25      | Y     | ✓        |
| 10 | REAR BUMPER SIDE REFLECTOR RH    | L <sub>m</sub> 1.00  | 99.00     | 25.00   | 74.25      | Y     | X        |
| 11 | REAR BUMPER TOP SIDE RETAINER LH | D <sub>11</sub> 1.00 | 100.00    | 25.00   | 75.00      | Y     | ✓        |
| 12 | REAR BUMPER TOP SIDE RETAINER RH | L <sub>m</sub> 1.00  | 100.00    | 25.00   | 75.00      | Y     | X        |
| 13 | REAR BUMPER TOWING COVER         | C <sub>M</sub> 1.00  | 60.00     | 25.00   | 45.00      | Y     | ✓        |
| 14 | SPARE TYRE HOLDER ASSY           | R 1.00               | 276.40    | 25.00   | 207.30     | Y     | X        |
| 15 | REAR END PANEL 798               | R <sub>g</sub> 1.00  | 868.90    | 25.00   | 651.68     | Y     | X        |
| 16 | REAR END PANEL INNER GARNISH     | L <sub>m</sub> 1.00  | 498.90    | 25.00   | 374.18     | Y     | X        |
| 17 | REAR END PANEL TOOL COVER        | L <sub>m</sub> 1.00  | 330.00    | 25.00   | 247.50     | Y     | X        |
| 18 | REAR END PANEL COVER             | L <sub>m</sub> 1.00  | 430.00    | 25.00   | 322.50     | Y     | X        |
| 19 | REAR END INNER PANEL             | R 1.00               | 798.00    | 25.00   | 598.50     | Y     | X        |
| 20 | REAR INNER SIDE GARNISH BOARD LH | L <sub>m</sub> 1.00  | 252.00    | 25.00   | 189.00     | Y     | X        |
| 21 | TAILGATE RUBBER                  | L <sub>m</sub> 1.00  | 357.90    | 25.00   | 268.43     | Y     | X        |
| 22 | TAILGATE 1806-23                 | R <sub>g</sub> 1.00  | 1956.40   | 25.00   | 1467.30    | Y     | ✓        |
| 23 | TAILGATE GLASS WITH MOULDING     | L <sub>m</sub> 1.00  | 2380.00   | 25.00   | 1785.00    | Y     | X        |
| 24 | TAILGATE LAMP RH                 | L <sub>m</sub> 1.00  | 647.90    | 25.00   | 485.93     | Y     | X        |
| 25 | TAILGATE LAMP LH                 | L <sub>m</sub> 1.00  | 647.90    | 25.00   | 485.93     | Y     | X        |
| 26 | TAILGATE LAMP CHROME LOWER LH    | L <sub>m</sub> 1.00  | 899.00    | 25.00   | 674.25     | Y     | X        |
| 27 | TAILGATE LAMP CHROME LOWER RH    | L <sub>m</sub> 1.00  | 899.00    | 25.00   | 674.25     | Y     | X        |
| 28 | TAILGATE CHORME TOP              | L <sub>m</sub> 1.00  | 655.90    | 25.00   | 491.93     | Y     | X        |
| 29 | TAILGATE EMBLEM ALPHARD          | L <sub>m</sub> 1.00  | 69.90     | 25.00   | 52.43      | Y     | ✓        |
| 30 | TAILGATE INNER TRIM BOARD 708    | L <sub>m</sub> 1.00  | 898.90    | 25.00   | 674.18     | Y     | ✓        |
| 31 | TAILGATE LOGO                    | L <sub>m</sub> 1.00  | 74.60     | 25.00   | 55.95      | Y     | ✓        |
| 32 | TAILGATE INNER LOCK              | R 1.00               | 768.90    | 25.00   | 576.68     | Y     | X        |
| 33 | TAILGATE INNER LOCK CATCH        | R 1.00               | 69.90     | 25.00   | 52.43      | Y     | X        |

|    |                         |               |      |        |        |        |        |   |   |
|----|-------------------------|---------------|------|--------|--------|--------|--------|---|---|
| 34 | TAILGATE STOPPER LH     | sm            | 1.00 | 30.00  | 25.00  | 22.50  | Y      | X |   |
| 35 | TAILGATE STOPPER RH     | sm            | 1.00 | 30.00  | 25.00  | 22.50  | Y      | X |   |
| 36 | TAILLAMP RH             | sm            | 1.00 | 634.90 | 25.00  | 476.18 | Y      | X |   |
| 37 | TAILLAMP LH             | mycm          | 1.00 | 634.90 | 25.00  | 476.18 | Y      | 2 |   |
| 38 | TAILGATE DAMPER LH      | sm            | 1.00 | 320.00 | 25.00  | 240.00 | Y      | X |   |
| 39 | TAILGATE DAMPER RH      | sm            | 1.00 | 320.00 | 25.00  | 240.00 | Y      | X |   |
| 40 | REAR BUMPER LOWER COVER | P-? 288.20 cm | 1.00 | 633.54 | 25.00  | 475.16 | Y      | 2 |   |
| 41 | KEYLESS CONTROL         | sm            | 1.00 | 380.00 | 25.00  | 285.00 | Y      | X |   |
| 42 | TAILGATE SAFETY SENSOR  | 262.60        | 0cl  | 1.00   | 306.00 | 25.00  | 229.50 | Y | 2 |

TOTAL (PARTS):

20616.04

15462.03

SPECIAL NETT ITEM

|    |                           |    |      |         |      |         |   |      |
|----|---------------------------|----|------|---------|------|---------|---|------|
| 1  | REAR END PANEL SEALANT    | sm | 1.00 | 50.00   | 0.00 | 50.00   | Y | 30sm |
| 2  | TAILGATE REVERSE CAMERA   | sm | 1.00 | 80.00   | 0.00 | 80.00   | Y | X    |
| 3  | TAILGATE REVERSE SENSOR   | sm | 1.00 | 1120.00 | 0.00 | 1120.00 | Y | X    |
| 4  | TAILGATE W/S SOLA FLIM    | sm | 1.00 | 380.00  | 0.00 | 380.00  | Y | X    |
| 5  | TAILGATE INNER TRIM CLIPS | sm | 1.00 | 50.00   | 0.00 | 50.00   | Y | —    |
| 6  | REAR BUMPER CLIPS         | sm | 1.00 | 50.00   | 0.00 | 50.00   | Y | —    |
| 7  | REVERSE CAMERA            | sm | 1.00 | 680.00  | 0.00 | 680.00  | Y | X    |
| 8  | TAILGATE GLASS SEALANT    | sm | 1.00 | 50.00   | 0.00 | 50.00   | Y | 40sm |
| 9  | TAILGATE GLASS INNER SEAL | sm | 1.00 | 50.00   | 0.00 | 50.00   | Y | 30sm |
| 10 | TAILGATE CLEANER & PRIMER | sm | 1.00 | 50.00   | 0.00 | 50.00   | Y | X    |

TOTAL (PARTS):

2560.00

2560.00

LABOUR

|   |                                              |      |         |      |         |   |       |
|---|----------------------------------------------|------|---------|------|---------|---|-------|
| 1 | STRAIGHTEN AND PANEL BEAT ACCIDENT AREA      | 1.00 | 1600.00 | 0.00 | 1600.00 | Y | 80cl  |
| 2 | SPRAY PAINTING ON ACCIDENT AREA              | 1.00 | 1600.00 | 0.00 | 1600.00 | Y | 100cl |
| 3 | REMOVE AND REFIT TAILGATE COMPARTMENT        | 1.00 | 180.00  | 0.00 | 180.00  | Y | 6cl   |
| 4 | REMOVE AND REFIT REAR TAILGATE GLASS         | 1.00 | 180.00  | 0.00 | 180.00  | Y | 12cl  |
| 5 | REMOVE AND REFIT CARPET, SEAT & INNER TRIM   | 1.00 | 180.00  | 0.00 | 180.00  | Y | 6cl   |
|   | TO ASSIST ACCIDENT REPAIR                    |      |         |      |         |   |       |
| 6 | REMOVE AND REFIT REVERSE SENSOR & RESET SYST | 1.00 | 180.00  | 0.00 | 180.00  | Y | 6cl   |
| 7 | RESPRAY TUFF KOTE ON ACCIDENT AREA           | 1.00 | 200.00  | 0.00 | 200.00  | Y | 8cl   |
| 8 | CHECK & REPAIR WIRING SYSTEM                 | 1.00 | 80.00   | 0.00 | 80.00   | Y | 2cl   |
| 9 | REMOVE & REFIT REVERSE CAMERA & CALIBRATION  | 1.00 | 280.00  | 0.00 | 280.00  | Y | X     |

TOTAL (LABOUR):

4480.00

4480.00

TOTAL PARTS & LABOUR

27656.04

22502.03

EXCESS : : \$

NO. OF D.:

RE-SURVEY : BEFORE / AFTER PAINTING

PART BY PART OR LUMP-SUM : \$

DATE OF SURV: 21 / 1 / 21

SURVEY : Kenneth

CONTACT : 96910663

FAX NO :

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.