

ASS. BY:

REF:

CC4/AIG 21000832/Dgs³

ASSIGNMENT

COE July 2025

From:

Date:

Estimated Cost:

OD / TPWS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No

Claims No

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark The veh had commenced its
repair at the time of inspection.



Bal. of Market Value:

IDAC Accident Report

Consistent? : Yes or No

GIA / PR Seant

Consistent? : Yes or No

Est. Repairs:

6

days

Res.:

Yes or No

Lump Sum:

10

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 3933Y

Yr Regn:

2017, July

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

c.c. 1798

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

510382

T/Radio: Insured / Std / NI / NA

Eng/No:

2ZR3054352

C/No:

JTDKBB3FU303560642

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65 R15

R:

— 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Duraturn

Front

Rear

R/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

08/01/2021

D.O.L.

18/01/2021

Survey held at

Bijoy's Sin Ming

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action/Instruction

AIG SNA 6469 H

Repairer change all parts with new parts. To apply 4S at 10%

24/08/21 from 21S 13,900/- into 6 days of work

Date/Time, File Pass to?



Prel. Report

1)



Final Report

Date/Time, File Return to?

2)

Repair Format:

Lump Sum / B.B. (%)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Week-end (\$

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

TOTAL

REPAIR ESTIMATE

INSURANCE: ALG

VEHICLE NO.: SHD 3933 Y

DESCRIPTION	QTY	LIST PRICE	AMOUNT
BONNET <i>st / Dent</i>	1	\$950.50	\$950.50
INSULATOR, HOOD <i>HH</i>	1	\$398.10	\$398.10
INSULATOR CLIPS 10 PCS <i>HH</i>	1	\$36.80	\$36.80
BONNET RUBBER <i>HH</i>	1	\$35.50	\$35.50
BONNET CABLE <i>HH</i>	1	\$83.20	\$83.20
BONNET HINGE (RH) <i>st</i>	1	\$87.70	\$87.70
BONNET HINGE (LH) <i>st</i>	1	\$87.70	\$87.70
BONNET LOCK <i>st</i>	1	\$132.60	\$132.60
RADIATOR GRILLE <i>broken</i>	1	\$438.00	\$438.00
RADIATOR GRILLE EMBLEM <i>broken / dislodged</i>	1	\$88.00	\$88.00
FRONT BUMPER COVER <i>turn</i>	1	\$499.90	\$499.90
FRONT BUMPER REINFORCEMENT <i>Dent / st</i>	1	\$696.40	\$696.40
FRONT BUMPER REINFORCEMENT ABSORBER <i>damaged / cut</i>	1	\$115.70	\$115.70
FRONT BUMPER LOWER REINFORCEMENT <i>st</i>	1	\$364.20	\$364.20
FRONT BUMPER LOWER REINFORCEMENT BRACKET <i>W/S Dent</i>	1	\$330.00	\$330.00
FRONT SIDE MEMBER REINFORCEMENT PANEL (LH/RH) <i>HH 2</i>	2	\$ 320.70	\$641.40
FRONT SIDE MEMBER SIDE COVER <i>HH</i>	1	\$ 172.50	\$172.50
FRONT BUMPER SPONGE <i>turn</i>	1	\$78.80	\$78.80
FRONT BUMPER LOWER GRILLE <i>damaged</i>	1	\$166.90	\$166.90
LAMP ASSY, FOG, RH <i>cut / mostly broken</i>	1	\$920.00	\$920.00
LAMP ASSY, FOG, LH <i>dislodged / broken</i>	1	\$920.00	\$920.00
FRONT BUMPER SIDE RETAINER <i>HH</i>	1	\$77.00	\$77.00
FRONT LOWER PANEL <i>2 st</i>	1	\$320.65	\$320.65
FRONT LOWER SIDE RAIL (LH/RH) <i>HH</i>	1	\$230.80	\$230.80
FRONT LOWER CROSSMEMBER <i>HH</i>	1	\$357.70	\$357.70
FRONT BUMPER TOP GARNISH <i>HH</i>	1	\$225.40	\$225.40
COVER, FRONT BUMPER HOLE, RH <i>dislodged</i>	1	\$28.38	\$28.38
COVER, FRONT BUMPER HOLE, LH <i>cut / dislodged</i>	1	\$28.38	\$28.38
ABSORBER, FRONT BUMPER, LOWER <i>HH</i>	1	\$127.70	\$127.70
UNIT ASSY, HEADLAMP, RH (LED) <i>mostly broken</i>	1	\$3,455.00	\$3,455.00
UNIT ASSY, HEADLAMP, LH (LED) <i>broken</i>	1	\$3,455.00	\$3,455.00
HEADLAMP ECU <i>HH</i>	1	\$682.60	\$682.60
HEAD LAMP PANEL (RH) <i>2 st</i>	1	\$240.10	\$240.10
HEAD LAMP PANEL (LH) <i>2 st</i>	1	\$240.10	\$240.10
TOP PANEL CENTRE <i>Dent / st.</i>	1	\$364.98	\$364.98
TOP PANEL SIDE <i>2 st o/s</i>	1	\$145.90	\$145.90
BRACE PANEL <i>st</i>	1	\$75.20	\$75.20
RADIATOR ASSY <i>2 st</i>	1	\$1,841.80	\$1,841.80
RADIATOR FAN GRILLE <i>HH</i>	1	\$632.40	\$632.40
GUIDE RADIATOR AIR NO.3 <i>HH</i>	1	\$299.70	\$299.70
COOLANT <i>HH</i>	1	\$45.00	\$45.00

[illegible]

DEFLECTOR, RADIATOR SIDE, RH <i>SVL</i>	1	\$83.50	\$83.50	X
DEFLECTOR, RADIATOR SIDE, LH <i>SVL</i>	1	\$83.50	\$83.50	X
RADIATOR SPARE TANK HYBRID <i>HH</i>	1	\$225.80	\$225.80	X
RADIATOR BOTTOM MOUNTING <i>HH</i>	1	\$27.50	\$27.50	X
STAY, RADIATOR SUPPORT, RH <i>HH</i>	1	\$65.70	\$65.70	X
STAY, RADIATOR SUPPORT, LH <i>HH</i>	1	\$65.70	\$65.70	X
RADIATOR FAN BLADE (RH) <i>HH</i>	1	\$233.10	\$233.10	X
RADIATOR FAN BLADE (LH) <i>HH</i>	1	\$233.10	\$233.10	X
RADIATOR FAN MOTOR (RH) <i>HH</i>	1	\$543.70	\$543.70	X
RADIATOR FAN MOTOR (LH) <i>HH</i>	1	\$543.70	\$543.70	X
RADIATOR FAN COWLING (LH/RH) <i>HH</i>	2	\$451.30	\$902.60	X
HORN (1 PC) <i>SVL</i>	1	\$112.71	\$112.71	X
CONDENSER ASSY, W/RECEIVER <i>Z 44</i>	1	\$1,336.60	\$1,336.60	X
FENDER SUB-ASSY, FRONT RH <i>rep</i>	1	\$945.30	\$945.30	X
FENDER SUB-ASSY, FRONT LH <i>Decker</i>	1	\$945.30	\$945.30	X
FRONT FENDER SHIELD CLIP <i>HH</i>	1	\$14.90	\$14.90	X
FRONT FENDER HYBRID EMBLEM, LH <i>HH</i>	1	\$86.50	\$86.50	X
FRONT FENDER HYBRID EMBLEM, RH <i>SVL</i>	1	\$86.50	\$86.50	X
BRACKET, FRONT SIDE PANEL, RH <i>HH</i>	1	\$86.30	\$86.30	X
BRACKET, FRONT SIDE PANEL, LH <i>HH</i>	1	\$86.30	\$86.30	X

SUB TOTAL

\$26,826.00

LESS 20% *25%*

\$5,365.20

DISCOUNTED TOTAL

\$21,460.80

FRONT NO. PLATE <i>deleted</i>	SN	1	\$25.00	\$25.00	
FRONT NO. PLATE TRIM COVER <i>deleted</i>	SN	1	\$30.00	\$30.00	
FRONT NO. PLATE GARNISH <i>broken</i>	SN	1	\$99.00	\$99.00	
FRONT BUMPER LOGO <i>HH</i>	SN	1	\$87.10	\$87.10	

SUB TOTAL

\$241.10

Labour Charge

Panel Beating	1	\$1,600.00	\$1,600.00	
Spray Painting Charge	1	\$1,400.00	\$1,400.00	
Wiring Charge	1	\$180.00	\$180.00	
Tuff Kote	1	\$160.00	\$160.00	
Towing Charge	1	\$80.00	\$80.00	
Remove/Refix Radiator	1	\$90.00	\$90.00	
Remove/Refix Aircon & Refill Gas	1	\$130.00	\$130.00	
Remove/Refix Fuse Box	1	\$120.00	\$120.00	

TOTAL LABOUR

LKK Auto Consultants hence notify the Repairer of ~~\$3,760.00~~

ESTIMATE TOTAL

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to approval from Insurance Company

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantity will be resurveyed and prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

18/01/2021 @ 17:00hrs 6 days
 H.A. Antoni LKK Auto
 L.H. P. R. J. R.

Acknowledged by Repairer
 Signature:
 Date:

16805.49

12604.11

451

14400

9001-

8001-

301-

401-

501-

801-

HH

HH

HH

HH

HH

HH

HH

HH

HH

HH

HH

HH

HH

BIFROST AUTO PTE LTD

Supplementary ESTIMATE

DATE: 20-Jan-21

MODEL: TOYOTA PRIUS

INSURANCE: AIG

VEHICLE NO.: SHD 3933Y (S)

DESCRIPTION	QTY	LIST PRICE	AMOUNT
TOP PANEL SIDE (LH) <i>kt</i>	1	\$145.90	\$145.90
FRONT FENDER SHIELD (LH) <i>km</i>	1	\$198.50	\$198.50
ENGINE UNDER COVER <i>destroyed</i>	1	\$457.20	\$457.20
ENGINE UNDER COVER FRONT <i>km</i>	1	\$288.30	\$288.30
SUB TOTAL			\$1,089.90
LESS 20% <i>25%</i>			\$217.98
DISCOUNTED TOTAL			\$871.82
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

817.42

Wan

2Kk Ando

8

14648.11

Supp 817.42

15465.53

45 13,900/-

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	821R
Vehicle Details	
Vehicle No.:	SHD3933Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	18 Jan 2021
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	2ZR5054352
Chassis No.:	JTDKB3FU303560642
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	19 Jul 2017
First Registration Date:	19 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Jul 2025
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	18 Jul 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$38,560.00
COE Rebate Amount:	\$21,690.00
Total Rebate Amount:	\$25,440.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 18 Jan 2021

OK