



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIG Insured's Veh No : GBG3073J
Date of Accident : 15 January 2021

not Accid
nr
h/s # 8400
Take photo of the car
6 days
18/1/21
Take photo of the car

Messrs BIS Motoring Pte Ltd

Date : 15 January 2021

Estimate To Repair SLV3374T - KIA CARENS 1.7 DCT DIESEL 5DR FWD
Chassis No : KNAHU815VJ7193716

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	front bumper <i>Dis</i>	\$ 627.00
02	10 ps <i>14</i>	front bumper clips @ \$5.50 <i>nr</i>	\$ 55.00
03	1 pc	front bumper side retainer n/s <i>MAX</i>	\$ 11.00
04	1 pc	n/s headlamp <i>SCR</i>	\$ 1,558.00
05	1 pc	n/s headlamp bracket <i>11X</i>	\$ 45.00
06	1 pc	n/s front fender <i>Body</i>	\$ 384.00
07	1 pc	n/s front fender inner cowling <i>Top</i>	\$ 67.00
08	10 ps <i>14</i>	n/s front fender inner cowling clips @ \$5.50 <i>nr</i>	\$ 44.00
09	1 pc	n/s front fender wind deflector <i>MAX</i>	\$ 65.00
10	1 pc	n/s front door <i>Body</i>	\$ 1,098.00
11	1 pc	n/s front door outer chrome moulding <i>SCR</i>	\$ 43.00
12	1 pc	n/s front door outer handle <i>SCR</i>	\$ 176.00
13	1 pc	n/s front door outer handle extension <i>MAX</i>	\$ 24.00
14	1 pc	n/s front door outer auto key lock <i>11X</i>	\$ 358.00
15	1 pc	n/s front door outer key lock button <i>SCR</i>	\$ 55.00
16	1 pc	n/s front door lock with actuator <i>JM/hold</i>	\$ 239.00
17	1 pc	n/s front door hinge - top <i>TM</i>	\$ 30.00
18	1 pc	n/s front door hinge - bottom <i>TM</i>	\$ 30.00
19	1 pc	n/s front door checker <i>TM</i>	\$ 45.00
20	1 pc	n/s front door power window motor assy with base <i>shorted</i>	\$ 280.00
21	1 pc	n/s front door regulator <i>JM</i>	\$ 210.00
22	1 pc	n/s front door inner trimboard <i>MAX</i>	\$ 875.00
23	1 pc	n/s front door front pillar <i>R</i>	\$ 1,788.00
24	1 pc	n/s front door weatherstrip <i>TM/nc</i>	\$ 95.00
25	1 pc	n/s front door frame sticker - top <i>nr</i>	\$ 11.00
26	1 pc	n/s front door frame sticker - bottom <i>nr</i>	\$ 12.00
27	1 pc	n/s side mirror assy <i>nr</i>	\$ 589.00
28	1 pc	n/s rear door <i>Body/nc</i>	\$ 978.00
29	1 pc	n/s rear door outer chrome moulding <i>11X</i>	\$ 53.00
30	1 pc	n/s rear door lock <i>11X</i>	\$ 207.00
31	1 pc	n/s rear door hinge - top <i>11X</i>	\$ 30.00
32	1 pc	n/s rear door hinge - lower <i>11X</i>	\$ 30.00
33	1 pc	n/s rear door checker <i>11X</i>	\$ 34.00
34	1 pc	n/s rocker panel <i>2X</i>	\$ 1,729.00
35	1 pc	n/s rear fender <i>Body</i>	\$ 1,349.00
36	1 pc	n/s rear fender inner cowling <i>11X</i>	\$ 202.00
37	8 ps	n/s rear fender inner cowling clips @ \$5.50 <i>11X</i>	\$ 44.00
38	1 pc	rear bumper <i>2X</i>	\$ 452.00
39	1 pc	n/s front lower arm <i>Body</i>	\$ 387.00

7975 8362



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIG Insured's Veh No : GBG3073J
Date of Accident : 15 January 2021

Messrs BIS Motoring Pte Ltd

Date : 15 January 2021

Estimate To Repair SLV3374T - KIA CARENS 1.7 DCT DIESEL 5DR FWD
Chassis No : KNAHU815VJ7193716

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
40	1 pc	n/s front shock absorber <i>nn X</i>	\$ 302.00 <i>X</i>
41	1 pc	n/s front knuckle arm <i>But</i>	\$ 311.00 <i>—</i>
42	1 pc	n/s front wheel bearing <i>nee</i>	\$ 214.00 <i>—</i>
43	1 pc	n/s A pillar <i>R</i>	\$ 1,786.00 <i>X</i>
44	1 pc	front windscreen glass moulding <i>nn</i>	\$ 82.00 <i>X</i>
			\$ 17,005.00
		Less 10 % <i>8887</i>	\$ 1,700.50 <i>8800</i>
			\$ 15,304.50
<u>SPECIAL NETT ITEMS</u>			
45	1 pc	n/s front 1/4 glass seal <i>nn X</i>	\$ 80.00 <i>X</i>
46	1 pc	n/s front 1/4 glass sealant <i>nn X</i>	\$ 40.00 <i>X</i>
47	1 pc	n/s rear 1/4 glass seal <i>nn /</i>	\$ 50.00 <i>20</i>
48	1 pc	n/s rear 1/4 glass sealant <i>nn /</i>	\$ 40.00 <i>✓</i>
49	1 pc	front windscreen glass sealant <i>nn X</i>	\$ 60.00 <i>X</i>
50	1 pc	front windscreen glass inner sponge seal <i>nn X</i>	\$ 40.00 <i>X</i>
51	1 pc	rear windscreen glass sealant <i>nn X</i>	\$ 60.00 <i>X</i>
			\$ 370.00
<u>LABOUR & MISC. CHARGES</u>			
01		To rust-proofing of the affected areas.	\$ 350.00 <i>90</i>
02		To drop front suspension undercarriage parts, remove and renewal of the necessary parts, to perform final checking and testing.	\$ 200.00 <i>20</i>
03		To remove and refit front windscreen glass.	\$ <i>11</i> 120.00 <i>X</i>
04		To remove and refit left front fender quarter glass.	\$ 100.00 <i>60</i>
05		To transfer of left both door fittings and perform water seepage test.	\$ 240.00 <i>120</i>
06		To remove and refit left rear fender quarter glass.	\$ <i>11</i> 120.00 <i>X</i>
07		To check electrical lighting concerned.	\$ 150.00 <i>20</i>
08		To check central locking function.	\$ <i>11</i> 140.00 <i>X</i>
09		To renew both door frame sticker	\$ <i>11</i> 100.00 <i>X</i>
10		To upholstery and make good repair to cushion seat and seat frame and reclining mechanism.	\$ 120.00 <i>80</i>
11		To dismantle and refit rear seat, backrest, trimming, garnish, roof-lining, speaker shelfboard, carpeting and other to enable body work repair.	\$ 150.00 <i>80</i>
12		To dismantle and refit instrument dashboard, check electrical lightings and re-run, re-route wire harness.	\$ <i>11</i> 250.00 <i>X</i>
13		To transfer of tyre, rim and on wheel balancing.	\$ <i>11</i> 30.00 <i>X</i>
14		To check steering geometry and computer wheel alignment.	\$ 100.00 <i>80</i>
15		Using onboard scan tool (OBD) perform full engine diagnostic check, to configure and clear, reset SRS service light.	\$ <i>11</i> 250.00 <i>X</i>



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
 Tel : 68585151 (24 Hours) Fax : 68580877
 GST Regn. No. : M2-8922054-2

AIG Insured's Veh No : GBG3073J
 Date of Accident : 15 January 2021

Messrs BIS Motoring Pte Ltd

Date : 15 January 2021

Estimate To Repair SLV3374T - KIA CARENS 1.7 DCT DIESEL 5DR FWD
 Chassis No : KNAHU815VJ7193716

S/No	Quantity	Description	Amount
		LABOUR & MISC. CHARGES	
16		To remove and refit rear windscreen glass.	\$ 11 120.00
17		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,600.00
18		Putty and spray painting of the affected portion.	\$ 1,200.00
			\$ 5,340.00
		Total	\$ 21,014.50

X
 900
 1000

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

10 028
 FY22

CITY AUTO PTE LTD

BLK 8 SIN MING IND. EST., #01-58/60/62
SINGAPORE 575643



Phone Number: 6453-1235

Fax Number: 6453-7944

Customer: TAN LIM	Date: 1/18/2021 11:00 AM
Company:	VIN
License NO: SLV 3374T	Technician:
Odometer:	Order NO:

VEHICLE ALIGNMENT REPORT

KIA, CARENS, 06-06 (Customized)

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	4°24'	4°14'	5°14'	4°24'
		Right	4°23'	4°14'	5°14'	4°24'
	Camber	Left	-1°42'	-1°00'	0°00'	-1°36'
		Right	-0°42'	-1°00'	0°00'	-0°42'
	Toe	Left	0°09'	-0°09'	0°09'	-0°18'
		Right	0°06'	-0°09'	0°09'	0°33'
Total		0°15'	-0°18'	0°18'	0°15'	
Rear	Camber	Left	-1°18'	-1°30'	-0°30'	-1°12'
		Right	-1°30'	-1°30'	-0°30'	-1°30'
	Toe	Left	0°09'	0°00'	0°18'	0°09'
		Right	0°06'	0°00'	0°18'	0°06'
		Total	0°15'	0°00'	0°36'	0°15'
	Thrust Angle			0°02'	----	0°02'

Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		14°36'	12°36'	13°36'	14°36'
	Right		14°37'	12°36'	13°36'	14°37'
Included Angle	Left		12°54'	----	----	13°00'
	Right		13°55'	----	----	13°55'
Toe Out On Turns	Left		----	----	----	----
	Right		----	----	----	----
Max Turn Inside	Left		----	----	----	----
	Right		----	----	----	----
Toe Curve Change	Left		----	----	----	----
	Right		----	----	----	----
Setback	Front		5mm	----	----	5mm
	Rear		-1mm	----	----	-1mm
Track Width Diff.			-0mm			-0mm
Wheel Base Diff.			6mm			6mm
Front Ride Height	Left		----	----	----	----
	Right		----	----	----	----
Rear Ride Height	Left		----	----	----	----
	Right		----	----	----	----
Frame Angle						----

ONE STOP AUTOMOTIVE SOLUTION

Thank You For Your Business !

CITY AUTO PTE LTD

BLK 8 SIN MING IND. EST., #01-58/60/62
SINGAPORE 575643

2

Phone Number: 6453-1235
Fax Number: 6453-7944

Customer: TAN LIM	Date: <u>1/20/2021 2:22 PM</u>
Company:	VIN
License NO: SLV 3374T	Technician:
Odometer:	Order NO:

VEHICLE ALIGNMENT REPORT

KIA, CARENS, 06-06 (Customized)

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	4°21'	4°14'	5°14'	4°24'
		Right	4°21'	4°14'	5°14'	4°24'
	Camber	Left	-0°18'	-1°00'	0°00'	-0°18'
		Right	-0°54'	-1°00'	0°00'	-0°36'
	Toe	Left	-0°09'	-0°09'	0°09'	0°03'
		Right	0°00'	-0°09'	0°09'	0°03'
Total		-0°09'	-0°18'	0°18'	0°06'	
Rear	Camber	Left	-1°18'	-1°30'	-0°30'	-1°12'
		Right	-1°36'	-1°30'	-0°30'	-1°36'
	Toe	Left	0°09'	0°00'	0°18'	0°09'
		Right	0°09'	0°00'	0°18'	0°09'
		Total	0°18'	0°00'	0°36'	0°18'
	Thrust Angle			0°00'	----	
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		14°27'	12°36'	13°36'	14°27'
	Right		14°47'	12°36'	13°36'	14°47'
Included Angle	Left		14°09'	----	----	14°09'
	Right		13°53'	----	----	14°11'
Toe Out On Turns	Left		----	----	----	----
	Right		----	----	----	----
Max Turn Inside	Left		----	----	----	----
	Right		----	----	----	----
Toe Curve Change	Left		----	----	----	----
	Right		----	----	----	----
Setback	Front		9mm	----	----	9mm
	Rear		-2mm	----	----	-2mm
Track Width Diff.			-6mm			-6mm
Wheel Base Diff.			11mm			11mm
Front Ride Height	Left		----	----	----	----
	Right		----	----	----	----
Rear Ride Height	Left		----	----	----	----
	Right		----	----	----	----
Frame Angle						----