

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
 78 Shenton Way #07-16
 Singapore 079120
 Tel : 6419 - 3000
 Fax : 6835 - 7416

Cecilia

Quotation

DATE : 25.01.2021
 VEH NO : SKA5864E
 MODEL : BMW 523i
 D O A : 15.01.2021
 YR REF : SDE8380B

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SKA5864E (BMW 523i)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Bumper <i>Debond</i>	1	1,592.00 ✓
2	Rear Bumper Side Holder - LH & RH <i>new</i>	2	206.40 ✓
3	Rear Bumper Reflector - LH & RH <i>new</i>	2	106.00 <i>1947.80</i> x.
4	Rear Bumper Undercover <i>new</i>	1	158.40 <i>1753.02</i> +
5	Rear Bumper Reinforcement <i>new</i>	1	685.00 +
6	Rear Bumper Centre Guide <i>Debond</i>	1	149.40 ✓
			2,897.20
			(289.72)
Less 10%			\$ 2,607.48
<u>S/NETT ITEMS</u>			
1	Rear Bumper Clips <i>new</i>	1 set	\$ 50.00 <i>30</i>
2	Rear Bumper Under Clips <i>new</i>	1 set	\$ 30.00 x.
3	Reverse Sensor <i>Damaged</i>	2	\$ 530.00 <i>400</i>
			\$ 610.00
Total Parts			\$ 3,217.48

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$ 500.00 <i>250</i>
2	To putty & spray up paint works	\$ 500.00 <i>250</i>
3	To check wiring	\$ 50.00 x.

RE : ESTIMATE FOR ACCIDENT REPAIR SKA5864E (BMW 523i)

4 To remove reverse sensor

	\$	100.00
Total Labour	\$	1,150.00
Grand Total	\$	4,367.48

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN
THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY
WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE
FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

Total: 2733.02

L/S: 2.2K.

02 Days.