# Lonpac Insurance Bhd

300 Beach Road ,#17-04/07 The Concourse Singapore 199555

Attention: Motor Vehicle Claim Department

Dear Sir / Mdm,

### Third Party Claim

We are currently assisting SMW5632T to make accident claims

Against vehicle number GBA9238T which eventuated on 15/01/2021 This vehicle is insured by Lonpac Insurance

We seek your co-operation to get the vehicle surveyed by your Accredited surveyors.

Once arrangement is being made, please do notify us to let us have the Ample time to get things arranged for the surveyor.

Your Faithfully,

Wega Engineering Pte Ltd

Leong Chee Kwong Claims Advisor

Mobile No: 84917768

## WEGA ENGINEERING PTE LTD

Blk 176 Sin Ming Drive #04-16 Sin Ming Autocare Singapore 575721

Tel: 6452 1493

Fax: 6452 9153

GST Reg: 19-9900741 / Z

Date

: 18.01.2021

Claim Ref:

### Lonpac Insurance Bhd

300 Beach Road ,#17-04/07 The Concourse Singapore 199555

Vehicle No

SMW5632T

Chassis No

WBAKB22020CN7490

Make/Model :

BMW 730LI AT

Year

Qty	Description	U	Unit Price		Amount		
Estimate Cost Of Repair							
1pc	REAR BUMPER	\$	2,376.00	\$	2,376.00		
1pc	REAR BUMPER ABSORBER GARNISH NO:13	\$	786.84	\$	786.84		
1pc	REAR BUMPER LOWER LIP NO:3	\$	638.00	\$	638.00		
1pc	REAR BUMPER RENTANNAL LH NO:11	\$	52.80	\$	52.80		
1pc	REAR BUMPER REFECTOR LH	\$	93.50	\$	93.50		
1pc	REAR BUMPER REVERSE SENSOR	\$	424.60	\$	424.6		
1pc	REAR FENDER LAMP LH	\$	825.00	\$	825.00		
2pc	REAR END PANAL	\$	1,358.50	\$	1,358.50		
5pc	REAR EXHAUST PIPE OULER	\$	198.00	\$	198.0		
1pc	REAR EXHAUST PIPE MOUNTING BRACKET	\$	27.50	\$	27.5		
1pc	EXHAUST PIPE MOUNTING	s	71.50	\$	71.5		
	1pc 1pc 1pc 1pc 1pc 1pc 1pc 1pc 1pc 2pc 5pc 1pc	1pc REAR BUMPER 1pc REAR BUMPER ABSORBER GARNISH NO:13 1pc REAR BUMPER LOWER LIP NO:3 1pc REAR BUMPER RENTANNAL LH NO:11 1pc REAR BUMPER REFECTOR LH 1pc REAR BUMPER REVERSE SENSOR 1pc REAR FENDER LAMP LH 2pc REAR END PANAL 5pc REAR EXHAUST PIPE OULER 1pc REAR EXHAUST PIPE MOUNTING BRACKET	te Cost Of Repair  1pc REAR BUMPER \$ 1pc REAR BUMPER ABSORBER GARNISH NO:13 \$ 1pc REAR BUMPER LOWER LIP NO:3 \$ 1pc REAR BUMPER RENTANNAL LH NO:11 \$ 1pc REAR BUMPER REFECTOR LH \$ 1pc REAR BUMPER REVERSE SENSOR \$ 1pc REAR BUMPER REVERSE SENSOR \$ 1pc REAR FENDER LAMP LH \$ 2pc REAR END PANAL \$ 5pc REAR EXHAUST PIPE OULER \$ 1pc REAR EXHAUST PIPE MOUNTING BRACKET \$	1pc       REAR BUMPER       \$ 2,376.00         1pc       REAR BUMPER ABSORBER GARNISH NO:13       \$ 786.84         1pc       REAR BUMPER LOWER LIP NO:3       \$ 638.00         1pc       REAR BUMPER RENTANNAL LH NO:11       \$ 52.80         1pc       REAR BUMPER REFECTOR LH       \$ 93.50         1pc       REAR BUMPER REVERSE SENSOR       \$ 424.60         1pc       REAR FENDER LAMP LH       \$ 825.00         2pc       REAR END PANAL       \$ 1,358.50         5pc       REAR EXHAUST PIPE OULER       \$ 198.00         1pc       REAR EXHAUST PIPE MOUNTING BRACKET       \$ 27.50	1pc       REAR BUMPER       \$ 2,376.00       \$         1pc       REAR BUMPER ABSORBER GARNISH NO:13       \$ 786.84       \$         1pc       REAR BUMPER LOWER LIP NO:3       \$ 638.00       \$         1pc       REAR BUMPER RENTANNAL LH NO:11       \$ 52.80       \$         1pc       REAR BUMPER REFECTOR LH       \$ 93.50       \$         1pc       REAR BUMPER REVERSE SENSOR       \$ 424.60       \$         1pc       REAR FENDER LAMP LH       \$ 825.00       \$         2pc       REAR END PANAL       \$ 1,358.50       \$         5pc       REAR EXHAUST PIPE OULER       \$ 198.00       \$         1pc       REAR EXHAUST PIPE MOUNTING BRACKET       \$ 27.50       \$		

#### **Labour Charges**

To check wiring & system function	\$	100.00
	\$	120.00
	\$	80.00
이번 그들은 이번 전에 되었습니다. 이렇게 나는 하는 아니라는 아이들에 되었다면 하게 되었다면 하는데 되었습니다	\$	180.00
	\$	1,000.00
	\$	1,000.00
	To check wiring & system function  To remove & refix rear reverse sensor  To check & reset reverse sensor system function  To conduct re-programme and setting of ecu systemto fault code  To replace, repair & knocking accident rear portion rear bumper, chassis Ih  rear tailgate, rear tyre panal and rear end panal  To respray rear bumper, rear tail gate, rear end panal, tyre panal n chassis Ih	To remove & refix rear reverse sensor \$  To check & reset reverse sensor system function \$  To conduct re-programme and setting of ecu system to fault code \$  To replace , repair & knocking accident rear portion rear bumper , chassis Ih \$  rear tailgate , rear tyre panal and rear end panal

**Grand Total** 

9332.24

Wega Engineering Pte Ltd

Authorised Signature Leong Chee Kwong Mobile No: 84917768