

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

1/5

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Mr
Sim
Chong Yee
Blk 615A Edgefield Plains
#13-331
SINGAPORE 821615

Document no.
Document date 15-01-2021
Customer no. 5211043795
Customer GST-ID 201009404M
Dealer 30001
Job order number 2021002168/ 1
Job order date 15-01-2021
Service Advisor YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SMU9119T	5T13NZ	15-09-2017	WVGZZZ1TZW056773	TOURAN 1.4 CLBMT 110TSI D7F	53,282

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
	Leaked Check, Vacuum & Regas	1	pcs.	420.00	#1	420.00	449.40
	A/C GAS	1	pcs.	60.00	#1	60.00	64.20
	To Align LED Headlight	1	pcs.	100.00	#1	100.00	107.00
5TA823031E	Hood	1	pcs.	2,081.57	1977.49	2,081.57	2,227.28
	FRT BONNET						
5TA823301D	Flap Hinge	1	pcs.	228.71	217.27	228.71	244.72
	LH						
5TA823315A	Hinge Cover	1	pcs.	8.67	8.24	8.67	9.28
	LH						
5TA823302D	Flap Hinge	1	pcs.	228.71	217.27	228.71	244.72
	RH						
5TA823316A	Hinge Cover	1	pcs.	8.67	8.24	8.67	9.28
	RH						
5TA823823E	Activator For Pedestrian	2	pcs.	171.98	326.76	343.96	368.04
8V0823397	Clip	4	pcs.	1.59	6.04	6.36	6.81
8V0823739	Gasket	4	pcs.	1.34	5.09	5.36	5.74
5TA823186A	Locking Catch	1	pcs.	83.39		83.39	89.23
	LATCH						
5G1823509D	Hood Latch	1	pcs.	265.73		265.73	284.33
	LOCK						
WHT000425	Hexagon Socket Oval Head	2	pcs.	2.50	4.75	5.00	5.35
5TA807217 GRU	Cover For Bumper Primed	1	pcs.	1,369.89	1301.40	1,369.89	1,465.78
	FRT BUMPER						
5TA807723	Support Part	1	pcs.	47.18	44.82	47.18	50.48
	BUMPER INNER BRACKET LH						
5TA807724	Support Part	1	pcs.	47.18		47.18	50.48
	BUMPER INNER BRACKET RH						
5TA807049	Guide Piece	1	pcs.	42.77		42.77	45.76
	BUMPER SIDE BRACKET LH						
5TA807050	Guide Piece	1	pcs.	42.77		42.77	45.76
	BUMPER SIDE BRACKET RH						
5TA807109K	Impact Beam	1	pcs.	676.88	643.04	676.88	724.26
	FRT REINFORCEMENT						
N 91234201	Riveted Cap Nut	4	pcs.	3.02	11.48	12.08	12.93
5TA807248	Foam Insert	1	pcs.	58.48	55.56	58.48	62.57
5TA959109A	Pressure Sensor (foam)	1	pcs.	183.97		183.97	196.85
5Q0959651B	Crash Sensor For Airbag	2	pcs.	255.92		511.84	547.67
	CRASH SENSOR (BUMPER)						
5K0973323	Flat Contact Housing		pcs.	10.56		21.12	22.60
	CRASH SENSOR WIRE HOUSING						
5TA853651L LDB	Radiator Grille With Sati	1	pcs.	427.48	406.11	427.48	457.40
3G0853601A JZA	Vw Sign Black/Bright Chro	1	pcs.	190.85	181.31	190.85	204.21

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

2/5

Company

AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:

Mr
Sim
Chong Yee
Blk 615A Edgefield Plains
#13-331
SINGAPORE 821615

Document no.

Document date 15-01-2021
Customer no. 5211043795
Customer GST-ID 201009404M
Dealer 30001
Job order number 2021002168/ 1
Job order date 15-01-2021
Service Advisor YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SMU9119T	5T13NZ	15-09-2017	WVGZZZ1TZW056773	TOURAN 1.4 CLBMT 110TSI D7F	53,282

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
5TA853677K 9B9	Cooling Air Grill Satin B BUMPER CTR LOWER GRILLE } <i>3 sin</i>	1	pcs.	190.53	181.00 #1	190.53	203.87
5TA853666C 9B9	Cover Part For Bumper Sat } <i>3? cm</i>	1	pcs.	77.59	73.71 #1	77.59	83.02
5TC941113A	FOG LAMP GRILLE RH Led Headlight } <i>3? xsu</i>	1	pcs.	1,953.18	#1	1,953.18	2,089.90
5TC941114A	H/LAMP LH Led Headlight } <i>3? xsu</i>	1	pcs.	1,953.18	#1	1,953.18	2,089.90
3C0973737	H/LAMP RH Flat Contact Housing With } <i>3? cm</i>	2	pcs.	19.35	36.77 #1	38.70	41.41
5TA805588C	H/LAMP WIRE HOUSING Lock Carrier With Mountin } <i>3? cm</i>	1	pcs.	1,201.04	1140.99 #1	1,201.04	1,285.11
5TA805705A	Guide BUMPER CTR BRACKET } <i>3? cm</i>	1	pcs.	62.56	59.43 #1	62.56	66.94
5TA805567	Support For Lock Carrier } <i>3? cm</i>	1	pcs.	61.50	58.43 #1	61.50	65.81
5TA806929	Cross Support H/LAMP TOP PANEL LH } <i>3? bt</i>	1	pcs.	33.22	31.56 #1	33.22	35.55
5TA806930	Cross Support RHS H/LAMP TOP PANEL } <i>3? xsu</i>	1	pcs.	33.22	#1	33.22	35.55
5WA816411A	Klimakondensator Mit Flüß } <i>3? xsu</i>	1	pcs.	700.74	#1	700.74	749.79
G 052300A2	A/C CONDENSER Oil For Refrigerant Compr } <i>3? Rec</i>	0.2	pcs.	183.51	34.87 #1	36.70	39.27
5Q0121251HQ	A/C OIL Additional Radiator } <i>3? bt</i>	1	pcs.	642.21	610.10 #1	642.21	687.16
5Q0121251GL	RADIATOR OUTER Radiador } <i>3? xsu</i>	1	pcs.	722.13	#1	722.13	772.68
G 12E050A2	RADIATOR INNER COOLANT } <i>3? Rec</i>	2	pcs.	20.88	39.67 #1	41.76	44.68
5TA121283E	Air Duct AIR GUIDE LH } <i>3? xsu</i>	1	pcs.	26.46	#1	26.46	28.31
5TA121284E	Air Duct AIR GUIDE RH } <i>3? xsu</i>	1	pcs.	26.46	#1	26.46	28.31
5Q0129954	Cover AIR INTAKE TOP COVER } <i>3? xsu</i>	1	pcs.	29.08	#1	29.08	31.12
5Q0010008D	Sticker 'Ac' *Refrigeran } <i>3? xsu</i>	1	pcs.	16.84	#1	16.84	18.02
701010002AA	Kennschild *Bei Ölüberfü } <i>3? xsu</i>	1	pcs.	14.54	#1	14.54	15.56
5Q0129254B	Air Duct AIR INTAKE CTR HOUSING } <i>3? ca</i>	1	pcs.	56.95	54.10 #1	56.95	60.94
5TA827025P	Rear Trunk Lid } <i>3? xsu</i>	1	pcs.	2,207.90	2097.51 #1	2,207.90	2,362.45
D 169300M2	1k Window Adhesive } <i>3? xsu</i>	2	pcs.	51.11	97.11 #1	102.22	109.38
D 00940104	All Purpose Cleaner } <i>3? xsu</i>	1	pcs.	94.03	89.33 #1	94.03	100.61
D 00920002	Primer } <i>3? xsu</i>	1	pcs.	27.39	26.02 #1	27.39	29.31
D 181802M1	Activator For Precoated W } <i>3? xsu</i>	1	pcs.	25.14	23.88 #1	25.14	26.90
D 00950025	Applicator } <i>3? xsu</i>	2	pcs.	10.12	14.23 #1	20.24	21.66
5TA827939 041	Spoiler Satin Black RR W/SCREEN SIDE TRIM LH } <i>3? xsu</i>	1	pcs.	260.54	247.51 #1	260.54	278.78
5TA827940 041	Spoiler Satin Black RR W/SCREEN SIDE TRIM RH } <i>3? xsu</i>	1	pcs.	272.52	258.89 #1	272.52	291.60

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

3/5

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Mr
Sim
Chong Yee
Blk 615A Edgefield Plains
#13-331
SINGAPORE 821615

Document no.
Document date 15-01-2021
Customer no. 5211043795
Customer GST-ID 201009404M
Dealer 30001
Job order number 2021002168/ 1
Job order date 15-01-2021
Service Advisor YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SMU9119T	5T13NZ	15-09-2017	WVGZZZ1TZW056773	TOURAN 1.4 CLBMT 110TSI D7F	53,282

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
8D0853419D	Packing Adhesive	1	pcs.	29.20	#1	29.20	31.24
	REAR NUMBER PLATE PACKING	1	pcs.	29.20	#1	29.20	31.24
WHT007341	Rivetted Cap Nut	4	pcs.	2.28	#1	9.12	9.76
5TA827566B	Pushbutton For Electric L	1	pcs.	1,470.77	#1	1,470.77	1,573.72
5TA827505D	Hood Latch	1	pcs.	158.42	#1	158.42	169.51
	LID LOCK	1	pcs.	158.42	#1	158.42	169.51
5TA827520 9B9	Cover Lock Satin Black	1	pcs.	19.79	#1	19.79	21.18
5TA827705A	Gasket	1	pcs.	317.42	#1	317.42	339.64
	BOOT WETHERSTRIP	1	pcs.	317.42	#1	317.42	339.64
3CN945087	Additional Brake Light Wi	1	pcs.	221.63	#1	221.63	237.14
	3RD BRAKELIGHT	1	pcs.	221.63	#1	221.63	237.14
5NA943021	Led Licence Place Light	1	pcs.	100.67	#1	201.34	215.43
5TA945093E	Taillight With Back-Up Li	1	pcs.	260.12	#1	260.12	278.33
	TAILLIGHT INNER LH	1	pcs.	260.12	#1	260.12	278.33
5TA945094E	Taillight With Back-Up Li	1	pcs.	260.12	#1	260.12	278.33
	TAILLIGHT INNER RH	1	pcs.	260.12	#1	260.12	278.33
5TA945095D	Schlussleuchte	1	pcs.	310.35	#1	310.35	332.07
	TAILLIGHT OUTER LH	1	pcs.	310.35	#1	310.35	332.07
5TA945096D	Tail Light	1	pcs.	310.35	#1	310.35	332.07
	TAILLIGHT OUTER RH	1	pcs.	310.35	#1	310.35	332.07
5TA945229	Mounting	2	pcs.	0.41	#1	0.82	0.88
5TA867601C 82V	Trim Panel For Hatch Gate	1	pcs.	291.69	#1	291.69	312.11
	BOOT LID TRIM COVER	1	pcs.	291.69	#1	291.69	312.11
5TA807417 GRU	Cover For Bumper Primed	1	pcs.	1,321.12	#1	1,321.12	1,413.60
	REAR BUMPER	1	pcs.	1,321.12	#1	1,321.12	1,413.60
5TA807568A 9B9	Spoiler Satin Black	1	pcs.	323.75	#1	323.75	346.41
WHT005263	Rivet	4	pcs.	1.14	#1	4.56	4.88
5TA807305	Bumper	1	pcs.	544.33	#1	544.33	582.43
	REAR REINFORCEMENT	1	pcs.	544.33	#1	544.33	582.43
5TA807863	Attachment Strip	1	pcs.	63.48	#1	63.48	67.92
	BUMPER CTR BRACKET	1	pcs.	63.48	#1	63.48	67.92
5TA807453	Guide Piece	1	pcs.	41.17	#1	41.17	44.05
	LHR BUMPER BRACKET (UPPER)	1	pcs.	41.17	#1	41.17	44.05
5TA807454	Guide Piece	1	pcs.	41.17	#1	41.17	44.05
	RHR BUMPER BRACKET (UPPER)	1	pcs.	41.17	#1	41.17	44.05
5TA807393	Guide Piece	1	pcs.	33.60	#1	33.60	35.95
	LHR BUMPER BRACKET (SIDE)	1	pcs.	33.60	#1	33.60	35.95
5TA807394	Guide Piece	1	pcs.	33.60	#1	33.60	35.95
	RHR BUMPER BRACKET (SIDE)	1	pcs.	33.60	#1	33.60	35.95
5TA945105	Reflector	1	pcs.	68.61	#1	68.61	73.41
	LHS REFLECTOR (INNER)	1	pcs.	68.61	#1	68.61	73.41
5TA945103	Reflector	1	pcs.	68.61	#1	68.61	73.41
	LHS REFLECTOR (OUTER)	1	pcs.	68.61	#1	68.61	73.41
5TA813309A	End Plate	1	pcs.	400.18	#1	400.18	428.19
	END PANEL OUTER	1	pcs.	400.18	#1	400.18	428.19
N 91017602	Weld Stud	4	pcs.	0.96	#1	3.84	4.11
D 007500A2	Zinc Spray	1	pcs.	62.88	#1	62.88	67.28

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 4/5

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Mr
Sim
Chong Yee
Blk 615A Edgefield Plains
#13-331
SINGAPORE 821615

Document no.
Document date 15-01-2021
Customer no. 5211043795
Customer GST-ID 201009404M
Dealer 30001
Job order number 2021002168/ 1
Job order date 15-01-2021
Service Advisor YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SMU9119T	5T13NZ	15-09-2017	WVGZZZ1TZW056773	TOURAN 1.4 CLBMT 110TSI D7F	53,282

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
D 180003M2	2k-Body Adhesive <i>? Xan</i>	1	pcs.	428.72	#1	428.72	458.73
D 476KD1M2	Sealant Can Be Sprayed <i>? Xan</i>	1	pcs.	64.15	#1	64.15	68.64
5TA863459E 82V	Cover For Lock Carrier Ti <i>? Xsu</i>	1	pcs.	171.94	#1	171.94	183.98
	END PANEL TRIM COVER						
5TA867705D 07N	Storage Unit Black <i>? Xsu</i>	1	pcs.	512.97	#1	512.97	548.88
5TA867508B 82V	Bracket Titanium Black <i>? Xsu</i>	1	pcs.	383.57	#1	383.57	410.42
5TA883608 82V	Trim For Seat Release Tit <i>? Xsu</i>	1	pcs.	48.60	#1	48.60	52.00
5TA810972	Wheelhouse Protector <i>? TORN</i>	1	pcs.	234.95	#1	234.95	251.40
	RHS FENDER LINER						
5TA253609B	Exhaust Silencer Rear <i>? Xsu</i>	1	pcs.	2,743.04	#1	2,743.04	2,935.05
5QA253409	Middle Exhaust Muffler <i>? Xsu</i>	1	pcs.	952.92	#1	952.92	1,019.62
	CTR SILENCER <i>? Xsu</i>						
1K0253141S	Dual Clamp <i>? Xan</i>	1	pcs.	60.12	#1	60.12	64.33
000071913A CH9	Exhaust Pipe Tips <i>? Xsu</i>	1	pcs.	183.87	#1	183.87	196.74
	LABOUR FRT	6	pcs.	840.00	#1	5,040.00	5,392.80
	SPRAY PAINT	6	pcs.	800.00	#1	4,800.00	5,136.00
	LABOUR REAR	8	pcs.	840.00	#1	6,720.00	7,190.40
	SPRAY PAINT REAR	6	pcs.	800.00	#1	4,800.00	5,136.00
	R&R REAR W/SCREEN	1	pcs.	840.00	#1	840.00	898.80
	TRANSFER BOOT LID MECHANISM	1	pcs.	840.00	#1	840.00	898.80
	R&R REAR LUGGAGE TRIM	1	pcs.	840.00	#1	840.00	898.80
	R&R REAR EXHAUST	1	pcs.	840.00	#1	840.00	898.80
	REAR WATER LEAK TEST	1	pcs.	150.00	#1	150.00	160.50
	REVERSE SENSOR <i>Shorted</i>	1	pcs.	400.00	#1	400.00	428.00
	FRT NUMBER PLATE <i>can</i>	1	pcs.	80.00	#1	80.00	85.60
	REAR NUMBER PLATE <i>can</i>	1	pcs.	80.00	#1	80.00	85.60

Quotation valid till 22-01-2021

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	1,340.00	55,914.08	7%	4,007.79	57,254.08	61,261.87
Total	1,340.00	55,914.08		4,007.79	57,254.08	61,261.87

Customer

Service Advisor

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

5/5

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Mr
Sim
Chong Yee
Blk 615A Edgefield Plains
#13-331
SINGAPORE 821615

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor

15-01-2021
5211043795
201009404M
30001
2021002168/ 1
15-01-2021
YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SMU9119T	5T13NZ	15-09-2017	WVGZZZ1TZW056773	TOURAN 1.4 CLBMT 110TSI D7F	53,282

-----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Ram

Hp 90010068

15 days

18/01/2021 @ 1645

Resurvey before paint

(A)

Supplementary or Omitted List

VEHICLE NUMBER: **SMU9119T**
MODEL **TOURAN**



CLAIMS DETAILS

	LABOUR DESCRIPTION	AMOUNT		
		Qty	Unit	Amount
Total				\$0.00

No.	Item No.	Description	Qty	Unit Price	Discount	Amount
1	5TA853630A DPJ	Vw Sign Black/Bright Chro	1	\$ 105.72		\$ 105.72 ✓ 100.43
2	5TA853687 2ZZ	REAR EMBLEM - TOURAN	1	\$ 72.44		\$ 72.44 ✓ 68.82
3	7N0853675J 2ZZ	REAR EMBLEM - 280 TSI	1	\$ 78.05		\$ 78.05 ✓ 74.15
	WHT005263	Rivet Repeated.	4	\$ 1.14		\$ 4.56 X
	5TA823359C	BONNET ABSORBER	1	\$ 128.12		\$ 128.12 ✓ 121.71
	5TA853665C 9B9	Cover PCH For Bumper Soft LHS Fog lamp grille	1	\$ 73.71		\$ 73.71 ✓
TOTAL:						\$388.89

Total Labour & Parts

\$388.89