

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21000858/T1PA3Q2
Date: 19/11/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800037039	
Claimant Vehicle No :	SHC2945A	Insured Vehicle No :	SLZ2646U	
Date of Loss:	17/01/2021	Nature of Claim:	TP	Claim No: 9153045551SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC2945A		
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Engine No:	G4LEKU299945
Reg. Date:	06/08/2019 (Man. Year: 2019)	Chassis No:	KMHC851CVKU164475
Colour:	Blue	Odometer:	185830 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,145.44	1,286.80	858.64	40.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,120.00	880.00	240.00	21.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,265.44	2,166.80	1,098.64	33.64
+ GST 7.00/7.00% (S\$)	228.58	151.68	76.90	33.64

Nett Amount (S\$)	3,494.02	2,318.48	1,175.54	33.64
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$125.19/day) (S\$)		375.57		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,846.05		
Global Sum Settlement (S\$)		2,760.00		

INSPECTION

Date of Assignment: 18/01/2021

Date Inspected: 18/01/2021

Estimated Period of Repair: 2.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	459.40 FL	*459.40 FL
2	1		*REAR BUMPER CTR MOULDING	Cracked	451.25 FL	*451.25 FL
3	1		*REAR BUMPER LWR MOULDING	Repair	155.00 FL	*- FL
4	1		*REAR BUMPER FOGLAMP	Cracked	201.50 FL	*201.50 FL
5	1		*REAR BUMPER BEAM	Not Necessary	394.80 FL	*- FL
6	1		*REAR BUMPER STAY LH	Not Necessary	138.10 FL	*- FL
7	1		*REAR BUMPER STAY RH	Not Necessary	138.10 FL	*- FL
8	1		*REAR FLOOR UNDER COVER	Not Necessary	108.00 FL	*- FL
9	1		*REAR BUMPER TOW COVER	Not Necessary	98.80 FL	*- FL
10	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
11	1		*REAR ANTENNA -SNARTKEY	Not Necessary	40.50 FL	*- FL
12	1		*REVERSE SENSOR	Not Working	180.00 FS	*180.00 FS
13	1		*BOOTLID EMBLEM -HYBRID	Necessary	24.30 FL	*24.30 FL
14	1		*BOOTLID EMBLEM -IONIQ	Necessary	31.30 FL	*31.30 FL
15	1		*BOOTLID COMFORTDELGRO	Necessary	30.00 FS	*30.00 FS
16	1		*BOOTLID 65521111	Necessary	30.00 FS	*30.00 FS
17	1		*BOOTLID APPS	Necessary	40.00 FS	*40.00 FS
18	1		*NO PLATE (S) W/TRIM COVER	Cracked	55.00 FS	*55.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,598.05	1,524.75
- List Item Discount on L Items 20.00/20.00% (\$\$)	452.61	237.95
Total Parts (\$\$)	2,145.44	1,286.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	350.00
2	SPRAYPAINT -BOOTLID ETC	New	600.00	500.00
3	R/I REVERSE SENSOR	New	120.00	30.00
Gross Labour Cost (\$\$)			1,120.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >