

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

ALG CPIP) JH
Date: 18.01.2021
Time: 11:53:03
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305448639
REGN NO : SHB6655R
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 18.04.2019
DATE/TIME IN : 18.01.2021 09:50
ACCIDENT DATE : 16.01.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1	459.40	20.00	367.52	Rp	
0002 04-01-0104-2533-G	IONIQV2-4 MOULDING ASSY-R	1	451.25	20.00	361.00	mb	
0003 04-01-0101-0111-G	I40VC BUMPER COVER CLIP R	10 L	22.00	20.00	17.60	nu	473.25
0004 04-01-0103-1150-A	I40VC PROTECTOR MAT	1 N	50.00	2.00-	50.00	* nu.	20% 378.60

SUB-TOTAL : 796.12

JOB NATURE

0000 PB	PANEL BEATING	400.00	350.
0001 SP	SPRAYPAINT CHARGE	300.00	250
0002 L	REMOVE/REFIX REVERSE SENSOR	80.00	30. 830
0003 20-05	RENEW ADVERTISEMENT STICKER-Fender	200.00	✓

SUB-TOTAL : 980.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Receipt
Tampin 97495749
WP 18/1/21 @ 5pm
P/P Resurvey after repair
2 days
Fajmie Khan
\$1208.60
2 days.