

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 21 January 2021 12:27 PM
To: jeremiah@falconair.com.sg
Cc: SUR
Subject: LPC-OD SKN 3207Y DOA: 17/01/2021

Dear Jeremiah,

As spoken with Jenet.

As instructed by our client, please proceed to repair the insured vehicle **SKN 3207Y at repair cost not more than \$9,000.00 on Lump Sum basis (Excess \$0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)