

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS / LPE 2100 of 70 / Uq43

ASSIGNMENT

From:

Date:

Estimated Cost:

(OD / TP / WS / TP RES / OD RES / EVA / INV / MV)

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

Veh No:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1) 24/02 TYPIST

Date/Time, File Return to?

2)

Report Format:

☐ : Preli. Report☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$

we until 29-5-2024 LTA 827730

20/1/21 @ 4.28am visit to Gerald ph by email.

19/1/21 confirmed L/S \$9000 with Jeremiah

21/01/21 @ 12.21pm Gerald informed C/A & Ex of by email.

21/01/21 @ 12.21pm informed Jeremiah C/A not more than 12.21pm Ex of by email

(Red \$12,105.20, 57%)



FALCON-AIR

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04 THE CONCOURSE SINGAPORE 199555

Attention : Motor Claim Department
Contact : (02) 6250 7388 Fax No. : 62963767

Page 1 / 3
FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

Estimate : ES707847

Date : 18/01/2021
Vehicle Num. : SKN 3207Y
Make/Model : VOLKSWAGEN JETTA
Chassis/Eng# : WWWZZZ16ZEM031410
Accident Date : 17/01/2021
Claim No. :
Reference : OD 1/2
Policy No. :

Not Authorized
2/5 9000
Express?
19/1/21
Whelpie Affinity
6 days

S/N	Quantity	Particular	Unit Price	Amount S\$
PARTS PURCHASED :				
1.	1 PC	BONNET <i>DD/BUL</i>		640.00 ✓
2.	1 PC	BONNET LATCH HOOK <i>twi</i>		65.00 ✓
3.	1 PC	BONNET LOWER LOCK <i>twi</i>		140.00 ✓
4.	1 PC	BONNET INSULATOR <i>11</i>		190.00 X
5.	12 PC	BONNET INSULATOR CLIP <i>11</i>	3.00	36.00 X
6.	1 PC	FRONT BUMPER <i>De</i>		640.00 ✓
7.	2 PC	FRONT BUMPER SIDE RETAINER <i>11</i>	35.00	70.00 X
8.	12 PC	FRONT BUMPER CLIP <i>11</i>	3.00	36.00 ✓
9.	1 PC	FRONT NUMBER PLATE GARNISH <i>Dis</i>		105.00 ✓
10.	1 PC	FRONT BUMPER CENTRE GRILLE <i>cut</i>		170.00 ✓
11.	1 PC	FRONT BUMPER LOWER SPOILER <i>cut</i>		390.00 ✓
12.	2 PC	FOG LAMP GARNISH <i>3 and</i>	80.00	160.00 ✓
13.	1 PC	FRONT BUMPER UNDERCOVER <i>11</i>		145.00 X
14.	12 PC	FRONT BUMPER UNDERCOVER CLIP <i>11</i>	3.00	36.00 X
15.	1 PC	RADIATOR GRILLE <i>CM</i>		295.00 ✓
16.	2 PC	HEADLAMP <i>n/s one old</i>	400.00	800.00 1pc
17.	2 PC	HEADLAMP PANEL <i>2</i>	45.00	90.00 X
18.	3 PC	FRONT BUMPER SPONGE <i>11</i>	80.00	240.00 X
19.	1 PC	FRONT BUMPER REINFORCEMENT <i>11</i>		325.00 ✓
20.	1 PC	FRONT BUMPER CENTRE BRACKET <i>CM</i>		115.00 ✓
21.	1 PC	FRONT BUMPER TOW HOOK COVER <i>twi</i>		45.00 ✓
22.	1 PC	BRACE PANEL <i>twi</i>		65.00 ✓

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04 THE CONCOURSE SINGAPORE 199555

Attention : Motor Claim Department

Contact : (02) 6250 7388 Fax No. : 62963767

Estimate : ES707847

Date : 18/01/2021

Vehicle Num. : SKN 3207Y

Make/Model : VOLKSWAGEN JETTA

Chassis/Eng# : WWWZZZ16ZEM031410

Accident Date : 17/01/2021

Claim No. :

Reference : OD 1/2

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
23.	1 PC	FRONT SUPPORT PANEL <i>2</i>		600.00 <i>X</i>
24.	1 PC	AIR-CON CONDENSER <i>17</i>		450.00 <i>X</i>
25.	1 PC	FRONT WINDSCREEN GLASS <i>eng</i>		550.00 <i>/</i>
26.	2 PC	SRS IMPACT SENSOR <i>Bound</i>	225.00	450.00 <i>/</i>
27.	1 PC	SRS CONTROL MODULE <i>Actual 1200</i>		1,000.00 <i>/</i>
28.	1 PC	STEERING AIR BAG <i>Actual</i>		1,800.00 <i>/</i>
29.	1 PC	PASSENGER AIRBAG <i>Actual 1600</i>		2,100.00 <i>/</i>
30.	1 PC	DRIVERS SEAT BELT <i>Bound</i>		520.00 <i>/</i>
31.	1 PC	DRIVER'S SEAT BELT BUCKLE <i>17</i>		190.00 <i>X</i>
32.	1 PC	PASSENGER'S SEAT BELT <i>Actual</i>		520.00 <i>/</i>
33.	1 PC	PASSENGER'S SEAT BELT BUCKLE <i>17</i>		190.00 <i>X</i>
34.	1 PC	STEERING SPIRAL WIRE <i>Actual 200</i>		540.00 <i>/</i>
35.	1 PC	DASHBOARD <i>Turn 1100</i>		2,200.00 <i>/</i>
Total Parts Purchased S\$:				15,908.00
15.00% Of The Above Parts S\$:				2,386.20
Based On Cost Plus S\$:				18,294.20
SPECIAL NETT ITEMS :				
1.	1 PC	FRONT NUMBER PLATE <i>But</i>	40	45.00
2.	1 PC	FRONT WINDSCREEN GLASS SEALANT <i>nu</i>	40	40.00
3.	1 PC	ERP IJ BRACKET <i>nel</i>	15	26.00
Special Nett Total S\$:				111.00

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

FALCON-AIR AUTO SERVICES PTE LTDCO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

FALCON-AIR

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04 THE CONCOURSE SINGAPORE 199555

Attention : Motor Claim Department

Contact : (02) 6250 7388 Fax No. : 62963767

Estimate : ES707847

Date : 18/01/2021

Vehicle Num. : SKN 3207Y

Make/Model : VOLKSWAGEN JETTA

Chassis/Eng# : WWWZZZ16ZEM031410

Accident Date : 17/01/2021

Claim No. :

Reference : OD 1/2

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LABOUR :				
		TO REMOVE/REFIT FRONT WINDSCREEN	120	150.00
		TO VACCUM, REOIL AND REGAS AIR CON	100	150.00
		CHECK LIGHT SYSTEM AND WIRING	20	50.00
		TO REMOVE/REPLACE SRS SYSTEM	250	500.00
		TO REMOVE NECESSARY PART TO REPAIR INNER PANEL, REPLACE		
		ACCIDENT DAMAGED PARTS AND ALIGN THE SAME	600	800.00
		TO PUTTY AND RESPRAY ACCIDENT DAMAGED AREAS	700	800.00
		TO USE DIAGNOSTIC SCANNER TO RESET SRS SYSTEM	100	250.00
		Labour Total S\$:		2,700.00

E. & O.E. Total S\$: 21,105.20

for FALCON AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg