



CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /DHANARAJ THOMAS JEYARAJ Reg No/Reg Date SMU9407L / 07/09/202 Date In/Mileage 18/01/2021/ 0 Chassis No KNACB81CVL5371398 Engine No G4LEKS616335 Make/Model KIA/NIRO 1.6 A EX A42 PE Colour/Trim C3U DEEP CERULEAN B/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	18/01/2021/ 16:03	QUK	282 / Kevin Leong	27570			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT BUMPER, SUPPORT PANEL & AFFECTED AREA REPAIR ON FRT LH FENDER					400 X 1			1600.00
E PNT98000 PAINT WORK ON FRT BUMPER, BONNET & FRT LH FENDER					350 X 3			1050.00
E PNT88000 REMOVE & INSTALL RAIDATOR, CONDENSER FOR FACILITATE REPAIR								120.00
M SUNDRY TO TOP UP AIRCON GAS								80.00
M SUNDRY PERFORM RUST PREVENTION								80.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								120.00
M SUNDRY TO SUPPLY FRONT NUMBER PLATE WITH FRAME								50.00
M SUNDRY SUNDRIES								50.00
M LAMP ASSY-HEAD,RH					1.00	904.00	20.00	723.20
M CARRIER ASSY-FRONT END MODULE					1.00	675.00	20.00	540.00
M BEAM COMPLETE-FR BUMPER					1.00	661.00	20.00	528.80
M HINGE ASSY-HOOD,RH					1.00	40.00	20.00	32.00
M HINGE ASSY-HOOD,LH					1.00	40.00	20.00	32.00
M CONDENSER ASSY-COOLER					1.00	639.00	20.00	511.20
M RADIATOR ASSY-INVERTER					1.00	768.00	20.00	614.40
M RADIATOR ASSY					1.00	492.00	20.00	393.60
M GUARD-AIR,LH					1.00	29.00	20.00	23.20
M GUARD-AIR,RH					1.00	29.00	20.00	23.20
M GUARD-AIR RADIATOR,UPR					1.00	15.00	20.00	12.00
M BLOWER ASSY					1.00	546.00	20.00	436.80
P COVER-FR BUMPER UPR					1.00	637.00	20.00	509.60

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /DHANARAJ THOMAS JEYARAJ Reg No/Reg Date SMU9407L / 07/09/202 Date In/Mileage 18/01/2021/ 0 Chassis No KNACB81CVL5371398 Engine No G4LEKS616335 Make/Model KIA/NIRO 1.6 A EX A42 PE Colour/Trim C3U DEEP CERULEAN B/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	18/01/2021/ 16:03	QUK	282 / Kevin Leong	27570			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M COVER-FR BUMPER,LWR	✓	CUT (UPPER)			1.00	373.00	20.00	298.40
M LIP ASSY-FRONT BUMPER	X	NM			1.00	38.00	20.00	30.40
M SKID PLATE-FR BUMPER	X	NM			1.00	60.00	20.00	48.00
M STRIP ASSY-FR BUMPER UPR		X NM			1.00	28.00	20.00	22.40
M GRILLE ASSY-RADIATOR	✓	OR			1.00	441.00	20.00	352.80
M COVER ASSY-RADIATOR GRILLE UPR		X NM			1.00	40.00	20.00	32.00
M ABSORBER-FRONT BUMPER ENERGY		OR			1.00	68.00	20.00	54.40
M COVER-DAYTIME RUNNING LIGHT,RH	✓	OR			1.00	46.00	20.00	36.80
M BRACKET-FR BUMPER SIDE MTG,LH	✓	OR			1.00	3.00	20.00	2.40
M BRACKET-FR BUMPER SIDE MTG,RH	✓	OR			1.00	3.00	20.00	2.40
M LAMP ASSY-DAY RUNNING LIGHT,RH	✓	OR			1.00	619.00	20.00	495.20
M GRILLE-FRONT BUMPER	(Black)	CUT			1.00	131.00	20.00	104.80
M STIFFNER-FR BPR LWR	X	NM			1.00	116.00	20.00	92.80
M DUCT ASSY-ACTIVE AIR		OR			1.00	64.00	20.00	51.20
M FLAP ASSY-ACTIVE AIR,LWR		X NM			1.00	481.00	20.00	384.80
M BRACKET-FR BUMPER SIDE,LH	X	NM			1.00	12.00	20.00	9.60
M BRACKET-FR BUMPER SIDE,RH	X	NM			1.00	12.00	20.00	9.60
M LOGO ASSY-KIA SUB	✓	OR			1.00	51.00	20.00	40.80

Steve (LKK) 19/1/20, 4:30pm

OO-M-AL

Excess - ?

6 #dys

P/P

M BL SKY

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

Parts prices are subject to confirmation

Confirmed & accepted by a "Without Prejudice" basis

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Authorized signatory and company stamp

Nett 9,628.80  
7% GST on 9628.80 674.02  
Total Payable 10,302.82

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.